

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014									
	Total	504	2929	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	2	1	2	1	2			
2	NLG	150	948		6		6		6			
3	MDK	87	828	2		2		2				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	8	3	8	3	8	0	0	
	Grand Total	908	6149	3	13	3	13	3	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.12.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/33KV Singotam	Narsaipally	33KV	Nagarkurnool	14.58	16.12	01.14	O/L	No visible fault	Narsaipally	No
1	MDK	Chegunta	Bonala	33KV	Toopran	16:50	19:40	2:50		BD due to Isolator failed	Bonala	No
2		Habsipur	Dubbak	33KV	Siddipet	07.45	09.35	01.50		BD due to HG fuse failed	Dubbak	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nawabpet	Lokirev	11KV	Jadcherla	12.40	14.15	01.35		Bird fallen on the 11KV line near Lokirev (V)	No
2		Badepally	Burgupally	11KV	Jadcherla	08.15	09.15	01.00		No visible fault	No
1	NLG	Gadipally	Ponugodu	11KV	Huzurnagar	8:50	13:00	4:10	EL	Due to 11KV Line Cut Near Ponugodu Village	No
2		Huzurnagar	Burugadda	11KV	Huzurnagar	7:30	15:30	8:00	EL	Due to 11KV Insuletor Failed Near Burugadda Village	No
3		Raghunadapalem	Raghunadapalem	11KV	Huzurnagar	01.40	09.20	07.40	EL	Due to 11KV Line Cut Near Raghunadapalem Village	No
4		Kethepally	Korlapahad	11KV	Nalgonda	02.00	08.50	06.50	EL	HT/LT line melting at SS-26	No
5		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	11.50	13.10	01.20	EL	11KV Jumper cut at SS-3	No
6		Chedella	Mukundapuram	11KV	Suryapet	8:40	12:00	3:20	EL	Jumper cut	No
1	RR S	CBIT	Gandipet	11KV	IBGH	8:02	9:10	1:08		Bird fallen on 11KV line at Gandipet Katta	No
1	RR N	Kandlakoya	Saigeetha Ashramam	11KV	Medchal	12:30	14:20	1:50		11KV Jumper Cut & Replaced at Shiva Shivani College Backside	No
1	RR E	Peddaamberpet	Kuntloor	11KV	Sarooranagar	14:35	15:55	1:10	EL	No visible fault	No
2		Injapur	CRCF	11KV	Ibrahimpattanam	13.40	17.20	03.40	EL	11KV Pole damaged	No
3		Aushapur	Edulabad	11KV	Keesara	09.20	12.00	02.40	EL	11KV Disc failed near Ace Engg College Backside	No