

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	1	1	1	1	1			
2	NLG	150	948		5		5		5			
3	MDK	87	828		3		3		3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	9	1	9	1	9	0	0	
	Grand Total	908	6149	1	9	1	9	1	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.12.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	11.33	13.40	02.07	E/L	No Visible Fault	Peddakothapally	-

TSSPDCL - LMRC / Corporate office

Date: 18.12.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Annasagar	11KV	Jadcherla	12.50	14.00	01.10		11 kv Wire cut near Gajulapet	-
1	NLG	Keethavarigudem	Rainigudam	11KV	Huzurnagar	11.20	14.55	03.35	O/L	11kv line Snapped near Rainigudam (v)	-
2		Amaravaram	Amaravaram	11KV	Huzurnagar	16.30	17.30	01.00	E/L	11kv line Cut near Amaravaram (v)	-
3		Thatipamula	Thatipamula	11KV	Suryapet	07.00	10.40	03.40	E/L	11Kv Jumper cut	-
4		Chandur	Kasthala	11KV	Nalgonda	08.45	12.45	04.00	E/L	11KV jumper cut	-
5		Eduloor	Naregudem	11KV	Nalgonda	06.00	10.00	04.00	E/L	HT/LT line melting at SS-22	-
1	MDK	Shalipet	Chennaipally	11KV	Medak	06.10	09.10	03.00		B/D due to Tree branches fallen on line	-
2		Sangareddy-I	Tallapally	11KV	Sangareddy	08.45	11.20	02.35		B/D due to 11KV Conductor snapped	-
3		Cheryal	DVR	11KV	Sangareddy	06.15	10.15	04.00		B/D due to 11KV Disc failed	-