

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360									
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948		4		4		4			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	



TSSPDCL - LMRC / Corporate office

Date: 22.12.17

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Konded	Chinnaadiralala	11KV	Jadcherla	10.50	12.25	01.35		11KV Insulator failed near Chinna Adiralala Village	No
1	NLG	Dirsincherla	Somaram	11KV	Huzurnagar	6:40	8:30	1:50	EL/OL	11KV Conductor snapped near Somaram village	No
2		Ponugodu	Velidanda	11KV	Huzurnagar	09.37	15.00	05.23	EL	Due to DTR failed near Velidanda village	No
3		Y.Singaram	Y.Singaram	11KV	Huzurnagar	00.00	06.15	06.15	EL	11KV Jumper cut near Y.Singaram village	No
4		Kethepally	Kasanagode	11KV	Nalgonda	03.00	09.00	06.00	E/L	11KV Jumper cut at SS-5	No
1	RR N	Subash Nagar	Pragatools	11KV	Medchal	15:06	16:01	0:55		11KV Conductor snapped at TS Seeds	No
2		Kandlakoya	Kandlakoya	11KV	Medchal	16.10	17.20	01.10		11KV Pole damaged at Altra Tech company	No