

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		5		5		5			
5	RR(N)	82	407		9		9		9			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		23		23		23			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>39</b>	<b>0</b>	<b>39</b>	<b>0</b>	<b>39</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	1	1	1	1	1			
2	NLG	150	948		10		10		10			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>1</b>	<b>50</b>	<b>1</b>	<b>50</b>	<b>1</b>	<b>50</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 06.07.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Thirumalaipally	Willamkonda	33KV	Wanaparthi	22.26	23.00	00.34		After Patrolling No visible fault	Willamkonda	Alternate supply arranged from 33KV Pebbar

## TSSPDCL - LMRC / Corporate office

Date: 06.07.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mustipur	Nadimalla	11KV	Mahabubnagar	15.00	16.30	01.30		11KV Phase to Phase	-
1	NLG	T.Giri	Thatipamula	11KV	Suryapet	05.30	09.00	03.30	E/L	Line Melt	-
2		Garidepally	Ponugodu	11KV	Huzurnagar	13.00	14.00	01.00	E/L	11 KV Jumper cut at Ponugodu village	-
3		Garidepally	Gaddipally	11KV	Huzurnagar	07.00	09.40	02.40	E/L	11 kv Jumper cut at Gaddipally village	-
4		Bethavolu	Bethavolu	11KV	Huzurnagar	10.30	11.30	01.00	E/L	11 kv line snapped at Bethavolu village	-
5		Chilukur	Kondapuram	11KV	Huzurnagar	13.45	16.10	02.25	E/L	11 kv line snapped at Kondapuram village	-
6		Madgulapally	Dacharam (Chervupally)	11KV	Nalgonda	03.00	05.00	02.00	E/L	11 KV LINE CUTTING	-
7		Mushampally	Muthyalammagudem	11KV	Nalgonda	13.00	15.30	02.30	E/L	11 KV Line Insulator Failed	-
8		NG Bandal	Konapur	11KV	Bhongir	07.00	11.00	04.00	E/L	11KV Line snapped	-
9		Junuthla	Makkapally	11KV	Devarakonda	08.00	11.00	03.00	EL&OL	11Kv Insulator failure	-
10		Mellavai	Revally	11KV	Devarakonda	05.00	07.00	02.00	E/L	11kv jumper cut	-
1	RR S	Manikonda	Panchavathi Colony	11KV	RJNR	18.07	19.38	01.31		11 KV Insulator fail at Panchavathi Colony	-
2		IBGH	Usmansagar	11KV	RJNR	18.10	19.26	01.16		Tree branchaces fallen on 11 KV Line at Narsing	-
3		Vanasthalipuram	NGOs Colony	11KV	CHPT	18.45	20.55	02.10	EL/OL BD	11KV Line cut at NGOS bus stop	-
4		Nandanavanam	Lalitha Nagar	11KV	CHPT	18.14	19.40	01.26	OL/BD	Tree branches fallen on 11KV Line at gayathri nagar	-
5		Leninnagar	Badang pet	11KV	CHPT	00.35	01.21	00.46	EL/OL/ BD	T/F Faid at Leninnagar water tank (load diversion)	-
1	RR N	Gachibowli	SudharshanNagar	11KV	GCB	12.28	14.28	02.00		11KV Pin-insulator failed at Yadav's Colony backside	-
2		Nanakramguda	Manjeera	11KV	GCB	17.39	18.50	01.11		100kva T/F AB-Switch insulator failed near manjeera diamond center	-
3		ChandaNagar	Rail Vihar	11KV	GCB	18.50	22.10	03.20		11kv Line conductor snapped at Sub-Station backside	-
4		Shemshiguda	N T R Nagar	11KV	KKP	18.10	19.20	01.10		11kv Conductor snapped At Dattathraya colony	-
5		J D M Ss-II	N R SA	11KV	KKP	17.48	19.30	01.42		Due To heavy Rain & 11kv AB Cable through Joint failure At phase-IV	-
6		Bahadurapally	Bahadurapally	11KV	KKP	14.30	15.15	00.45		Tree Branches Fallen on the 11kv line at Bhadurapally	-
7		K P H B	BhagyNagar	11KV	KKP	00.20	01.11	00.51		11kv Ab Cable spark at Annupamma tower bhagynagar	-

8		R G K Suraram	Bahadurapally	11KV	KKP	17.30	19.10	01.40		T/F insulator failure at R G K	-
9		UMCC	Mahadevpuram	11KV	MDCL	17.35	18.30	00.55		11KV Pin Insulator failed at Yandamuri Layout	-
1	RR E	Nacharam	Chandamama	11KV	Habsiguda	11.05	12.25	01.20		11KV Line snapped near Seeco Company at IDA Nacharam	-
2		Yapral	Yapral	11KV	Sainikpuri	18.05	18.45	00.40		Tree fallen on 11KV line at Govardhan Puri Garden (L.Insp Narshima)	-
1	HYD N	Lalaguda	Shanthi Nagar	11KV	V	05.25	06.35	01.10	EL,OL-Rph	Cable fault at Jana Priya Apts	-----
2		Kundanbagh	Shanthi Shikara	11KV	IV	18.00	19.19	01.19	EL	Tree branches fallen on lines at Shanthi Shikara Apts	-----
3		Raheja	Gafoor Nagar	11KV	X	18.00	20.20	02.20	EL	Cable fault	Arranged B/F on 11KV Art Gallery fdr
4		Gymkhana	Balamrai	11KV	V	18.15	19.30	01.15	EL	DTR fault at Balamrai	-----
5		K.I.M.S	Nakshatra	11KV	V	18.15	19.55	01.40	EL	Cable fault	Arranged B/F on 11KV Chikoti fdr
6		Chilalguda	Dandu Pentaiah	11KV	V	18.20	21.00	02.40	EL	Tree branches fallen on lines at Ambedkar Statue	-----
7		N.I.M.S.	Tata Rao	11KV	X	19.20	20.45	01.25	EL	Tree branches fallen on lines at Road No.7	-----
8		N.I.M.S.	Nagarjuna Hills	11KV	X	19.35	21.15	01.40	EL	Tree branches fallen on lines at Plot No.18, Nagarjuna Hills	-----
1	HYD S	Salarjung	Purani Haveli	11KV	III	01.43	06.05	04.22	EL	DTR fault at Miralam Mandi	-
2		Attapur	Puranaphool	11KV	III	18.05	20.30	02.25	EL	Disc Insulator flash over at Golden DTR	-
3		Malakpet B-Block	Akber Bagh	11KV	VIII	18.11	21.21	03.10	EL,OL-Bph	Tree branches fallen on Lines at Akber Bagh	-
4		Asmangadh	Saidabad Colony	11KV	VIII	18.12	19.25	01.13	EL,OL	No Visible Fault	-
5		Yakuthpura	Murthuza Nagar	11KV	VIII	18.16	19.30	01.14	EL	No Visible Fault	-
6		Chanchalguda	Arya Samaj	11KV	VIII	18.25	20.10	01.45	EL,OL-Bph	O/G AB Switch Jumper cut SS	-
7		Malakpet	Malakpet	11KV	VIII	19.20	20.25	01.05	EL	Kite stick & tree branches fallen on Lines at Old Malakpet	-
8		Malakpet	Plant Protection	11KV	VIII	19.30	21.30	02.00	EL,OL-Rph	Disc Insulator flash over at City Light Hotel	-
9		Chanchalguda	Anand Nagar	11KV	VIII	20.55	22.25	01.30	OL-Rph	Tree branches fallen on lines at Anand Nagar	-
1	HYD C	Z.P Office	Z.P Office	11KV	I	18.07	19.55	01.48	EL	Flexi fallen on lines & 2No. Pin Insulators flash over at Sridhar Function Hall	-
2		Nampally	Yousufian Darga	11KV	VII	18.09	19.14	01.05	EL,OL-Rph	DTR fault at Biyaban	-
3		Bathkammakunta	Saibaba Temple	11KV	II	18.10	20.50	02.40	EL,OL-Rph	Tree branches fallen on lines at Andhra Bank Line	-
4		Amberpet	Zindalimath	11KV	II	18.10	19.35	01.25	EL	No Visible Fault	-
5		Mothi Mahal	Balansar	11KV	VII	18.12	19.34	01.22	EL	Pin Insulator flash over at backside Govt. Hospital	-
6		Z.P Office	Z.P Office	11KV	I	20.58	22.45	01.47	EL,OL	2Nos Pin Insulators flash over at SBI Bank & Jumper cut at Apex Apts	-