

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201	1	3	1	3	1	3			
5	RR(N)	82	407	1	17	1	17	1	17			
6	RR(E)	38	360		4		4		4			
7	Hyd	186	1014		3		3		3			
	Total	504	2929	2	27	2	27	2	27	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	5		5		5				
2	NLG	150	948	1	8	1	8	1	8			
3	MDK	87	828	1		1		1				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	7	8	7	8	7	8	0	0	
	Grand Total	908	6149	9	35	9	35	9	35	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Koukuntla	33KV	Mahabubnagar	19.10	19.40	00.30	E/L	Koukuntla Feeder Load Daivited to 33KV Devarkadra Feeder Supply Stud Ok	Koukuntla	Koukuntla Feeder Load Daivited to 33KV Devarkadra Feeder at 19:40Hrs Supply Stud Ok at
2		Polepally	Gangapur	33KV	Jadcherla	23.51	08.50	08.59	E/L	2 No's Insulator Damage and replace at Lingampally SS Cut Point Replaced	Gangapur	-
3		Polepally	Gangapur	33KV	Jadcherla	22.54	23.17	00.23	E/L	Break Down and Back Feeding Supply Taken to 33KV Jadcherla Feeder Supply Stud Ok	Gangapur	Back Feeding Supply Taken to 33KV Jadcherla Feeder 23:17Hrs Supply Stud Ok
4		Nagarkurnool	Tadoor	33KV	Nagarkurnool	19.50	21.55	02.05	O/L	No Visable Fault	Tadoor	-
5		Nagarkurnool	lthole	33KV	Nagarkurnool	19.50	22.53	03.03	O/L	33KV Insulator Replasment	lthole	-
1	NLG	Guntipally	Chandampet	33KV	Devarakonda	04.00	07.00	03.00	E/L	insulator failure	Chandampet	-
1	MDK	Zaheerabad	Mannapur	33KV	Zaheerabad	06.05	07.05	01.00		B/D due to after petrolling no fault found & alternate supply arranged by Chota hyderabad feeder	Mannapur	-
1	RR S	132kv RC Puram	33kv Shankar pally	33KV	RJNR	20.40	23.35	02.55	B/D	No fault Due to Heavy rain and Gale		33kv Shankar pally
1	RR N	Shapur Nagar	Agarwal	33KV	Kukatpally	16.53	21.10	04.17	BD	33KV bus-II, Bus isolator R-phase jumper cut in SS	Agarwal	-

TSSPDCL - LMRC / Corporate office

Date: 07.07.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Arlagaddagudem	N.R Gudem	11KV	Suryapet	13.20	15.40	02.20	E/L	Tree branch fallen	-
2		B.Chandupatla	Pachyathanda	11KV	Suryapet	05.45	07.10	01.25	E/L	Jumper cut	-
3		Mushampally	Mushampally AGL	11KV	Nalgonda	08.10	11.30	03.20	E/L	11KV jumper cut at SS-20	-
4		Angadipet	R.R.Gudem	11KV	Devarakonda	05.00	08.00	03.00	E/L	11kv jumper cutt	-
5		Motakondur	Cholleru	11KV	Bhongir	10.10	12.50	02.40	EL	Insulator failed	-
6		Alair	Ikkurthy	11KV	Bhongir	23.00	02.00	03.00	EL	11KV Jumper snapped ss-12 near Ikkurthy	-
7		Mungala	Repala	11KV	Huzurnagar	08.00	10.50	02.50	EL	11 kv line snapped at Repala village	-
8		Timmareddy gudem	Timmareddy gudem	11KV	Huzurnagar	14.05	16.45	02.40	EL	11 KV inslater failed at Timmareddy gudem	-
1	RR S	Champapet	Real Baker	11KV	CPT	15.15	16.20	01.05	EL/OL	Cat fallen on 11KV line at Hanuman Temple	-
2		Manikonda	Panchavathi colony	11KV	RRS	16.45	18.25	01.40	B/D	11KV Disc failed at Road no 6 Panchavathi colony	-
3		Ibrahimbagh	Osmansagar	11KV	RRS	17.15	19.36	02.21	B/D	CTPT failed at Manchirevula venture	-
1	RR N	Papi Reddy Nagar	Market	11KV	Gachibowli	06.20	07.20	01.00	BD	11KV Pin-insulator failed at chandanagar	-
2		Papi Reddy Nagar	Dubey Colony	11KV	Gachibowli	15.45	17.40	01.55	BD	11KV insulator failed at nallagandala X road	-
3		ChandaNagar	Engineers Enclave	11KV	Gachibowli	08.00	09.10	01.10	BD	11KV Jumper snapped at engineers enclave,community hall	-
4		ChandaNagar	Rail Vihar	11KV	Gachibowli	16.10	17.30	01.20	BD	Tree branch fallen on line at Huda trade center	-
5		Gachibowli	Mezquity	11KV	Gachibowli	15.40	17.20	01.40	BD	Due to heavy rain & wind.	-
6		Gachibowli	Kalajyothi	11KV	Gachibowli	16.20	17.40	01.20	BD	Due to heavy rain & wind.	-
7		Ayyappa Society	Ayyappa Society	11KV	Gachibowli	16.40	18.15	01.35	BD	11KV Disc failed at indore hospital	-
8		Huda Truck Park	Raghavendra	11KV	Gachibowli	13.51	14.35	00.44	BD	11KV Pin-insulator failed at raghavendra colony	-
9		Jeedimetla SS III	Ramreddy Nagar	11KV	Kukatpally	12.50	14.20	01.30	BD	11kv line snapped near Nandini Printing at Ramreddy Nagar	-
10		Suraram	IDA Suraram	11KV	Kukatpally	17.35	18.30	00.55	BD	Tree branch fall on the 11kv line near Narayana Hrudalaya Hospital	-
11		Vaddepally	R P Colony	11KV	Kukatpally	19.00	20.20	01.20	BD	11kv HG Fuse Insulator failure near Govt School at Pragathi Nagar	-
12		Kistapur	IDA Hanuman	11KV	Medchal	15.45	16.25	00.40	BD	No Fault	-
13		Medchal	IDA Kandlakoya	11KV	Medchal	15.48	16.56	01.08	BD	11KV Pin Insualator at Forest Area,Ganga Kavari	-
14		Devarayamjal	Kottapet	11KV	Medchal	17.45	19.45	02.00	BD	11KV Line cut & replaced at Jayadharishini Thota	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
15		Kistapur	IDA Hanuman	11KV	Medchal	16.50	17.50	01.00	BD	11KV Pin Insulator failed at Forest area,Ganga Kavari	-
16		Devarayamjal	Kottapet	11KV	Medchal	21.10	22.10	01.00	BD	11KV Disc failed at Devarayamjal Village	-
17		Athiwelly	Athiwelly	11KV	Medchal	20.40	22.00	01.20	BD	11KV Disc failed at Balaji Nagar, Athiwelly	-
1	RR E	MOHAN NAGAR	KOTHAPET	11KV	SAROOR NAGAR	08.08	09.04	00.56	EL	11KV PIN INSULATOR FAIL AT KOTHAPET	-
2		FRUITMARKET	FRUITMARKET	11KV	SAROOR NAGAR	03.59	05.05	01.04	OL/EL	11KV LINE AB SWITCH JUPER CUT AT FRUITMARKET	-
3		AUTO NAGAR	AUTO NAGAR	11KV	SAROOR NAGAR	01.15	03.40	02.25	EL	11KV LINE CUT AT AUTO NAGAR	-
4		Chengicherla	Kamela	11KV	Habsiguda	09.40	10.52	01.12		11KV Line cut at Kamela	-
1	HYD N	Toli Chowki	Hanuman Temple	11KV	X	21.02	22.48	01.46	EL	Tree branches fallen on lines at Bommarillu Guest House	-
1	HYD S	Kandikal Gate	Saibaba Nagar	11KV	III	04.50	07.20	02.30	All Indication	2No. DTR's fault at Saibaba Nagar	-
1	HYD C	Bathkammakunta	Saibaba Temple	11KV	II	07.12	08.35	01.23	EL,OL	Cable fault	Arranged B/F on 11KV Ahobil Mutt feeder