

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	1	3	1	3	1	3			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014		6		6		6			
	Total	504	2929	1	10	1	10	1	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2	1	2	1	2	1			
2	NLG	150	948	1	8	1	8	1	8			
3	MDK	87	828		4		4		4			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	13	3	13	3	13	0	0	
	Grand Total	908	6149	4	23	4	23	4	23	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.07.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Dhanwada	33KV	Mahabubnagar	20.00	22.10	02.10	E/L	for 33KV Line 3No's Pin Insulator Damgaed and Replaced at 33/11KV Appampally SS	Dhanwada	-
2		Ghanapur	Lattupally	33KV	Wanaparthi	19.47	22.23	02.36	E/L	Due to Heavy Gale & Rain & Feeder Tag on to 132KV Nagarkurnool SS	Lattupally	Alternate supply Arranged at 132KV Nagarkurnool SS at 22:23 Hrs
1	NLG	Ramannapeta	Valigonda	33KV	Nalgonda	06.50	12.20	05.30	EL/OL	33KV Line Jumper Cut	Valigonda	-
1	RR N	LGM Pet	LGM Pet	33KV	Medchal	19.02	21.58	02.56	BD	Tree fallen on the 33KV line at Jenetek Com, Thurkaply	LGM Pet	-

TSSPDCL - LMRC / Corporate office

Date: 13.07.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Amarchinta	Jurala	11KV	Mahabubnagar	09.00	13.15	04.15		11KV Phase to Phase at motlampally (Vi)	-
1	NLG	Mushampally	Mushampally	11KV	Nalgonda	04.30	07.45	03.15	E/L	11 KV Line Insulator Failure SS-15	-
2		Gondiryala	Gondiryala 02	11KV	Huzurnagar	04.00	08.00	04.00	E/L	Tree branch fall on 11Kv line near Palakeedu (v)	-
3		Chilukur	Janaki nagar	11KV	Huzurnagar	08.00	12.10	04.10	E/L	Tree branch fall on 11Kv line near Palakeedu (v)	-
4		Keethavarigudem	Rainigudam	11KV	Huzurnagar	02.00	06.00	04.00	E/L	11kv line cutted near Rainigudam village	-
5		Addagudur	Addaguduru	11KV	Bhongir	06.00	09.30	03.30	E/L	11KV Line snapped at SS-10	-
6		Pamukunta	JALA	11KV	Bhongir	02.00	05.00	03.00	E/L	Tree Branches Fallen On Line	-
7		Angadipet	Chilakamarri	11KV	Devarakonda	04.00	07.30	03.30	E/L	11kv Jumper cutting	-
8		Marriguda	Y.G.Pally	11KV	Devarakonda	03.00	07.00	04.00	E/L	11Kv Insulator failure	-
1	MDK	Pillykottal	Pillykottal	11KV	Medak	07.00	10.00	03.00		B/D Due to Insulator fail at Pillikottal	-
2		Rajpally	Balanagar	11KV	Medak	05.00	11.00	06.00		B/D Due to Jumper cut at Thimmakapally village	-
3		Hathnoora	Hathnoora	11KV	Medak	05.00	08.00	03.00		B/D Due to Insulator fail at Hathnoora village	-
4		Yengigandla	Yenigandla	11KV	Medak	10.40	15.30	04.50		B/D Due to Disk fail at Yenigandla village	-
1	RR N	Madinaguda	BK Enclave	11KV	Kukatpally	22.04	23.20	01.16		Shari Fallon the 11kv line & Due to Rain at Subhash chandra Bosh Nagar	-
2		Lanco Hills	Chitrapuri Colony	11KV	Gachibowli	18.11	19.20	01.09	EL & OL	Breaker Problem Inside HIG Apartments at Chitrapuri Colony	-
3		Nanakramguda	Gowlidoddi	11KV	Gachibowli	17.11	18.40	01.29	EL	11KV AB Cable Starting and Ending End Kit Failure to Cable removed near Home Inn Hostel at Gowlidoddi.	-
1	RR E	Yadgarpally	Timmaipally	11KV	Habsiguda	12.30	14.10	01.40		11KV Pole damaged at Saight Walls Timmaipally	-
1	HYD S	Aliabad	Rooplal Bazar	11KV	III	02.50	04.56	02.06	OL	4Nos HG fuses blown at Shah Gouse Area	-
2		Malakpet	Bibi Ka Alawa	11KV	VIII	18.20	20.11	01.51	EL	Cable fault	Arranged B/F on 11KV Farath Nagar feeder
3		Hyderguda	Hyderguda	11KV	III	18.25	20.05	01.40	EL	Pin Insulator flash over at Pleasure Park	-
1	HYD C	Bathkammakunta	Bathkammakunta	11KV	II	18.30	20.30	02.00	EL	Pin Insulator flash over at Karthika Apts	-
2		Asif Nagar	Military	11KV	VII	18.50	20.10	01.20	EL	Tree branches fallen on lines at Military Area	-
3		Asif Nagar	Toli Chowki	11KV	VII	18.45	21.20	02.35	EL,OL-R&Bph	UG Cable failed at Alasnath Colony	-