

TSSPDCL - LMRC / Corporate office

Date: 15.07.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Kangal	Kopple	33KV	Devarakonda	2:00	6:00	4:00	EL/OL	2 insulator failure Near Kangal SS-24,SS-25	Kopple	No
1	RR N	Medchal	Devarayamjal	33KV	Medchal	18:39	20:04	1:25	EL&OL	11KV Line touched with the 33KV Devaramjal Line at Saigeetha Asramam Road (Due to Lorry touched with 11KV Line), Bus Isolator damaged in 132KV Medchal	Devarayamjal	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pasupula	Mustipally	11KV	Mahabubnagar	6:30	9:00	2:30		11KV Conductor cut at Parevulla (Vi)	No
1	NLG	Kethapally	Inupamula	11KV	Suryapet	6:30	9:00	2:30	E/L	11KV Line cut	No
2		Gattuppal	Lachammagudem	11KV	Nalgonda	06.00	09.45	03.45	E/L	11KV Jumper cut	No
3		Palakeedu	Nagireddigudam	11KV	Huzurnagar	06.00	10.30	04.30	EL	11KV Line cut near Nagireddigudam village	No
4		Keethavarigudem	Rainigudam	11KV	Huzurnagar	14.50	17.20	02.30	EL	11KV Line snapped near Rainigudamvillage	No
5		Y.Singaram	Magdum nagar	11KV	Huzurnagar	09.30	13.00	03.30	OL	11Kv Jumper cut near Magdum nagar village	No
6		Thogarrai	GudiBanda	11KV	Huzurnagar	04.35	07.35	03.00	EL	11kv line cutted near GudiBanda village	No
7		Thogarrai	Ganapavaram	11KV	Huzurnagar	04.30	05.45	01.15	OL	AB Switch fault near Ganapavaram village	No
8		Mamillagudem	Thummalapally	11KV	Huzurnagar	08.50	10.30	01.40	OL	Tree branch fall on 11Kv line near Thummalapally village	No
9		G.Malkapuram	Chinriyala	11KV	Huzurnagar	10.00	12.30	02.30	EL	AB Switch fault near Chinriyala village	No
10		Paladugu	Dattapagudem	11KV	Bhongir	14.45	16.40	01.55	EL	3 Ph DTR Jumper snapped at Dattapagudem	No
11		K.M.Pally	Palwai	11KV	Devarakonda	7:00	11:00	4:00	EL	Insulator failure	No
1	MDK	Kowdipally	Yelmakanna	11KV	Medak	11:00	12:00	1:00		B/D due to 11KV Conductor Snapped	No
2		Nizampur	Venkatapur	11KV	Sangareddy	05.00	08.00	03.00		Conductor Snapped at Venkatapur Village	No
1	RR S	Mamidipally	Quba Colony	11KV	Champapet	16:44	18:18	1:34	EL	11KV Jumper snapped at Pahadishareef X road	No
2		Champapet	Anjireddy Colony	11KV	Champapet	19.30	20.10	00.40	EL	11KV Insulator failed at Karmanghat Srivani apartment	No
1	RR N	Balaji Nagar	Indu Project-1	11KV	Gachibowli	9:58	11:05	1:07		11kv UG-Cable damaged at Indu Apartments	No
2		Gachibowli	Aparna	11KV	Gachibowli	18.45	19.45	01.00		11kv Disk failed at Nallagandla huda	No
3		Vijayanagar	Aruna society	11KV	Kukatpally	07.55	08.55	01.00		A Bird Fallen On the 11kv Line At Sai Paven Redency	No
4		J D M SS-I	Raghava	11KV	Kukatpally	00.05	02.45	02.40		11kv Jumper cut In Sub Station	No
5		J D M SS-I	Apiic	11KV	Kukatpally	04.40	06.20	01.40		11kv Ab Cable Failure at Apiic Colony	No
6		KPHB	Huder Nagar	11KV	Kukatpally	11.33	12.50	01.17		11kv AB Cable Failure at More Super Market Nizampet X Road	No
7		Town Medchal	Balaji Nagar	11KV	Medchal	06.30	08.40	02.10		No visible fault	No
8		Kandlakoya	Saigeetha Asramam	11KV	Medchal	18:50	19:20	0:30		11KV Line touched with the 33KV Devaramjal Line at Saigeetha Assramam Road (Due to Lorry touched with 11KV Line)	No
1	RR E	Vinayak Nagar	Old Safilguda	11KV	Sainikpuri	20:15	21:20	1:05		11Kv UG cable failure at Railway Track Chandragiri Colony	No
1	HYD N	Raheja	Gafoor Nagar	11KV	Banjara Hills	17.58	20.20	02.22	All Indication	faulty loads of 11KV Kummur Basti feeder	No
1	HYD S	Salarjung	Pathar Gatti	11KV	Charminar	23.05	00.40	01.35	All Indication	I/C Yph Jumper at SS	No

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		2		2		2			
5	RR(N)	82	407	1	8	1	8	1	8			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014		2		2		2			
	Total	504	2929	1	13	1	13	1	13	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948	1	11	1	11	1	11			
3	MDK	87	828		2		2		2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	14	1	14	1	14	0	0	
	Grand Total	908	6149	2	27	2	27	2	27	0	0	