

TSSPDCL - LMRC / Corporate office

Date: 18.07.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Marriguda	Shivannagudem	33KV	Devarakonda	03.15	06.20	03.05	EL	Tree Fallen the Line Near K.B.Pally	Marriguda	-
1	MDK	Sadasivpet	Munipally	33KV	Sangareddy	13.40	14.50	01.10		B/D Due to Insulator failure	Sadasivpet	-
2		Zaheerabad	Jharasangam	33KV	Sangareddy	14.20	15.40	01.20		B/D Due to Jumper Cut	Zaheerabad	-
1	HYD N	132KV Erragadda	Srinagar Colony	NT	Kalyan Ngr	11.38	11.53	00.15	EL,OL	33KV Cable End Kit failed near 132KV Erragadda SS	132KV Erragadda	Loads transferred onto 33KV Erragadda - Yellareddyguda line

TSSPDCL - LMRC / Corporate office

Date: 18.07.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	B.Banda	B.Banda	11KV	Suryapet	05.00	08.00	03.00	E/L	Jumper cut	-
2		Ch.Annaram	Ch.Annaram	11KV	Suryapet	11.40	13.30	01.50	E/L	Jumper cut	-
3		Aipoor	Aipoor	11KV	Suryapet	12.10	14.20	02.10	E/L	Line cut	-
4		Aregudem	Pedda Kaparthy	11KV	Nalgonda	08.00	10.40	02.40	E/L	11KV line milting	-
5		Kanagal	Kanagal	11KV	Nalgonda	06.00	07.00	01.00	O/L	Insulator failed	-
6		Madgulapally	Dacharam	11KV	Nalgonda	13.00	15.00	02.00	E/L	Insulator failed	-
7		Mamidala	Mamidala	11KV	Nalgonda	05.00	06.50	01.50	O/L	Insulator failed	-
8		Narketpally IE	Vanipakala	11KV	Nalgonda	09.30	12.00	02.30	E/L	Jumper cut	-
9		Thoragal	Thangalavari gudem	11KV	Nalgonda	08.45	11.30	02.45	O/L	11KV line cut	-
10		Cherukupally	Bollnampally	11KV	Devarakona	07.00	10.30	03.30	EL	Tree Fallen tha Line Near Bollanampally	-
11		Kopple	A.B.Colony	11KV	Devarakona	04.00	07.00	03.00	EL	insulator failure Near Sudhakar well	-
12		Kopple	Bollaram	11KV	Devarakona	06.00	10.00	04.00	EL	11kv Jumper cutting	-
13		Marriguda	Y.G.Pally	11KV	Devarakona	03.00	06.00	03.00	EL & OL	25KVA New DTR AB Switch to Cross arms	-
14		Palakeedu	Sajjapuram	11KV	Huzurnagar	00.00	02.00	02.00	EL	Due to 11kv Snapped near Sajjapuram village	-
15		Palakeedu	Palakeedu	11KV	Huzurnagar	06.15	09.15	03.00	EL	Due to 11kv Snapped near Palakeedu village	-
16		Garidepally	Ponugodu	11KV	Huzurnagar	10.20	13.00	02.40	EL	Due to Tree branch fall on 11kv line near Ponugodu village	-
17		Mattampally	Choutupally	11KV	Huzurnagar	09.40	11.40	02.00	EL	Due to 11Kv line cutted cutted near Choutupally village	-
18		Huzurnagar	Y.Singaram	11KV	Huzurnagar	02.30	04.30	02.00	EL	Due to 11Kv Disk failure near Y.Singaram village	-
19		R.N.Palem	Gundlapally	11KV	Huzurnagar	00.00	02.45	02.45	EL	Due to Jumper Cut near Gundlapally village	-
20		Repala	Repala	11KV	Huzurnagar	00.00	03.00	03.00	EL	Due to Jumper Cut near Repala village	-
21		Akupamula	Singaram	11KV	Huzurnagar	11.10	13.45	02.35	EL	Due to 11 kv snapped near Singaram village	-
22		Siripuram	Srirangapuram	11KV	Huzurnagar	11.25	14.00	02.35	EL	Due to Jumper Cut near Srirangapuram village	-
23		Mamillagudem	Vibula puram	11KV	Huzurnagar	14.30	16.10	01.40	OL	Due to Tree branch fall on 11kv line near Vibula puram village	-
24		Ponugodu	Kothagudem	11KV	Huzurnagar	07.00	09.00	02.00	EL	Due to Insulator failure near Kothagudem village	-
25		Karvirala	Ramchandrapuram	11KV	Huzurnagar	05.00	08.00	03.00	EL	Due to Insulator failure near Ramchandrapuram village	-
26		Keethavarigudem	Velidanda	11KV	Huzurnagar	07.10	08.35	01.25	OL	Due to Tree branch fall on 11kv line near Velidanda village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
27		N.B.Gudem	Redlakunta	11KV	Huzurnagar	06.30	08.00	01.30	EL	Due to Insulator failure near Redlakunta village	-
28		Amaravaram	Amaravaram	11KV	Huzurnagar	05.30	08.00	02.30	EL/OL	Due to Jumper Cut near Amaravaram village	-
29		Gaddipally	Medaram	11KV	Huzurnagar	07.00	10.00	03.00	EL	Due to 11 kv snapped near Medaram village	-
30		Mukundhaapuram	Dacharam	11KV	Huzurnagar	14.06	17.00	02.54	OL	Due to Tree branch fall on 11kv line near Dacharam village	-
1	MDK	Toopran	Nacharam	11KV	Toopran	09.50	11.20	01.30		B/D Due to Insulator Failure	-
2		Kallakal	Kallakal AGL	11KV	Toopran	07.00	10.00	03.00		B/D Due to Jumper Cut	-
3		Ramayampet	Ramayampet Agl	11KV	Toopran	03.20	08.20	05.00		B/D Due to Insulator Failure	-
4		Chegunta	Chegunta Town	11KV	Toopran	10.00	12.00	02.00		B/D Due to Jumper Cut	-
5		Jagadevapur	Itikyala	11KV	Toopran	06.00	09.00	03.00		B/D Due to tree Branches fallen on line	-
6		Wargal	Choudarpally	11KV	Toopran	13.00	14.00	01.00		B/D Due to tree Branches fallen on line	-
7		Gaddapotharam-II	Apex	11KV	Medak	05.20	10.30	05.10		B/D Due to Conductor snapped	-
8		Gaddapotharam-I	Matrix	11KV	Medak	00.00	01.40	01.40		B/D Due to Jumper Cut	-
1	RR S	Mamidipally	Rajev gandhi nagar	11KV	CHPT	01.20	03.57	02.37		11KV Line snapped at charminar masjid pahadishareef	-
2		Mamidipally	Aghakhan	11KV	CHPT	07.25	10.05	02.40		11KV Insulators failed at agha khan foundation	-
3		Mamidipally	Rajev gandhi nagar	11KV	CHPT	09.34	11.00	01.26		Tree branches fallen on 11KV Line at Waddera basthi, Pahadishareef	-
4		Mallapur	Venkatapur	11KV	CHPT	02.15	05.32	03.17		insulators failed at MIM office Venkatapur	-
5		Ibrahimbagh	Military-I	11KV	RJNR	12.45	14.02	01.17	B/D	Bird Fallen on 11kv Line at Pasha colony	-
6		APPA	Himayathsagar	11KV	RJNR	02.10	03.10	01.00	B/D	Tree branches fallen on 11KV Line at Exchange academy	-
7		APPA	Himayathsagar	11KV	RJNR	09.20	11.35	02.15	B/D	Tree branches fallen on 11KV Line at Exchange academy	-
8		NPA	Hasan nagar	11KV	RJNR	07.49	09.10	01.21	B/D	Tree branches fallen on 11KV Line at SS-1/1 T/F Hasan nagar	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Mathrusri Nagar	Madhava Nagar ©	11KV	Gachibowli	10.50	11.55	01.05	BD	11kv Pin-insulator failed beside Navya Hotel, Madhava Nagar	-
2		Chanda Nagar	Chanda Nagar	11KV	Gachibowli	08.00	13.30	05.30	BD	11kv Cable kit failed at Sub-Station Opposite	-
3		Gachibowli	Aparna	11KV	Gachibowli	00.30	01.50	01.20	BD	11kv Pin-insulator failed at Apana, Line AB-Switch opened Opposite Software company	-
4		Gachibowli	Sudharshan Nagar	11KV	Gachibowli	08.10	09.30	01.20	BD	Line AB-Switch opened at Navayuga, and tree branches fallen on the 11kv line at Sub-Station Opposite	-
5		Gachibowli	Sree Ram Nagar(K)	11KV	Gachibowli	13.25	15.30	02.05	BD	11kv Pin-insulator failed (2 No) at Madhu Construction and Chira public school	-
6		IIIT	IVRCL	11KV	Gachibowli	06.22	07.26	01.04	BD	HG fuse failed at IVRCL, 10th block(11KV UG Cable and AB-Switch opened at Gopichand Academy)	-
7		Lanco Hills	Khajaguda	11KV	Gachibowli	12.27	14.56	02.29	BD	11kv pin-insulator failed at Sai Aishwarya Layout, Khajaguda	-
8		Lanco Hills	Khajaguda	11KV	Gachibowli	15.20	16.20	01.00	BD	11kv pin-insulator failed at Stadium Opposite, Khajaguda	-
9		Ayyappa Society	Servey of india(K)	11KV	Gachibowli	06.10	07.30	01.20	BD	11kv Jumper cut at Thanda, Ayyappa Society	-
10		Shemshiguda	Tulsi vanam	11KV	Kukatpally	07.20	09.30	02.10	BD	11kv AB Cable Failure At P J R Colony	-
11		Jeedimetla-III	Vinayakanagar	11KV	Kukatpally	12.10	12.50	00.40	BD	11kv line 3No pole Bend at Vijaya Sri Chemical at Vinayaka anagar	-
12		DPPally	Ganddimaisamma	11KV	Kukatpally	09.00	10.00	01.00	BD	11kv line Jumper Cut near Sub-Station	-
13		Jeedimetla-IV	Axies	11KV	Kukatpally	11.10	12.25	01.15	BD	11kv line Jumper Cut near Ice Company	-
14		Jeedimetla-IV	AAI Matha	11KV	Kukatpally	11.35	12.55	01.20	BD	11kv line Jumper Cut at AAI Matha Temple	-
15		Bowrampet	Co-Ca-Cola	11KV	Kukatpally	11.50	12.45	00.55	BD	11kv line pinInsulater failure near Arbitukes School Bowrampet	-
16		Kompally	Petbasherabad	11KV	Medchal	00.15	01.20	01.05	BD	Tree falledn on the 11KV line at RR hospital	-
17		Subash nagar	Jairam nagar	11KV	Medchal	03.30	04.50	01.20	BD	11KV pin insulater failed at gayathri nagar	-
18		Medchal	IDA-I	11KV	Medchal	05.46	07.17	01.31	BD	11KV jumper cut and AB switch opend at sagar Asia Company IDA Medchal	-
19		Dulapally	IDA-II	11KV	Medchal	06.10	07.50	01.40	BD	11KV pin insulater failed at SS Kwanta	-
20		Aliabad	LGMpet	11KV	Medchal	07.00	10.50	03.50	BD	11KV pin insulater failed at forest side	-
21		Medchal	IDA-I	11KV	Medchal	11.02	12.52	01.50	BD	11KV pin insulater failed at ganesh kwanta	-
22		Thurakapally	Thurakapally	11KV	Medchal	13.10	16.50	03.40	BD	11KV pin insulater failed at Dharmareddy Thota Thurakapally	-
23		Komapplky	Content Park	11KV	Medchal	11.08	12.17	01.09	BD	11KV AB cable & pin insulater failed at Sri Venu gate LNCL	-
24		Athevelly	IDA	11KV	Medchal	16.10	17.05	00.55	BD	Tree falledn on the 11KV line Willow spring Dhaba Dabeerpur	-
25		Aliabad	Ravileea	11KV	Medchal	13.00	17.20	04.20	BD	CT failed ibn SS ,back feedin arangefrom 11KV HBLfeeder	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	BANDLAGUDA	VAMBAYCOLONY	11KV	SAROOR NAGAR	10.54	12.05	01.11	EL/OL	11KV INSULATER FAIL AT MANSOORABAD	-
2		Cherelapally-I	EC Computer	11KV	Sainikpuri	10.45	11.30	00.45		CTBT failed at Phase-II (L.Insp Satya Narayana)	-
3		Nacharam	Chandamama	11KV	Habsiguda	04.50	06.15	01.25		11KV & LT Line Snapped near Road No.10 Deepak Company at IDA Nacharam	-
4		Mallapur-2	AP Colony	11KV	Habsiguda	08.13	09.45	01.32		Line Patrolling & Tree branches fallen on 11KV line near Mayflower Park Apartments at Mallapur	-
5		Mallapur-2	Narsimha Nagar	11KV	Habsiguda	21.18	22.18	01.00		Net Cable wire touched to 11kv line near Thirumala Apartment at Narsimha Nagar	-
6		ABDULLAPERMET	ANAJPER	11KV	SAROOR NAGAR	08.15	09.20	01.05	OL	11KV LINE CUT AT ANAJPER	-
7		RFC	ANAJPER	11KV	SAROOR NAGAR	02.15	04.25	02.15	EL/OL	11KV LINE PERLLING NO FAIL	-
8		Chengicherla	Myvillas	11KV	Habsiguda	10.42	12.42	02.00		11KV Pin Insulator failed at Myvillas	-
9		Nagaran	Bandlaguda	11KV	Habsiguda	06.04	09.40	03.36		11KV Pin Insulator failed at Sri Ram nagar	-
10		Rampally Dayara	Kareemguda	11KV	Habsiguda	13.30	14.15	00.45		11KV 3 Poles damaged due to heavy rain & gale near Ramesh Reddy Bhavi	-
1	HYD N	Yousufguda	Venkatagiri	11KV	Banjarahills	00.20	02.58	02.38	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Venkatagiri Water Works feeder
2		Kalyan Nagar	Vengalrao Nagar	11KV	Banjarahills	07.15	09.05	01.50	EL	Moisture formed on DTR RMU at Erragadda Bus Stop	-
3		Jana Priya	Shankerlal Nagar	11KV	Erragadda	07.15	09.05	01.50	EL	Moisture formed on Bata Show DTR	-
4		Macha Bollaram	Father Balaiah Nagar	11KV	Bowenpally	10.20	12.20	02.00	EL	Cable fault at Citizen Colony	-
5		Yousufguda	Hylam Colony	11KV	Banjarahills	11.05	13.20	02.15	EL	Tree fallen on lines at Venkatagiri	-
6		Mothi Nagar	B.S.Puri	11KV	Erragadda	12.21	13.25	01.04	All Indication	RMU fault at Plot No.137, B.S.Puri	-
1	HYD S	Malakpet	Chaderghat	11KV	Asmangadh	09.10	10.40	01.30	EL	Cable End Kit fault at Maisamma Temple	-
2		Seetharambagh	Asif Nagar	11KV	Begumbazar	21.48	23.00	01.12	EL	Pin Insulator flash over at Drupathi Garden	-
1	HYD C	Fever Hospital	Tourist Hotel	11KV	Azamabad	06.25	09.57	03.32	All Indication	Cable fault	Partial fdr charged & remaining loads added on 11KV Quthbiguda fdr
2		S.D.Hospital	Humayun Nagar	11KV	Mehdipatanam	08.52	10.30	01.38	EL	Tree branches fallen on HT lines at Prince Hotel	-
3		Gudimalkapur	Navodaya Colony	11KV	Mehdipatanam	09.29	10.40	01.11	EL	No Visible Fault	-
4		Chilkaiguda	Golconda X Road	11KV	Azamabad	13.30	17.35	04.05	EL	Insulator flash over & Jumper cut	-

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		8		8		8			
5	RR(N)	82	407		25		25		25			
6	RR(E)	38	360		10		10		10			
7	Hyd	186	1014	1	12	1	12	1	12			
	Total	504	2929	1	55	1	55	1	55	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948	1	30	1	30	1	30			
3	MDK	87	828	2	8	2	8	2	8			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	38	3	38	3	38	0	0	
	Grand Total	908	6149	4	93	4	93	4	93	0	0	