

TSSPDCL - LMRC / Corporate office

Date: 17.06.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevally	Hemajipur	11kv	Jadcherla	06.00	10.20	04.20		11KV Insulator Failure near Hemajipur(V)	-
2		Bhoothpur	Amistapur	11kv	Jadcherla	06.00	10.00	04.00		11KV Disc Failed at HBL Back Side Bhoothpur(V)	-
3		Kourampet	Kourampet	11kv	Jadcherla	06.20	07.20	01.00		11KV Pole Damaged at Bandameedipally(V)	-
4		Nagaram	Ellikatta	11kv	Jadcherla	09.30	13.30	04.00		DTR Failed at Ellikatta(V)	-
1	NLG	Reddygudem	Kothagudem	11kv	Suryapet	10.45	13.00	02.15	E/L	11Kv Jumper cut	-
2		Koduru	Kommala	11kv	Suryapet	06.00	08.30	02.30	E/L	11Kv Insulator failed	-
3		Mukundapuram	Mukundapuram	11kv	Huzurnagar	02.00	05.00	03.00	EL/OL	11KV line melt near Munkundhapuram (v)	-
4		M R Gudem	Gangasanipally	11kv	Bhongir	03.00	06.00	03.00	E/L	11Kv Jumper snapped at Gangasanipally	-
5		Narkatpally IE	Vattimarthy	11kv	Nalgonda	02.20	06.00	03.40	E/L	11KV Insulator failed at SS-14	-
6		Marrigudem	Y.G.Pally	11kv	Devarakonda	08.00	11.00	03.00	E/L	11Kv Insulator failed	-
1	MDK	Jinnaram	Jinnaram	11kv	Medak	12.10	13.50	01.40		B/D due to 11KV Jumper Cut Near Jinnaram Vg	-
1	RR N	Devarayamjal	Kottapet	11kv	Medchal	12.05	13.25	01.20		HT Line fallen on the LT Line at Saigeetha Asramam	-
2		Dulapally	IDA-II	11kv	Medchal	12.54	13.32	00.38		11KV Jumper cut at Siddivinayaka Company, IDA Dulapally	-
3		Kolthur	Vishwa	11kv	Medchal	17.25	18.30	01.05		Tree Fallen on 11KV Line at Rice mill,Kolthur	-
4		Kolthur	Anantharam	11kv	Medchal	17.15	18.45	01.30		11KV Conductor Snapped at Lingaiah Bavi,Anatharam	-
5		Gowdavelly	Basaragadi	11kv	Medchal	16.40	17.50	01.10		11KV Pin Insulator Failed at Viba Seeds,Bandamadaram Road	-
6		Medchal	Town Medchal	11kv	Medchal	16.33	18.40	02.07		11KV Tree Fallen on 11KV Line at Lamba Garden,Checkpost and 11KV Conductor snapped at REVL backside	-
7		Athiwelly	Dabeerapur	11kv	Medchal	19.30	20.20	00.50		11KV Jumper Opened at Railway Colony(11KV Conductor Snapped)	-
8		Madinguda	Swarnapuri Colony	11kv	Kukatpally	11.20	13.06	01.46		11kv line AB Cable Failure near Krishna Sai Apt at Swarnapuri Colony	-

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Erragadda	Jana Priya	33kv	Erragadda	04.24	04.28	00.04	EL,OL	Cable fault near Vijaya Towers, Mothi Nagar	Jana Priya	Loads transferred onto 132KV Erragadda SS via 33KV I.D.P.L feeder

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		8		8		8			
6	RR(E)	38	360									
7	Hyd	186	1014	1		1		1				
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		4		4		4			
2	NLG	150	948		6		6		6			
3	MDK	87	828		1		1		1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>1</b>	<b>19</b>	<b>1</b>	<b>19</b>	<b>1</b>	<b>19</b>	<b>0</b>	<b>0</b>	