

TSSPDCL - LMRC / Corporate office

Date: 18.06.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Maganoor	33KV	Mahabubnagar	21.15	22.20	01.05	E/L	Closing 33KV Maganoor Opened Incoming Bus AB Switch at Maganoor SS & Supply to Maganoor SS by Gudeballore Feeder No Supply to Kolpur SS	Maganoor	No
2		Thirumalaipally	Kurumurthy	33KV	Wanaparthy	16.31	19.51	03.20	E/L	33KV Insulator Damaged near Wanaparthy Road Railway Gate	Kurumurthy	No
1	HYD N	132KV Erragadda	Mothi Nagar	33KV	Allwyn	00.18	00.30	00.12	OL-Rph	End Kit failure near SS	Mothi Nagar	Loads transferred onto 132KV Erragadda SS via 33KV I.D.P.L. fdr

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pallerla	Nandipad	11KV	Mahabubnagar	15.10	16.16	01.06		11KV Insulator Damage at Nandipad (vi)	No
2		Maddur	Pallerla	11KV	Mahabubnagar	15.45	19.02	03.17		11KV Insulator Damage at Chinthaldhinne (vi)	No
3		Makthal	Nerdgam	11KV	Mahabubnagar	12.00	13.00	01.00		11KV Conductor cut Near Makthal (Vi)	No
4		Badepally	Badepally	11KV	Jadcherla	16:25	18:00	1:35		Pole damaged at Nallakunta at Badepally	No
5		Badepally	Malleboinpally	11KV	Jadcherla	14.25	18.35	04.10		11KV insulator failed near Shivalayam temple Old Bazar Badepally	No
1	NLG	Marriguda	Thamadapally	11KV	Devarakonda	8:00	10:30	2:30	EL	Jumper Cut	No
2		Koppole	Bheemaram	11KV	Suryapet	04.10	06.40	02.30	E/L	Tree Branche fallen	No
3		Dirsincherla	Dirsincherla	11KV	Huzurnagar	03.00	09.00	06.00	EL	Due to 11 Kv Jumper cut near Dirsincherla village	No
4		Mamillagudem	Vibula puram	11KV	Huzurnagar	03.10	07.45	04.35	EL	Due to 11kv line snapped near Vibula puram vllage	No
5		Gurraladandi	Raviphad	11KV	Bhongir	07.00	09.45	02.45	EL	Single Ph DTR Failure & 11Kv Line snapped at Raviphad	No
6		Nandanam	Nagireddy Pally	11KV	Bhongir	23.00	02.00	03.00	EL	Tree Branches Fallen On Line Near Yerramballi	No
7		Narkatpally	Mandra	11KV	Nalgonda	11.00	12.30	01.30	EL	11KV Insuletor Failed	No
8		Laxmapur	Laxmapur	11KV	Nalgonda	13.20	15.50	02.30	EL	11kv Line Melting SS NO 13	No
1	MDK	Kowdipally	Mohd Nagar	11KV	Medak	5:00	12:50	7:50		B/D due to 11KV Line cut	No
2		Jinnaram	Jinnaram	11KV	Medak	11.00	14.20	03.20		B/D due to 11KV insulator failed	No
3		Anantharam	Kanukunta	11KV	Medak	05.00	13.00	08.00		B/D due to 11KVDisc insulator failed	No
1	RR N	Gachibowli	Mezquity	11KV	Gachibowli	14:25	15:40	1:15		Bird Fallen on 11kv Line at Gotami Society	No
2		Kothaguda	Jagruthi Colony	11KV	Gachibowli	16.45	18.05	01.20		Tree Branches Fallen on the 11kv Line at Anand Nagar Masjid Back Side	No
3		IIT	Kendriya Vihar	11KV	Gachibowli	16.20	17.42	01.22		11kv Disk Failed at KFC Back Side Vinnyak Nagar	No
4		Madinaguda	Aurobindo	11KV	Gachibowli	18.32	21.25	02.53		11kv Disk Failed at Sitra Hotel, Allwyn Colony	No
5		Jeedimetla-I	C S Wire	11KV	Kukatpally	16.27	17.43	01.16		11kv line Endkit failure at Azanda Engineer ,phase-Line	No
6		Jeedimetla-III	Backlighty Hylam	11KV	Kukatpally	16.55	18.35	01.40		11kv line PinInsulater Failure at opp: JETL & { Due to Rain}	No
7		Medicity	Munirabad	11KV	Medchal	17.00	17.55	00.55		Tree Fallen on 11KV Line at Balasani Thota ,Munirabad	No
8		Kistapur	Goshaiguda	11KV	Medchal	17.30	18.20	00.50		Tree Fallen on the 11KV Line at Tekkala, Goshaiguda	No
9		Medchal	IDA Kandlakoya	11KV	Medchal	17:25	18:10	0:45		CTPT Problem Astra Daimond Company, IDA Medchal	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	St.No.08	Ravindra Nagar	11KV	Habsiguda	13:28	14:38	1:10		Bird fallen on 11KV line near Swathi Tiffins Backside	No
2		Ramanthapur	Gokhale Nagar	11KV	Habsiguda	19.00	20.00	01.00		11KV Line snapped near Shubham Garden at R'pur MainRoad	No
3		Peerzathiguda	Shankar Nagar	11KV	Habsiguda	04.30	05.30	01.00		11KV Copper patti cut at Shankar Nagar	No
4		Keesara	Anki Reddy Pally	11KV	Habsiguda	05.30	07.30	02.00		Lorry dashed to 11KV Pole & Pole damaged at AR Pally 'X' Road	No
5		Abdullapurmet	Batasingaram	11KV	Saroornagar	17.30	19.40	02.10	EL	Tree BRACHANS FALLOW ON 11KV LINE AT batasingaram	No
6		Abdullapurmet	Sanghi	11KV	Saroornagar	17.30	20.25	02.55	OL	11kv line AB switch open at AGL side feeder charge	No
7		RFC	Umarkhanguda	11KV	Saroornagar	19.05	20.00	00.55	EL/OL	DTR copper patty cut at near ranga raj poultry	No
8		Kothapet	Dental college	11KV	Saroornagar	01.35	02.18	00.43	EL/OL	11KV end kit fail at kamalanagar road no 3	No
9		RR Court	Shivaganga	11KV	Saroornagar	17:16	19:12	1:56	EL/OL	2 no 11kv pin insulators fail at srinivasa colony	No
1	HYD N	Kalyan Nagar	Vengalrao Nagar	11KV	Jublee Hills	03.48	05.29	01.41	EL,OL-R&Bph	No Visible Fault	No
2		LV Prasad Marg	Gymkhana Club	11KV	Jublee Hills	4:13	5:14	1:01	EL,OL	HT Jumper cut at Eye Hospital Gate	No
3		Madhapur	Ohris	11KV	Jublee Hills	16:20	17:40	1:20	OL-R&Bph	Faulty End Kit at Opp. Infotech	No
4		Hakimpet	Risala Bazar	11KV	Bowenpally	16:57	18:05	1:08	EL,OL-Rph	HT Jumper cut at Risala Bazar Bus stop	No
5		Marredpally	Nehru Nagar	11KV	Sec'bad	17:00	18:10	1:10	EL	Faulty DTR at Club	No
6		Allwyn	E.S.I.	11KV	Erragadda	17:55	20:10	2:15	EL,OL	Tree branches fallen on Lines & HT Jumper cut at Sunder Nagar	No
7		Allwyn	I.O.L	11KV	Erragadda	17.30	19.50	02.20	EL	Conductor snapped at ECE factory	No
1	HYD S	Miralam	Ranjan Colony	11KV	Charminar	16.40	18.15	01.35	EL,OL	Faulty DTR at King Darbar Hotel & Bushing Jumper cut at Rasoolkhan Janda	No
1	HYD C	Lakeview	NKMS Hotel	11KV	Saifabad	19.36	20.45	01.09	EL	I/C Cable fault at SS	Arranged B/F on 11KV Viaya Hospital fdr

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		9		9		9			
6	RR(E)	38	360		9		9		9			
7	Hyd	186	1014	1	9	1	9	1	9			
	Total	504	2929	1	27	1	27	1	27	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2	5	2	5	2	5			
2	NLG	150	948		8		8		8			
3	MDK	87	828		3		3		3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	16	2	16	2	16	0	0	
	Grand Total	908	6149	3	43	3	43	3	43	0	0	