

TSSPDCL - LMRC / Corporate office

Date: 19.06.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Peddmandadi	33KV	Wanaparthy	20.58	21.35	00.37	E/L	Tripped on E/L Due to Heavy Wind & Gail	Peddmandadi	At 21:35 hrs. Alternate Supply Arranged at 132KV Thirumalaipally SS
1	MDK	Narayankhed	Poosalpad	33KV	Jogipet	4:45	10:20	5:35		Insulator failed near Panchagama Village.	Poosalpad	No
2		Narayankhed	Wasar	33KV	Jogipet	05.10	11.15	06.05		B/D due to Insulator failed	Wasar	No
3		Jogipet	Laxmisagar	33KV	Jogipet	08.05	12.35	04.30		Tree branches fallen on the line near Sangupet Village.	Laxmisagar	No
4		Chegunta	Narsingi	33KV	Toopran	01.20	07.35	06.15		Disc failed near narsingi Village.	Narsingi	No
5		Siddiept	Narayanraopet	33KV	Siddiept	1:10	7:10	6:00		B/D due to Insulator failed.	Narayanraopet	No
1	RR S	220kv Shivarampally	33kv Upparpally	33KV	Rajendranagar	6:10	6:40	0:30		33kv Cable failed at Ag College	Upparpally	No
1	RR N	Madhapur	Hitech city	33KV	Gachibowli	1:15	2:30	1:15	EL,OL	B/D due to Konadapur HSBC A-Block Meter panel burnt	Hitech city	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bomraspet	Erupumalla	11KV	Mahabubnagar	10.00	11.00	01.00		11KV Insulator Damage at Erupumalla(vi)	No
2		Hamsanipally	Gouraram	11KV	Mahabubnagar	09.40	10.05	00.25		11KV Insulator Damage Near Gouraram(vi)	No
3		Mogalmadka	Mogalmadka	11KV	Mahabubnagar	10.30	12.30	02.00		11KV Jumper cut at Thirumalapur (vi)	No
1	NLG	Mandapuram	Kumarid	11KV	Devarakonda	8:00	10:00	2:00	E/L	11kv Jumper cut	No
2		Nampally	Madapurm	11KV	Devarakonda	04.00	07.00	03.00	O/L	11kv Insulator failed	No
3		Sh. Gowraram	Kondaram	11KV	Suryapet	06.00	09.00	03.00	E/L	11Kv Insulator failed	No
4		Bethavolu	chennarigudem	11KV	Huzurnagar	10.20	11.50	01.30	EL/OL	11Kv Jumper Cut near chennarigudem village	No
5		Dondapadu	Kakatiya	11KV	Huzurnagar	04.00	05.30	01.30	E/L	11Kv Insulator Failure near Kakatiya village	No
6		Akkenapally	Akkenapally	11KV	Nalgonda	09.00	12.00	03.00	E/L	HT / LT Line Melting near By Kummarinarsimha Bavi	No
7		Rajupeta	Rajupeta	11KV	Nalgonda	13.00	14.20	01.20	E/L	11KV Line Insulator Failed	No
8		Nandanam	Tukkapur	11KV	Bhongir	02.00	05.00	03.00	E/L	11KV Disk failed at Tukkapuram	No
9		Kondamadugu	Kondamadugu	11KV	Bhongir	2:00	5:00	3:00	E/L	11KV Jumper snapped at Guduru	No
1	MDK	B.B Pur	Burugupally	11KV	Medak	5:00	9:00	4:00		Tree branch fallen on the line 11 kv wire	No
2		Narsapur	Avancha	11KV	Medak	10.00	12.00	02.00		Insulator failed	No
3		Narsapur	Kajzammadur	11KV	Medak	10.00	12.00	02.00		Conductor snapped	No
4		Avancha	Ramchandrapuram	11KV	Medak	06.00	11.00	05.00		B/D due to 11 kv disc failed	No
5		Kulcharam	Kulcharam	11KV	Medak	05.00	11.52	06.52		B/D due to Conductor snapped	No
6		Amsanpally	Kongode	11KV	Medak	11.00	12.00	01.00		Jumper cut	No
7		Kowdipally	Mohd Nagar	11KV	Medak	4:20	9:50	5:30		Tree branch fallen on the 11KV line	No
1	RR S	Mallapur	Shaheen Nagar	11KV	Champapet	4:30	8:53	4:23	EL/BD	Tree branches fallen on the 11KV Line at shaheen nagar	No
2		Injapur	CRPF	11KV	Champapet	04.58	06.42	01.44	EL/BD	11KV Disc failed at petrol pump oposite venkateshwara nagar	No
3		Vanasthalipuram	Chaitnyanagar	11KV	Champapet	04.50	05.40	00.50	EL/BD	11KV Insulator failed at venkramana colony AB Switch open at AGL Colony	No
4		Indira gandhi society	Indirashivashakti	11KV	Rajendranagar	RJNR	12.10	05.20		CTPT Failed at JS bakery opp Pooranamall	No
5		Gaganpahad	Manage	11KV	Rajendranagar	07.27	11.40	04.13		CTPT Problem mahalaxmi battery & metro shopping mall ,Goshala Due to Heavy Rain	No
6		Gaganpahad	Rajendranagar(GPH D)	11KV	Rajendranagar	07.27	09.11	01.44		No visible fault Due to Heavy Rain	No
7		CBIT	Movie tower	11KV	Rajendranagar	09.10	10.10	01.00		11kv Insulator failed at Movie tower	No
8		CBIT	Gandipet	11KV	Rajendranagar	11.40	13.40	02.00		11kv Disc failed at Brundavan colony	No
9		Kismathpur	LV Prasad	11KV	Rajendranagar	04.40	07.40	03.00		No visible fault Due to Heavy Rain	No
10		Kismathpur	Difence colony	11KV	Rajendranagar	05.15	06.25	01.10		No visible fault Due to Heavy Rain	No
11		Puppalaguda	Manikonda	11KV	Rajendranagar	15.30	16.35	01.05		11kv Disc failed at Tanisha nagar manikonda	No
12		MD Pally	Laxmiguda	11KV	Rajendranagar	06.30	07.40	01.10		11kv Disc failed at bombay colony	No
13		Ibrahimbagh	Osmansagar	11KV	Rajendranagar	7:52	9:16	1:24		Tree branches fallen on 11kv line	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jeedimetla SS I	Subhash Nagar	11KV	Kukatpally	5:47	9:25	3:38		Jumper cut	No
2		Jeedimetla SS II	Excell	11KV	Kukatpally	03.50	07.17	03.27		Pin insulator failed	No
3		Aleap	Doctor's Colony	11KV	Kukatpally	00.00	03.00	03.00		Pin insulator failed	No
4		Vijayanagar Colony	Jalakanya	11KV	Kukatpally	03.40	07.05	03.25		11KV line pin insulator failed at II nd Phase & due to heavy rain	No
5		Bahadurpally	IDA II	11KV	Kukatpally	00.21	01.03	00.42		A B Switch spark at Ice Company at Bachupally	No
6		DP Pally	Gagillapur	11KV	Kukatpally	11.00	14.00	03.00		Tree fallen on the 11kv line near cheruvu katta at Gagilapur	No
7		J D M SS III	U S P Organic	11KV	Kukatpally	15.55	17.10	01.15		11KV AB Cable failed at Standard Glass company	No
8		Shameerpet	Nalsar	11KV	Medchal	01.00	03.45	02.45		11KV Pin Insuator failed at Shameerpet Bus Stop	No
9		Medchal	IDA Kandlakoya	11KV	Medchal	05.20	08.40	03.20		11KV Pin Insulator failed near Outer Ring Road	No
10		Medchal	Rural Kandlakoya	11KV	Medchal	05.00	08.10	03.10		3 Places 11KV conductor Snapped at SS backside and Decan oil,IDA Medchal	No
11		GP Pally	Maisammaguda	11KV	Medchal	04.45	06.55	02.10		Tree Fallen on 11KV Line at Satyam computers	No
12		Kandlakoya	Goderj	11KV	Medchal	01.50	05.50	04.00		Tree fallen on 11KV Line at Sriram seeds company(Jumper Opened)	No
13		HMT	Quthbullapur	11KV	Medchal	04.00	05.25	01.25		11KV Pin Insulator Failed at Quthbullapur Auto stand	No
14		Ravalkole	IDA Ravalkole	11KV	Medchal	05.15	07.15	02.00		11KV Pin Insulator failed at venkateshwara gutta,Rajabollaram(11KV Jumper Opened)	No
15		Kistapur	Kistapur	11KV	Medchal	05.10	08.10	03.00		2 Nos Discs failed and Jumper cut at Archana colony,Kistapur	No
16		Gowdavelly	Basaragadi	11KV	Medchal	05.44	08.30	02.46		11KV Pin Insulator failed at MLR College, Ayodhya	No
17		Gowdavelly	Ayodhaya	11KV	Medchal	07.20	10.00	02.40		5 no. 11KV Poles damaged at Gowdavelly Cheruvukatta	No
18		Kompally	Kompally	11KV	Medchal	12.02	12.35	00.33		Tree branch fallen on the 11KV Line at Aparna Farm House	No
19		Kothaguda	Kondapur	11KV	Gachibowli	02.40	03.40	01.00		11kv Pin Insulator failed at Jublee Garden.Kondapur	No
20		Kothaguda	Botanical Garden	11KV	Gachibowli	02.48	05.50	03.02		11kv Line Phase to Phase,11kv Line Snaped & Jumper Cut at Ratnadeep Super Market	No
21		JNTU	Gokulplots	11KV	Gachibowli	03.52	05.10	01.18		No visible fault	No
22		Nanakramguda	Goulidoddi	11KV	Gachibowli	06.21	08.49	02.28		UG Cable failed & Cable Removed at Goulidoddi	No
23		ESCI	Gachibowli	11KV	Gachibowli	07.51	09.25	01.34		T/F AB Switch Sparked at Rajiv Nagar Gachibowli	No
24		Lanco Hills	Chitrapuri Colony	11KV	Gachibowli	8:40	10:14	1:34		No visible fault	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal	Raghavendra Colony	11KV	Habsiguda	4:50	6:20	1:30		Tree branches fallen at Uppal Police Quarters	No
2		Uppal	Raghavendra Colony	11KV	Habsiguda	08.15	09.50	01.35		Tree branches fallen at Govt Hospital Uppal	No
3		Uppal	Ghatkesar	11KV	Habsiguda	05.20	07.20	02.00		11KV Disc failed at Bharath Nagar	No
4		Mallapur-2	AP Colony	11KV	Habsiguda	04.19	05.50	01.31		Post Type Insulator failed at Janapriya Apartment	No
5		Mallapur	Standard Tiles	11KV	Habsiguda	03.20	04.50	01.30		Insulator failed at Manikchand X Road	No
6		Moula-Ali	Venkateshwar Nagar	11KV	Sainikpuri	05.00	06.15	01.15		11Kv line Jumper cut on Pin Insuletor failed at Laxmi Nagar (Foc Naresh)	No
7		Moula-Ali	Mirjalguda	11KV	Sainikpuri	06.35	08.20	01.45		Tree fallen on the 11Kv line at near Petri Bunk	No
8		Moula-Ali	Malkajgiri	11KV	Sainikpuri	01.50	02.45	00.55		11KV Insulator failed at Gayathri Nagar	No
9		Auto Nagar	Highcourt Colony	11KV	Saroonagar	07.10	09.05	01.55		HT/LT LT Line Cut at Sushmasai Nagar	No
10		Maruthi Nagar	Vasavi Colony	11KV	Saroonagar	03.50	06.10	02.20		No visible fault	No
11		Kothapet	Pushpagarden	11KV	Saroonagar	09.28	10.00	00.32		11KV Jumper cut at Vijaya Textiles Kothapet	No
12		Pirzadiguda	Pirzadiguda	11KV	Habsiguda	05.00	08.00	03.00		11KV Disc failed at Pirzadiguda	No
13		Singapur	RGK	11KV	Habsiguda	6:00	7:00	1:00		Insulator failed at Gayatri Temple	No
1	HYD N	N.I.M.S.	Banjara Hills	11KV	Banjara Hills	02.37	03.56	01.19	OL-R&Bph	Tree branches fallen on Lines at Gemini TV	No
2		Lalaguda	Vijayapuri	11KV	Sec'bad	3:35	5:25	1:50	EL,OL	Pin Insulator flash over at Vijayapuri	No
3		Zamisthanpur	S.P.College	11KV	Sec'bad	8:00	9:20	1:20	EL,OL	Tree branches fallen on Lines & HT Jumper cut at S.P.College	No
4		Chilkaiguda	P.R Nagar	11KV	Sec'bad	14:40	16:35	1:55	EL	Tree branches fallen on Lines & HT Jumper cut at Water Works	No
5		Nehru Nagar	J.B.S	11KV	Sec'bad	15.15	16.35	01.20	OL-Rph	HT Jumper cut at J.B.S	No
1	HYD S	Salarjung	Madina	11KV	Charminar	04.50	07.40	02.50	EL	Jumpers cut at SS & DE Office	No
2		Ch' Baradari	Ramnaspura	11KV	Charminar	4:55	6:25	1:30	EL	Pin Insulator flash over at Ramnaspura	No
3		Petlaburz	Chowk	11KV	Charminar	5:20	8:20	3:00	EL,OL	Cable fault	Arranged B/F on 11KV Gulzar House feeder
4		C.R.P.F	Balapur	11KV	Charminar	5:35	7:20	1:45	OL-R&Bph	HT Line twisted & tree branches fallen on Lines at Rahamath Masjid	No
1	HYD C	Bathkamma Kunta	Indira Nagar	11KV	Azamabad	04.40	05.50	01.10	EL,OL-Rph	Kite Sticks on lines at Tilak Nagar Railway Bridge	No
2		Fever Hospital	Fever Hosptial	11KV	Azamabad	04.55	06.10	01.15	EL,OL	Tree branches fallen on Lines at Ratna Degree College	No
3		Industrial Area	RTC X Road	11KV	Azamabad	06.30	09.30	03.00	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Dayara Market feeder

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201	1	13	1	13	1	13			
5	RR(N)	82	407	1	24	1	24	1	24			
6	RR(E)	38	360		13		13		13			
7	Hyd	186	1014		12		12		12			
	Total	504	2929	2	62	2	62	2	62	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	3	1	3	1	3			
2	NLG	150	948		9		9		9			
3	MDK	87	828	5	7	5	7	5	7			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	6	19	6	19	6	19	0	0	
	Grand Total	908	6149	8	81	8	81	8	81	0	0	