

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Kondapur	33KV	Mahabubnagar	23.30	06.10	06.40	E/L	Insulator failed	Marikal	No
2		Ghanapur	Solipur	33KV	Wanaparthi	16.26	18.18	01.52	E/L	Pad Clamp Replacement at Kandur Reliance tower	Solipur	No
3		Ghanapur	Lattupally	33KV	Wanaparthi	18.10	18.50	00.40	E/L	Tree branches follen on the line	Lattupally	Alternate Supply Arranged from 33KV Bijinepally feeder at 18:50hrs
1	NLG	Kanagal	Thimmannagudem	33KV	Nalgonda	5:00	8:30	3:30	EL	Jumper cut	Thimmannagudem	No
1	MDK	Habsipur	Thimmapur	33KV	Siddipet	12:15	12:55	0:40		Tree branches fallen on the line	Thimmapur	No
1	HYD N	132KV J' Hills	Road No.22	33KV	Kalyan Ngr	13.35	13.45	00.10	OL-Bph	Cable End Kit failed at 33KV Road No.22 SS	Road No.22	Loads transferred onto 132KV J' Hills SS via 33KV Yousufguda SS
1	HYD S	220KV Ch' Gutta	D.R.D.L	33KV	Malakpet	09.20	11.20	02.00	All Indication	Lightning Arrestor flash over at DRML HT Service	D.R.D.L	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddakadmoor	Nagal Kadmoor	11KV	Mahabubnagar	06.00	10.00	04.00		11KV Disc failure at Nagireddy pally (Vg)	No
2		Jaklair	Gudigandla	11KV	Mahabubnagar	10.00	11.00	01.00		11KV Conductor cut at Gudigandla(Vg)	No
3		Maganoor	Advi Satyaram	11KV	Mahabubnagar	07.20	11.00	03.40		11KV Phase to Phase Near Achampet (Vg)	No
4		Nawabpet	Kondapur	11KV	Mahabubnagar	18.30	19.05	00.35		11KV Conductor cut Near Dhayapanthula Pally (Vg)	No
5		Vepoor	Gundyal Feeder	11KV	Mahabubnagar	7:00	9:50	2:50		11KV Insulator Damage at Shekpally (Vg)	No
6		Vepoor	Chandraspally	11KV	Mahabubnagar	17.00	18.50	01.50		11KV Conductor cut Near Vepoor(Vg)	No
1	NLG	Gaddipally	Medaram	11KV	Huzurnagar	10:30	13:30	3:00	EL	Tree branch fall on 11KV line near Medaram village	No
2		Janpahad	Janpahad	11KV	Huzurnagar	03.00	07.00	04.00	EL	Tree branch fall on 11KV line	No
3		Ananthagiri	Ameenabad	11KV	Huzurnagar	02.25	05.30	03.05	EL	Insulator failure near Ameenabad village	No
4		Siripuram	Siripuram	11KV	Huzurnagar	03.00	05.00	02.00	EL	11 kv snapped near Siripuram village	No
5		Suryapet	Estate	11KV	Suryapet	08.00	10.20	02.20	EL	Jumper cut	No
6		Phanigiri	Phanigiri	11KV	Suryapet	09.20	12.00	02.40	EL	11 KV Line cut	No
7		Nandanam	Nagireddypally	11KV	Bhongir	23.00	02.00	03.00	EL	11KV Insulator failed near N.R Pally	No
8		Sharajipet	Tangutoor	11KV	Bhongir	02.00	06.00	04.00	EL	11KV Disk failed at Tangutoor(v)	No
9		Addagudur	Ch.Ramaram	11KV	Bhongir	23.00	02.00	03.00	EL	Tree Branches fallen on Line & snapped	No
10		B.Vellemla	B.Vellemla	11KV	Nalgonda	06.00	09.30	03.30	EL	11KV Line disc failed	No
11		Choutupal	Lingojigudem	11KV	Nalgonda	4:00	8:00	4:00	EL	11KV Insulator failed	No
1	MDK	Hathnoora	Nawabpet	11KV	Medak	11:00	14:00	3:00		11KV Insulator failed	No
1	RR N	Lanco Hills	Khajaguda	11KV	Gachibowli	0:07	1:04	0:57		Due To Heavy Rain And Wind. No Visible Fault. Feeder 'OK'	No
2		Nanakramguda	Church	11KV	Gachibowli	00.06	02.35	02.29		AB Cable End KIT Failure Near SC Basthi At Nanakramguda.	No
3		Gachibowli	Kothaguda	11KV	Gachibowli	17.00	18.25	01.25		Tree Branches Fallen On The 11KV Line At Reliance Opposite.	No
4		Gachibowli	Mezzequity	11KV	Gachibowli	17.05	18.40	01.35		11KV Mezzequity Feeder Load Added On 11KV Sriram Nagar Feeder.	No
5		Gachibowli	Kalajyothy	11KV	Gachibowli	20.30	21.30	01.00		11KV Pin Insulator Failed At HCU University Gate.	No
6		Balajinagar	Kukatpally	11KV	Kukatpally	00.00	02.00	02.00		11kv line Pininsulater failure near Hanumantemple at kukatpally	No
7		Vaddepally	Madhavramnagar	11KV	Kukatpally	11.30	12.40	01.10		Steel rod fallon the 11kv line near plot:91 at madhavram nagar	No
8		Medchal	IDA Kandlakoya	11KV	Medchal	17.20	19.55	02.35		Tree Fallen on the 11KV Line at 132KV Medchal SS Back side	No
9		Medicity	Munirabad	11KV	Medchal	18.55	20.20	01.25		11KV Pin Insulator failed at Munirabad Village	No
10		Uddamary	Keshavpur	11KV	Medchal	21.35	22.20	00.45		No Fault	No
11		Uddamary	Yellaguda	11KV	Medchal	21:50	23:50	2:00		AB switch insulator failed in SS	No
1	RR E	Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	17:26	18:06	0:40		11Kv Pin Insuletor failure at Jawahar Nagar Colony	No
2		Fruit Market	Chaitanyapuri	11KV	Saroonnagar	17.33	18.35	01.02	OL	11KV Conductor snapped	No
3		Singapur	RGK	11KV	Habsiguda	18.40	19.45	01.05		11kv line cut at NTPC wall back side	No

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		11		11		11			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014	2		2		2				
	Total	504	2929	2	14	2	14	2	14	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	3	6	3	6	3	6			
2	NLG	150	948	1	11	1	11	1	11			
3	MDK	87	828	1	1	1	1	1	1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	5	18	5	18	5	18	0	0	
	Grand Total	908	6149	7	32	7	32	7	32	0	0	