

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		3		3		3			
5	RR(N)	82	407		4		4		4			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		2		2		2			
2	NLG	150	948	1	6	1	6	1	6			
3	MDK	87	828		1		1		1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 29.06.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Madgulapally	Thipparthi	33KV	Nalgonda	08.00	11.30	03.30	E/L	33KV Pin insulators failed nearby Madgulapally(V)	Thipparthi	-

TSSPDCL - LMRC / Corporate office

Date: 29.06.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Burgupally	11KV	Jadcherla	08.25	12.45	04.20		11KV Insulator Failure Near Burgupally Tanda	-
2		Rajapur	Mallepally	11KV	Jadcherla	11.00	14.00	03.00		11KV Wire Cut Near Mallemmatanda	-
1	NLG	Sh.Gowraram	Gowraram	11KV	Suryapet	05.00	08.15	03.15	E/L	Jumper cut	-
2		Ananthagiri	Shantinagar	11KV	Huzurnagar	13.00	16.00	03.00	EL	insulator Failure near Shantinagar village	-
3		Gondiryala	Gondiryala 01	11KV	Huzurnagar	09.15	11.04	01.49	EL	AB switch fault near Gondiryala 01 village	-
4		Narkatpally IE	Vanipakala	11KV	Nalgonda	07.00	10.00	03.00	EL	11KV Disc failed	-
5		Gundrampally	Gundrampally	11KV	Nalgonda	04.35	07.00	02.25	EL	11KV jumper cut	-
6		Yennaram	Suraram	11KV	Nalgonda	09.45	11.30	01.45	EL	11KV line melting at SS-4	-
1	MDK	Gavvalapally	Madur	11KV	Medak	05.00	06.00	01.00		B/D Due to pin insulator failed	-
1	RR S	Mamidipally	AMP	11KV	CPT	11.25	15.30	04.05		CT PT problem at AMP company	-
2		Mallapur	al jabri Colony	11KV	CPT	09.03	12.26	03.23		Bird fallen on 11KV line AB switch at Aljabri Colony	-
3		MD Pally	Laxmiguda	11KV	RJNR	12.30	13.30	01.00		T/F AB switch sparking at Noorinagar	-
1	RR N	Mathrusri Nagar	Durgamatha Temple	11KV	GCB	11.15	12.45	01.30	BD	Tree branches fallen on the 11kv line at CBCID Colony	-
2		Gachibowli	Aparna	11KV	GCB	14.20	15.24	01.04	BD	11kv line snapped at biryani house, Nallagandala	-
3		Kandlakoya	Saigeetha Asramam	11KV	Medchal	00.30	02.40	02.10	BD	Tree Branch fallen on the 11KV Line at Prestiage Park Opposite	-
4		Ravalkole	Cheruvukatta	11KV	Medchal	09.45	12.45	03.00	BD	11KV Conductor Snapped at JK Seeds	-
1	RR E	NGRI	HMT nagar	11KV	Habsiguda	03.37	04.46	01.09		Coconut tree branches fallen on line at st no 11 HMT nagar	-
2		Keesara	Ankireddypally	11KV	Habsiguda	12.00	13.20	01.20		11kv line cut at Peddamma temple cherruvu	-
1	HYD N	Gymkhana	Tadbun Temple	11KV	V	09.20	10.35	01.15	EL,OL-Rph	No Visible Fault	-
1	HYD S	Malakpet	Noorkhan Bazar	11KV	VIII	04.50	06.45	01.55	All Indication	DTR fault at Govt.School	-