

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		2		2		2			
	Total	504	2929	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		3		3		3			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	3	0	3	0	3	0	0	
	Grand Total	908	6149	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.11.17

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mukundapuram	Mukundapuram	11KV	Huzurnagar	3:00	9:10	6:10	EL/OL	Tree branch fallen on 11KV line	No
2		Repala	Kalakova	11KV	Huzurnagar	02.30	09.20	06.50	EL	11KV Jumper cut near Kalakova village	No
3		Penphad	Macharam	11KV	Suryapet	14.15	16.20	02.05	EL	Jumper cut	No
1	RR N	Bachupally	Nizampet	11KV	Kukatpally	19:10	19:40	0:30	EL	11kv Disc failed at Govt. High School Bachupally	No
1	RR E	Taramathipet	Gowrelly	11KV	Ibrahimpattam	15:40	17:10	1:30	EL/OL	Tree branches fallen on the 11KV line at Taramathipet	
2		Aushapur	Aushapur	11KV	Habsiguda	15.30	16.30	01.00		Bird fallen on 11KV line near Arora College	No
1	HYD N	Jubilee Hills	H.P.Gas	11KV	Jubilee Hills	17.25	18.30	01.05	EL	Cable fault	Arranged B/F on 11KV P.I.E-UG feeder
1	HYD S	Panjasha	Gulzar House	11KV	Charminar	02.43	04.45	02.02	EL	Cable fault	Arranged B/F on 11KV Telephone Exg. feeder

