

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407	1	3	1	3	1	3			
6	RR(E)	38	360									
7	Hyd	186	1014		2		2		2			
	Total	504	2929	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		6		6		6			
3	MDK	87	828	1	7	1	7	1	7			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	13	1	13	1	13	0	0	
	Grand Total	908	6149	2	19	2	19	2	19	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Athmakur(S)	T.Penpahad	11KV	Suryapet	13.50	15.50	02.00	EL	Jumper cut	-
2		Pamangundla	Pittampally	11KV	Nalgonda	07.40	09.55	02.15	EL	11 KV line cutting	-
3		Narsingbatla	Chennugudam	11KV	Nalgonda	07.45	10.40	02.55	EL	11 KV Line insulator failed and jumper cutting	-
4		Nandanam	Anajipur	11KV	Bhongir	02.50	07.40	04.50	EL	11KV Line snapped at Balakrishna reddy Well	-
5		Alair	Ikkurthy	11KV	Bhongir	13.50	14.50	01.00	EL	Tree Branches Fallen On Line at Ikkurthy	-
6		M.T.Pally	Dataipally	11KV	Bhongir	16.45	18.00	01.15	EL	Dataipally Feeder CT Failed 1 Yad	-
1	MDK	Monoharabad	Kallakal AGL	11KV	Toopran	11.40	13.30	01.50		B/D Due to Insulator Failure	-
2		Togita	Kuchanpally	11KV	Medak	05.30	08.30	03.00		B/D Due to tree branches fallen on wires	-
3		Yenigandla	Yenigandla	11KV	Medak	02.20	09.40	07.20		B/D Due to Insulator Failure	-
4		Yenigandla	Rangampet	11KV	Medak	02.20	09.40	07.20		B/D Due to Insulator Failure	-
5		Yenigandla	Y. Mandapur	11KV	Medak	02.20	09.40	07.20		B/D Due to Insulator Failure	-
6		Rangampet	Rangampet	11KV	Medak	02.20	09.40	07.20		B/D Due to Insulator Failure	-
7		Rangampet	Paithra	11KV	Medak	02.20	09.40	07.20		B/D Due to Insulator Failure	-
1	RR S	Upparpally-II	Naiducolony	11KV	RJNR	13.10	14.35	01.25	B/D	Tree branches fallen on 11KV line at Naiducolony	-
1	RR N	J D M SS-II	N R S A	11KV	Jeedimetla	18.35	19.45	01.10	EL&OL	11kv AB Cable Endy Kit Failure Near V R K Engineering Phase_IV	-
2		Medchal	Navadurga	11KV	Medchal	19.30	20.25	00.55	BD	11KV Conductor snapped at Ida Medchal	-
3		Aliabad	Majeedpur	11KV	Medchal	19.15	20.30	01.15	BD	Breaker problem in SS (Backfeeding arranged from 11KV Bommarajpet Feeder)	-
1	HYD S	Chanchalguda	Islamiya	11KV	Asmangadh	11.45	13.00	01.15	EL,OL-Rph	Cable fault at Dabeerpura	-----
2	HYD N	N.I.M.S.	Telephone Exchange	11KV	Erragadda	16.15	17.30	01.15	EL	Incoming Cable fault	Arranged B/F on 11KV Saibaba Temple fdr

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Siddipet	Mettapaly	33KV	Siddipet	07.45	08.25	00.40		B/D Due to Jumper Cut	Mettapaly	-
1	RR N	132KV LGM Pet	33KV LGM Pet	33KV	Medchal	05.28	06.21	00.53		No Fault(Tripped on EL Indication)Backfeeding arranged from 33KV Ratnalayam out	33KV LGM Pet	-