

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014	1	2	1	2	1	2			
	Total	504	2929	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		7		7		7			
3	MDK	87	828	2	3	2	3	2	3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	10	2	10	2	10	0	0	
	Grand Total	908	6149	3	13	3	13	3	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Medak	NSF	33KV	Medak	02.25	07.20	04.55		B/d due to Tree fallen on the line near Pillikotal (V)	NSF	-
2		Gajwel	Pregnapur	33KV	Toopran	12.30	13.10	00.40		B/d due to Pin Insulator fail.	Pregnapur	-
1	HYD S	220KV Shivrampally	Miralam UG Cable	33KV	Malakpet	15.25	16.10	00.45	EL,OL	Cable fault	Miralam UG Cable	Loads transferred onto 33KV Miralam OH feeder

TSSPDCL - LMRC / Corporate office

Date: 09.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Eduloor	Naregudem	11KV	Nalgonda	10.00	14.20	04.20	E/L	11 KV Jumper Cut Under SS-22	-
2		Kattangur	Bollepally	11KV	Nalgonda	05.00	09.00	04.00	E/L	HT/LT Lines Melt Under SS-3	-
3		Nandanam	Anajipur	11KV	Bhongir	03.05	07.00	03.55	EL	DTR Lighting Erester Failed	-
4		Mothkur Rural	Anajipur	11KV	Bhongir	13.10	14.20	01.10	EL	Bird Fallen On Line at Dacharam	-
5		Keethavarigudem	Kothagudem	11KV	Huzurnagar	02.00	10.30	08.30	EL	11 kv line sanpped at Kothagudem village	-
6		Garidepally	Kalmalcheruvu	11KV	Huzurnagar	04.00	06.00	02.00	EL	11 kv line sanpped at Kalmalcheruvu village	-
7		Amararam	Srinivasapuram	11KV	Huzurnagar	00.45	07.30	06.45	EL	11 kv line snapped at Srinivasapuram village	-
1	MDK	Nangunoor	Siddannapet	11KV	Siddipet	09.10	11.00	01.50		B/D due to Jamper cut	-
2		Baddipadaga	Baddipadaga	11KV	Siddipet	09.00	12.30	03.30		B/D due to Tree branches fallen on the 11kv line	-
3		Irkode	Burugupally	11KV	Siddipet	08.30	12.30	04.00		B/D due to Insuletor fail	-
1	RR E	Kushaiguda	AS Rao Nagar	11KV	Sainikpuri	04.00	05.20	01.20		Tree branches fallen on 11Kv line at Mahesh Nagar Water Tank (LM Srinivas)	-
1	HYD N	Prashasan Nagar	Nandagiri Hills	11KV	X	13.58	15.08	01.10	EL,OL-Bph	Tree branches fallen on lines at Nandagiri Hills	-
1	HYD S	E.N.T	C.B.I	11KV	IX	02.20	03.40	01.20	All Indication	Limb failed at SS	Arranged B/F on 11KV Koti feeder