

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		5		5		5			
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		3		3		3			
2	NLG	150	948		9		9		9			
3	MDK	87	828	2		2		2				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	12	2	12	2	12	0	0	
	Grand Total	908	6149	2	18	2	18	2	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Bollaram	Meenakshi	33KV	Sangareddy	08.50	14.50	06.00		B/d due to Bus jumper cut	Bollaram	-
2		Jogipet	Chitkul	33KV	Jogipet	10.30	12.30	02.00		B/d due to Tree branches fallen on the line near Chintakunta (V).	Jogipet	-

TSSPDCL - LMRC / Corporate office

Date: 10.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Nacharam	11KV	Mahabubnagar	08.30	10.30	02.00		11KV Phase to Phase at Nacharam (Vi)	-
2		Kosgi	Vittalapur	11KV	Mahabubnagar	08.30	12.00	03.30		11KV Conductor cut at Gorlonibha (Vi)	-
3		Suraipally	Kudurumalla	11KV	Mahabubnagar	07.00	08.30	01.30		11KV Conductor cut at Kudurumalla (Vi)	-
1	NLG	Eduloor	Naregudem	11KV	Nalgonda	02.00	06.00	04.00	E/L	11 KV Insulator Failed	-
2		Velimnedu	Pitampally	11KV	Nalgonda	06.00	10.00	04.00	E/L	HT/LT Lines Melt Under SS-3 & 11Kv Line Insulator Failed	-
3		G.T Giri	Bakthalapuram	11KV	Suryapet	06.00	07.45	01.45	E/L	11Kv Jumper cut	-
4		Pamukunta	Jala	11KV	Bhongir	13.30	17.00	03.30	E/L	11KV Jumper snapped at Jala Outside	-
5		Mothkur	Anajipur	11KV	Bhongir	16.20	17.40	01.20	E/L	11KV Line snapped Near Mtkr	-
6		Puligilla	Kechupally	11KV	Bhongir	12.40	16.40	04.20	E/L	HT/LT	-
7		Mattampally	Allipuram	11KV	Huzurnagar	07.40	11.30	03.50	E/L	11Kv Jumperer cut near Allipuram (v)	-
8		Raghunadapalem	Raghunadapalem	11KV	Huzurnagar	03.40	07.40	04.00	E/L	DTR failure near Raghunadapalem (v)	-
9		Repala	V R Puram	11KV	Huzurnagar	13.30	17.30	04.00	E/L	11Kv Jumperer cut near V R Puram (v)	-
1	RR N	Mayurinagar	Bk Enclave	11KV	KKP	17.10	17.50	00.40	BD	T/F Brass patti Cut at Mayurinagar	-
2		Bowrampet	Bowrampet Village	11KV	JDM	03.40	04.50	01.10	BD	11kv Cable Failure at Ring Road	-
3		Chinthal	Surya Nagar	11KV	Medchal	07.10	07.50	00.40	BD	11KV Cable Touched with 11KV Line at Ram Reddy Nagar, Hanuman Temple	-
4		Bandamadaram	Rock Sand	11KV	Medchal	04.50	05.50	01.00	BD	11KV Pole damaged by Lorry at Srirangavaram Gate	-
5		Aliabad	LGM Pet	11KV	Medchal	14.00	15.25	01.25	BD	Bird fallen on the 11KV Line at Monsanto Company	-
1	HYD N	I.I.C.T	Deccan	11KV	Sec-Bad	00.30	01.42	01.12	EL	Street Light Pole fell down at Street No.14 (1No. DTR kept off)	-