

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948	1	4	1	4	1	4			
3	MDK	87	828	2	2	2	2	2	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>4</b>	<b>6</b>	<b>4</b>	<b>6</b>	<b>4</b>	<b>6</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>4</b>	<b>6</b>	<b>4</b>	<b>6</b>	<b>4</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 11.11.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	leeza	Venkatapuram	33KV	Gadwal	09.44	13.10	03.26	E/L&O/L	Insulator Replacement and tree cutting work near leeza	Venkatapuram	No
1	NLG	Ramannapet	Voligonda	33KV	Bhonagiri	8:46	13:26	4:40		33KV Pad clamp jumper snpped	Voligonda	No
1	MDK	Sadasivpet	Manjeera	33KV	Sangareddy	8:45	14:25	5:40		Tree branches fallen on the line	Manjeera	No
2		Manoharabad	Shivampet	33KV	Toopran	04.05	08.00	03.55		Tree branches fallen on the line	Shivampet	No

TSSPDCL - LMRC / Corporate office

Date: 11.11.17

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Urumadla	Elikatte	11KV	Nalgonda	08.05	10.26	02.21	EL	Jumper cut	No
2		G.Yedavally	G.Yedavally	11KV	Nalgonda	06.20	08.00	01.40	EL	Insulator failed	No
3		Thatipamula	Sri ramulu Thanda	11KV	Suryapet	11.30	14.00	02.30	EL	Jumper cut	No
4		Mamillagudam	Mothey	11KV	Huzurnagar	04.30	11.15	06.45	EL	11KV Line snaped	No
1	MDK	Rajpet	Thimmapur	11KV	Medak	09.00	10.53	01.53		Jumper cut	No
2		Reddy pally	Khajipet	11KV	Medak	15.05	16.55	01.50		Conductor snapped	No