

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948		3		3		3			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	3	1	3	1	3	0	0	
	Grand Total	908	6149	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kodur	Kodur	11KV	Suryapet	08.30	11.00	02.30	E/L	Jumper cut	-
2		Mellacheruvu	Revooru	11KV	Huzurnagar	15.00	16.05	01.05	EL	11Kv Jumper cut	-
3		Cherkupally	Baddapalem	11KV	Nalgonda	08.10	11.30	03.20	EL	11 KV Line Insulator Failed	-
1	RR N	Kistapur	Goshaiguda	11kv	Medchal	09.30	11.30	02.00		No Fault	-
2		Gowdavelly	Gowdavelly	11kv	Medchal	08.05	08.45	00.40		Bird fallen on the 11KV Line at Gowdavelly Village	-
1	RR E	Mohan nagar	Vijayapuri	11kv	SAROORNAGAR	23.39	01.01	01.22	EL	Lorry Dash to Tree, Tree Branch Fallen on 11kv line at Road No 2 Vijayapuri Colony	-
1	HYD S	Chanchalguda	Chowni	11kv	Asmangadh	06.35	08.00	01.25	EL	Snapped Conductor & Bird fault on Lines at Chowni Bus Stop	

TSSPDCL - LMRC / Corporate office

Date: 14.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Navadurga	33kv	Jadcherla	17.55	20.15	02.20	EL	Bird follen on the line and Pin bairding loose connecting problem.	Navadurga	-