

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		3		3		3			
6	RR(E)	38	360									
7	Hyd	186	1014	1	1	1	1	1	1			
	Total	504	2929	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		9		9		9			
3	MDK	87	828	1	2	1	2	1	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	11	1	11	1	11	0	0	
	Grand Total	908	6149	2	15	2	15	2	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 15.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Narsapur	Reddypally	33kv	Medak	16.50	18.35	01.45		B/D Due to tree branches fallen on the line	Reddypally	-
1	HYD C	132KV Imlibun	Jiyaguda	33kv	Mehdipatnam	12.50	13.10	00.20	EL,OL- RY&Bph	CT & Control pannel damaged at EHT and Cable damaged by GHMC at Puranapool	Jiyaguda	Loads transferred onto 220KV Shi.Pally SS vai 33KV Karwan UG

TSSPDCL - LMRC / Corporate office

Date: 15.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Aitipamula	Rasoolgudem	11KV	Nalgonda	08.00	09.50	01.50	EL	11 KV Line cut and Insulator Failed	-
2		Narketpally	Mandra	11KV	Nalgonda	11.00	13.10	02.10	EL	Tree fallen on line	-
3		Kattangur	Kalmera	11KV	Nalgonda	13.00	15.00	02.00	EL	Abswitch fault	-
4		Reddygudem	Kothagudem	11KV	Suryapet	11.37	14.19	02.42	EL	Insulator failed	-
5		Kondamadugu	Nemaragomula	11KV	Bhongir	07.00	08.30	01.30	EL	Tree Branches Fallen On Line	-
6		Kolanupaka ss	Aalir Agl	11KV	Bhongir	14.10	15.30	01.20	EL	AB Switch Problem	-
7		Alingapuram	Gundlapahad	11KV	Huzurnagar	07.05	09.55	02.00	EL	11 kv jumper cut at gundlapahad village	-
8		Repala	Repala	11KV	Huzurnagar	15.00	19.00	04.00	EL	11 KV Line snapped at Repala village	-
9		Ananthagiri	Shantinagar	11KV	Huzurnagar	19.00	20.15	01.15	EL	11 kv line snapped at shantinagar village	-
1	MDK	Narayanraopet	Narayanraopet	11KV	Siddipet	13.15	15.40	02.25		B/D Due to Jumper Cut	-
2		Ch Ghanpur	Wariguntham	11KV	Medak	10.33	11.25	00.52		B/D Due to Conductor Snapped	-
1	RR N	Dulapally	Kartekavanam	11KV	Medchal	10.32	12.20	01.48		Tree fallen on the 11KV Line at Forest Area	-
2		Athiwelly	Ravalkole Thanda	11KV	Medchal	12.20	13.40	01.20		Tree Fallen on 11KV Line at BHL Company	-
3		Medchal	Town Medchal	11KV	Medchal	15.25	17.21	01.56		Tree Fallen on 11KV Line at REVL backside	-

1	HYD S	Falaknuma	Chatrinaka	11KV		21.00	22.18	01.18	OL-Rph	Cable fault near Falaknuma SS	
---	-------	-----------	------------	------	--	-------	-------	-------	--------	-------------------------------	--