

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2		2		2				
2	NLG	150	948		10		10		10			
3	MDK	87	828	2	7	2	7	2	7			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	4	17	4	17	4	17	0	0	
	Grand Total	908	6149	4	17	4	17	4	17	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chedella	Mukundapuram	11kv	Suryapet	5:30	9:15	3:45	E/L	Jumper cut	-
2		Mukundapuram	Kalluru	11kv	Huzurnagar	7:47	9:10	1:23	E/L	11 kv line snapped at Penchekaldenne village	-
3		Kodad Town	Srirangapuram	11kv	Huzurnagar	7:00	8:45	1:45	E/L	11kv conductor snapped at Near Dorakunta village	
4		Nadigudem	Ratnavaram	11kv	Huzurnagar	14:00	15:45	1:45	E/L	11 kv line snapped at Ratnavaram village	
5		Siripuram	Siripuram	11kv	Huzurnagar	17:55	19:45	1:50	E/L	11 kv line snapped at Siripuram village	
6		Ch.Mamidi	Kompally	11kv	Nalgonda	5:00	8:30	3:30	E/L	11 KV Insulator Failed	
7		Kopple	Kopple	11kv	Nalgonda	9:00	12:42	3:42	E/L	11 KV Jumper Cut and Insulator Failed	-
8		Bollepally	Jampally	11kv	Bhongir	2:00	5:00	3:00	EL	HT/LT	-
9		Motakondur	Cholleru	11kv	Bhongir	7:00	10:50	3:50	EL	11Kv Jumper Snapped at Mabhoobpet	-
10		Paladugu	Panakabanda	11kv	Bhongir	12:55	15:10	2:15	EL	Bird Fallen On Line at Pankabanda	-
1	MDK	Medak	Komtur	11kv	Medak	08.44	11.02	02.18	EL	B/D due to jumper cut.	-
2		Reddypally	Reddy pally	11kv	Medak	00.10	09.45	09.35	EL	B/D due to conductor cut.	-
3		Nangunoor	Nagarajupally	11kv	Siddipet	05.10	05.50	00.40	EL	B/D due to jumper cut.	-
4		Mittapally	Yellupally	11kv	Siddipet	00.00	08.10	08.10	EL	B/D due to AB Swith fail	-
5		Pedda Chekode	Pedda Chekode	11kv	Siddipet	04.00	09.00	05.00	EL	B/D due to Tree branches fall on the 11KV line	-
6		Ragothampally	Ramakkapet	11kv	Siddipet	00.00	09.00	09.00	EL	B/D due to Tree branches fall on the 11KV line	-
7		Chittapur	Mothet	11kv	Siddipet	03.51	09.00	05.09	EL	B/D due to Tree branches fall on the 11KV line	-

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Nawabpet	33KV	Mahabubnagar	03.30	11.05	07.35	E/L&O/L	Disc Replacing at Railway Crossing near Laxmi nagar Colony	Nawabpet	-
2		Thirumalaipally	Willamkonda	33KV	Wanaparthi	17.30	17.50	00.20	E/L	Alternate Supply Arranged to 33KV Pabbair Feeder at 17:50 Supply Stud Ok	Willamkonda	-
1	MDK	Habsipur	Thimmapur	33KV	Siddipet	08.40	10.45	02.05		Tree branches fall on the 11KV line	Thimmapur	-
2		Habsipur	Pothareddypet	33KV	Siddipet	21.20	22.20	01.00		Insulater Failed at Chittapur	Pothareddypet	-