

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948		4		4		4			
3	MDK	87	828	1		1		1				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	5	1	5	1	5	0	0	
	Grand Total	908	6149	1	6	1	6	1	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Kothamolgara	11KV	Jadcherla	08.50	12.00	03.10		11Kv Jumper Cut Touched and The Cross arm Near Chinnakappeta Village	-
1	NLG	S V College	Kasarabadha	11KV	Suryapet	07.40	09.00	01.20	E/L	Jumper cut	-
2		Gaddipally	Kuthubshapuram	11KV	Huzurnagar	12.15	15.00	02.45	E/L	11 kv line snapped at Gaddipallyvillage	-
3		Y.Singaram	Magdum Nagar	11KV	Huzurnagar	05.30	08.30	03.00	E/L	11 Kv Conductor snapped at Magdum nagar village	-
4		Raghunathpoor	Raghunathpoor	11KV	BHONGIR	03.30	07.40	04.10	E/L	JUMPAR CUT AT RN POOR VILLAGE	-
1	RR S	NPA	Saibabanagar	11KV	RJNR	06.20	07.53	01.33	B/D	11KV Cable failed at Aramghar Railway track B/F Given on 11KV Babulreddy nagar	-

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Medak	B.B.Pur	33kv	Medak	15.45	16.30	00.45		B/D due to Jumper cut ITC Collage	B.B.Pur	-