

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		10		10		10			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014		8		8		8			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>22</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2		2		2				
2	NLG	150	948		5		5		5			
3	MDK	87	828	2	6	2	6	2	6			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>4</b>	<b>11</b>	<b>4</b>	<b>11</b>	<b>4</b>	<b>11</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>4</b>	<b>33</b>	<b>4</b>	<b>33</b>	<b>4</b>	<b>33</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 09.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Maldakal	33KV	Gadwal	01.30	09.30	08.00	E/L	Jumpers Opened at Mallemdoddy.Budidapadu,Bijwar	Maldakal	-
2		Gadwal	Maldakal	33KV	Gadwal	10.55	13.25	02.30	E/L	Insulator Replacement Near Bijwaram SS and Insulator Replacement Near Sangala (vi)	Maldakal	-
1	MDK	Narayankhed	Poosalpad	33KV	Jogipet	17.50	20.15	02.25		B/D due to heavy rain	Poosalpad	-
2		Chegunta	yeldurthi	33KV	Toopran	20.00	21.25	01.25		B/D due to heavy rain	yeldurthi	-

## TSSPDCL - LMRC / Corporate office

Date: 09.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Velugupally	Velugupally	11KV	Suryapet	06.20	09.30	03.10		Disk failure	-
2		Thimmannagude	Narsimhapur	11KV	Nalgonda	06.00	10.00	04.00		Disk failure	-
3		Kattangur	Dugnevelly	11KV	Nalgonda	06.00	10.00	04.00		11 KV Line Jumper cut	-
4		Pedaveedu	Krishna thanda	11KV	Huzurnagar	06.50	09.50	03.00		11 KV Line Jumper cut	-
5		Thimmareddy gudem	Ganapavaram	11KV	Huzurnagar	09.00	11.00	02.00		11 KV Disk failure	-
1	MDK	Mustabad	Gadicherlapally	11KV	Siddipet	07.35	11.50	04.15		B/d due to Insuletor fail.	-
2		Mustabad	Division Office	11KV	Siddipet	05.35	07.35	02.00		B/D due to Tree branches fallen on the 11KV line.	-
3		Kondamrajpally	Gattlamalyal	11KV	Siddipet	07.30	11.00	03.30		B/d due to Disk fail	-
4		Pothareddypet	Rameshwarpally	11KV	Siddipet	03.03	08.30	05.27		B/D due to Jumper cut.	-
5		Cheryal	Kandi	11KV	Sangareddy	00.00	08.00	08.00		B/D Due to jumper cut near Mamidipally Vg	-
6		SRD T I	Nansabgadda	11KV	Sangareddy	13.30	14.52	01.22		B/D Due to 11KV conductor snaped at Hanuan Nagar	-
1	RR S	Puppalaguda	Puppalaguda	11KV	Rajendranagar	22.27	02.07	B/D		Tree branches fallen on 11KV Line at Prathibha School	-
1	RR N	Nizampet	Rajadhani School	11KV	Kukatpally	19.34	20.54	01.20	E/L	11kv Pininsulator failure at Nallpochamma Temple	-
2		J T P L	K S R	11KV	Kukatpally	18.25	20.15	01.50	E/L	11kv Pininsulator failure at Road 7 K S R	-
3		Vijayanagar	Sapathagiri	11KV	Kukatpally	19.35	21.43	02.08	E/L	11kv AB cable Failure At Venkateshwaranagar	-
4		Vijayanagar	A S RajuNagar	11KV	Kukatpally	19.40	20.30	00.50	E/L	11kv Disk Failed At M N R Collage	-
5		J D M SS-I	ShapuraNagar	11KV	Jeedimetla	11.37	13.00	01.23	EL	11Kv JumperCut Touched To channel At shapur Nagar Main Road	-
6		Subash Nagar	Suchitra	11KV	Medchal	19.05	20.40	01.35		11KV AB Cable Failed at Green Park(Suchitra feeder Load added to ramraj Nagar)	-
7		Subash Nagar	Padma Nagar	11KV	Medchal	21.45	22.45	01.00		11KV Pin Insualtor failed at MN Reddy Nagar	-
8		Medicity	Munirabad	11KV	Medchal	21.30	23.40	02.10		11KV Pin Insulator failed at Munirabad Village	-
9		Athiwelly	Somaram	11KV	Medchal	22.20	01.00	02.40		11kv Disk Failed at Somaram Village	-
10		Athiwelly	SPIC	11KV	Medchal	22.20	00.50	02.30		NO visuval fault	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Mallapur	Standed tiles	11KV	Habsiguda	23.30	00.50	01.20		11kv line snapped near Andhara bank & jumper cut at manikchand	-
2		Mallapur2	Ashok nagar	11KV	Habsiguda	05.25	07.00	01.35		11kv pin insulator fail at neheru nagar mahila mandal	-
3		TARAMATHIPET	INDUSTRIAL	11KV	IBRAHIMPATNAM	18.30	21.15	02.45	EL	11KV V KHASARAM BINDU 11KV LINE TOUCHUDU AT SEDDUPALLY	-
1	HYD N	Road No.12	Kanaka Durga	11KV	X	03.55	05.05	01.10	EL,OL-Rph	Cable sparking near SS	-
2		Madhapur	HUDA	11KV	X	20.10	22.15	02.05	EL	DTR fault at NIFT College	-
3		Madhapur	Vaisnavi Residency	11KV	X	20.15	23.10	02.55	OL-R&Bph	No Visible Fault (Kept off 3No. DTR's)	-
4		Film Nagar	Padmalaya Studio	11KV	X	21.30	22.35	01.05	EL	Tree branches fallen on lines at Road No.8	-
1	HYD C	Bathkammkunta	Ahobilmutt	11KV	II	18.20	19.55	01.35	EL	Post type Insulator flash over at Legend Apts	-
2		Langer House	Pensionpura	11KV	VII	21.15	23.23	02.08	EL	Pin Insulator flash over at HUDA Park	-
3		Asif Nagar	Mehdipatnam Cable	11KV	VII	22.35	00.37	02.02	EL	Faulty loads of 11KV Mehdipatnam OH fdr	-
4		Hyderguda	Boggula Kunta	11KV	I	22.45	23.55	01.10	EL	Disc Insulator flash over & Tree branches fallen on lines at Meena Bazar	-