

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Koukuntla	33KV	Mahabubnagar	01.30	15.00	13.30	E/L	Pin Insulator Changed near Baswaipally and 2Nos Pin Insulator Changed near Dokur Village	Koukuntla	Alternate Supply Arranged to 33KV Devarkadra at 5:10
2		Kodangal	Peddanandigama	33KV	Mahabubnagar	00.30	16.55	16.25	E/L	3No Pin Insulator Replacement near Regadmailaram Village	Peddanandigama	No
3		Kodangal	Hamsanpally	33KV	Mahabubnagar	00.30	13.05	12.35	E/L	3No Pin Insulator Replacement near Regadmailaram Village	Hamsanpally	Hamsanpally Feeder Loads Tag on to 33KV Peddakothapally Feeder
4		Wanaparthy	Solipur	33KV	Wanaparthy	0:40	13:37	12:57	E/L	Damaged Jumper Removed and Replacement near 220KV Wanaparthy SS	Solipur	No
5		Thirmalaipally	Veltoor	33KV	Wanaparthy	0:35	3:15	2:40	E/L	3No,Pin Insulater Replacement near Palem (vi)	Veltoor	Alternet Supply Arraged to 33KV Wanaparthy Feeder at 3:15Hrs Supply Stud Ok
6		Kalwakurthy	Jaknalapally	33KV	Jadcherla	0:00	3:12	3:12	E/L	33KV Jumpers Open at DC Pole near Urkonda Petrol Pump	Jaknalapally	No
7		Achampet	Uppunuthala	33KV	Nagarkurnool	00.30	05.40	05.10	E/L	Tree Fallen on the near Uppunuthala Village	Uppunuthala	No
1	MDK	Gummadidala	Jinnaram	33KV	Jogipet	0:10	9:15	9:05		Tree branches fallen on the line	Jinnaram	No
2		Jogipet	Laxmisager	33KV	Jogipet	02.15	10.25	08.10		Insulator failed	Laxmisager	No
3		Narayankhed	Poosalpad	33KV	Jogipet	09.50	15.50	06.00		Tree branches fallen on the line	Poosalpad	No
4		Habsipur	Kajipur	33KV	Siddipet	06.32	08.17	01.45		Jumper cut	Kajipur	No
5		Habsipur	Kajipur	33KV	Siddipet	11.25	12.45	01.20		Tree branches fallen on the line and Insulator failure	Kajipur	No
6		Siddipet	Komaticheruvu	33KV	Siddipet	15:35	18:10	2:35		Tree branches fallen on the line	Komaticheruvu	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marikal	Appampally	11KV	Mahabubnagar	06.00	11.30	05.30		11KV Conductor cut at Appampally (Vi)	No
2		Marikal	Theelair	11KV	Mahabubnagar	06.00	11.30	05.30		11KV Conductor cut at Theelair (Vi)	No
3		Dhanwada	Kamsanpally	11KV	Mahabubnagar	06.00	08.00	02.00		11KV Disc failure at Dhanwada SS (vi)	No
4		Sanginonipally	Ankilla	11KV	Mahabubnagar	14:30	16:10	1:40		11KV Insulator failure at Ankilla (vi)	No
5		Nawabpet	Kondapur	11KV	Jadcherla	6:00	7:15	1:15		Disk failed near Kondapur	No
6		Rajapur	Mallepally	11KV	Jadcherla	9:00	13:30	4:30		Disk fail near Rajapur	No
7		Midjil	Boinpally	11KV	Jadcherla	08.00	10.30	02.30		wire cut near Boinpally	No
1	NLG	Gaddipally	Kuthubushapur	11KV	Huzurnagar	9:30	11:50	2:20	EL	Due to 11KV Insulator failed	No
2		Y.Singam	Magdum Nagar	11KV	Huzurnagar	00.00	06.00	06.00	EL	Jumper cut	No
3		Koppole(K)	Kopolu	11KV	Nalgonda	09.00	12.00	03.00	EL	Insulator failed	No
4		Maryala	Mailaram	11KV	Bhongiri	06.00	11.00	05.00	EL	Male & female contacts failed at SS	No
5		Rajapet	Renikunta	11KV	Bhongiri	5:00	9:30	4:30	EL	11KV Insulator failed	No
1	MDK	Shivampet	Shivampet Rural	11KV	Toopran	10:00	12:00	2:00		11KV Conductor snapped near Nayudu form	No
2		Sikindlapur	Bijilipur	11KV	Toopran	05.50	11.50	06.00		11KV Conductor snapped near Bijilipur Chowrastha	No
3		Kothapet	Lingojiguda	11KV	Toopran	05.30	13.30	08.00		11KV Poles damaged Near Parama swamy Gudi	No
4		Danthanpally	Hasthalpur	11KV	Toopran	22.07	07.00	08.43		Insulator fail Near Peddapur	No
5		Narsapur	Narayanpur	11KV	Medak	00.00	12.00	12.00		Jumper cut	No
6		Reddypally	Reddypally	11KV	Medak	00.00	11.30	11.30		Jumper cut	No
7		Lingapur	Lingapur	11KV	Medak	00.00	06.00	06.00		Insulator failed	No
8		Lingapur	Thujalpur	11KV	Medak	00.00	06.00	06.00		Insulator failed	No
9		Moosapet	Rusthumpet	11KV	Medak	02.15	08.10	05.55		Jumper cut	No
10		Venktraopet	Thunki	11KV	Medak	00.00	12.00	12.00		Tree branches fallen on the line	No
11		Chittkul	Chitkul	11KV	Medak	11.00	13.00	02.00		Tree branches fallen on the line	No
12		Kanchanpally	Lingampally	11KV	Medak	05.00	11.14	06.14		Tree branches fallen on the line	No
13		Ch Ghanpur	Wariguntham	11KV	Medak	00.00	11.20	11.20		Conductor snapped	No
14		NSF	Rampur	11KV	Medak	07.37	11.21	03.44		Insulator failed	No
15		Gadipeddapur	Muslapur	11KV	Medak	00.00	08.50	08.50		Conductor snapped	No
16		Tekmal	Akasapur	11KV	Medak	00.00	06.00	06.00		Insulator failed	No
17		Tekmal	Tamploor	11KV	Medak	00.00	09.00	09.00		Jumper cut	No
18		Shankarampet	Gotimukkula	11KV	Medak	00.00	09.00	09.00		Conductor snapped	No
19		Cherial	Kandi	11KV	Sangareddy	10:35	18:20	7:45		Insulator failed	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR S	Kattedan-II	Jalpally	11KV	Rajendranagar	1:48	4:27	2:39		11KV Post type Insulator failed at Universal company	No
2		Kokapet	Kokapet	11KV	Ibrahimbagh	01.27	03.55	02.28		11KV Insulator failed at Goshala	No
1	RR N	JTPL	PNR Hills	11KV	Kukatpally	2:55	4:20	1:25		11KV Line pin insulater failed at Road No:22, Nachram ,Sridatta	No
2		madinaguda	HMT	11KV	Kukatpally	02.50	03.50	01.00		11KV Line disc failed at Krushi Nagar	No
3		Nuthankal	Oystar	11KV	Medchal	03.30	06.14	02.44		Tree fallen on the 11KV line Lingapur Thada	No
4		Nuthankal	Bharathi	11KV	Medchal	01.42	02.55	01.13		11KV Pole damaged and replaced at Pochamma Temple	No
5		Nuthankal	Nuthankal	11KV	Medchal	0:00	5:00	5:00		11KV Pole damaged and replaced at Pochamma Temple, Nuthankal	No
1	HYD N	Lalaguda	Railway Work Shop	11KV	Sec'bad	10.28	13.35	03.07	EL	Insulator flashed over at Railway Work Shop	No
1	HYD C	Golconda	Darga Cable	11KV	Mehdipatnam	00.26	02.30	02.04	EL	HT Service AB Cable fault at Darga	No

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		2		2		2			
5	RR(N)	82	407		5		5		5			
6	RR(E)	38	360									
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	7	7	7	7	7	7			
2	NLG	150	948		5		5		5			
3	MDK	87	828	6	19	6	19	6	19			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>13</b>	<b>31</b>	<b>13</b>	<b>31</b>	<b>13</b>	<b>31</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>13</b>	<b>40</b>	<b>13</b>	<b>40</b>	<b>13</b>	<b>40</b>	<b>0</b>	<b>0</b>	