

## TSSPDCL - LMRC / Corporate office

Date: 13.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kondapur	Hanmanpally	11KV	Mahabubnagar	10.50	13.00	02.10		11KV Conductor cut at Rakashigutta thanda (Vi)	-
2		Janampet	Moosapet	11KV	Jadcherla	06.00	11.00	05.00		Jumper cut near Nizalapur	-
3		Teegalapally	Kakarlpadu	11KV	Jadcherla	10.00	12.20	02.20		11kv Wire cut near Kakarlpadu	-
1	NLG	Nuthankal	Chilpakuntla	11KV	Suryapet	06.00	08.40	02.40	EL	Jumper cut	-
2		Dilshicherla	Somaram	11KV	Huzurnagar	05.30	08.30	03.00	EL	Due to 11Kv jumpercutted	-
3		Gaddipally	Medaram	11KV	Huzurnagar	05.00	07.00	02.00	EL	11 KV Disk failure	-
4		Peddathanda	Vedagiri	11KV	Bhongir	06.00	08.30	02.30	EL	11KV Insulator failed	-
5		Peddathanda	Peddathanda	11KV	Bhongir	04.30	08.30	04.00	EL	11KV 2 Insulator failed	-
6		Akaram	Vallala	11KV	Nalgonda	07.20	09.50	02.30	EL	11 KV Line Jumper Cutting	-
7		Ch.Gouraram	Gurajala	11KV	Nalgonda	07.30	10.15	02.45	EL	11 KV Insulator Failed Under SS-2	-
8		Ch.Gouraram	Sh.Gouraram	11KV	Nalgonda	07.00	09.40	02.40	EL	11 KV Insulator Failed Under SS-2	-
1	MDK	Athmakur	yellaram	11KV	Sangareddy	05.30	09.30	04.00		B/d due to Tree fallain on 11kv line at chandapur vg	-
1	RR S	Ibrahimbagh	Military-I	11KV	RJNR	19.18	20.21	01.03	B/D	Kites stick fallen on 11KV Line at Ibrahimbagh	-
1	HYD S	E.N.T	Jambagh	11KV	Begumbazar	06.10	07.55	01.45	All Indication	Jumper cut at Poosala Basti	----
1	HYD C	Fever Hospital	Kachiguda Railway Station	11KV	Azamabad	16.29	21.19	04.50	EL,OL	Cable fault at Raghavendra Hotel	Arranged B/F on 11KV BKP Bus Depot fdr

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Bollaram	Bollaram-II	33kv	Sangareddy	16.35	21.50	05.15		B/d due to Conductor snapped near SS	Bollaram-II	-
2		Manoharabad	Shivampet	33kv	Toopran	21.45	22.25	00.40		Altrenate supply given Sabashpally Feeder to Shivampet Feeder	Shivampet	-
3		Narsapur	Reddipally	33kv	Medak	21.45	22.50	01.05		B/d due to Tree branches fallain on the line near Sitharampur Village.	Reddipally	-

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		3		3		3			
2	NLG	150	948		8		8		8			
3	MDK	87	828	3	1	3	1	3	1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>0</b>	<b>0</b>	