

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	2	17	2	17	2	17			
6	RR(E)	38	360									
7	Hyd	186	1014		4		4		4			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>2</b>	<b>21</b>	<b>2</b>	<b>21</b>	<b>2</b>	<b>21</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	3	1	1	1	1	1	2		2 Nos-33KV Still
2	NLG	150	948		8		8		8			
3	MDK	87	828	4	6	4	6	4	6			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>7</b>	<b>15</b>	<b>5</b>	<b>15</b>	<b>5</b>	<b>15</b>	<b>2</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>9</b>	<b>36</b>	<b>7</b>	<b>36</b>	<b>7</b>	<b>36</b>	<b>2</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 15.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Damargidda	33KV	Mahabubnagar	08.12	11.15	03.03	E/L&O/L	Pin Binding Failed near Ayyawarpally	Damargidda	-
2		Kalwakurthy	Vanoor	33KV	Jadcherla	17.30	00.00	06.30	E/L&O/L	Not Rectified Due to Conductor Snapped & Insulator & Disc Replacement Due to Heavy Lightning	Vanoor	-
3		Kalwakurthy	Jajala	33KV	Jadcherla	16.55	00.00	07.05	E/L&O/L	Not Rectified Due to Lightning Storke & 10No Insulators Damaged	Jajala	-
1	MDK	Bollaram	ITC	33KV	Sangareddy	14.50	17.50	03.00		B/D due to Heavy rain & Tree branch fallen on line	ITC	-
2		Manoharabad	Shivampet	33KV	Toopran	15.05	18.35	03.30		B/D due to After petrolling no fault found	Shivampet	-
3		Kowdipally	CH Ghanpur	33KV	Medak	16.35	19.35	03.00		B/D due to Insulator failed	CH Ghanpur	-
4		Gajwel	BV Pur	33KV	Siddipet	10.05	13.00	02.55		B/D due to Pin Insulator failed	BV Pur	-
1	RR N	132KV Chinthal	33KV Subash Nagar	33KV	Medchal	14.49	17.32	02.43	BD	33KV Pin Insulator Failed at near by 33KV Subash Nagar SS	33KV Subash Nagar	-
2		132KV LGM Pet	33KV LGM Pet	33KV	Medchal	14.50	16.44	01.54	BD	2Nos 33KV Pin Insulators Failed at Prokarna company and Surya Vamshi Main Gate	33KV LGM Pet	-

TSSPDCL - LMRC / Corporate office

Date: 15.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Konded	Chinna Adirala	11KV	Jadcherla	13.00	15.00	02.00		11 KV Insulator Failure Near Thupragadda Tanda Side.	-
1	NLG	Dirsincherla	Somaram	11KV	Huzurnagar	02.00	06.00	04.00	E/L	DTR failure in Somaram village	-
2		Dondapadu	Kakatiya	11KV	Huzurnagar	04.30	08.30	04.00	E/L	11Kv Jumper cutted Kakatiya village	-
3		Janpahad	Ravipahad	11KV	Huzurnagar	06.30	08.30	02.00	E/L	11Kv Insulator failure Ravipahad village	-
4		Kodur	Kommala	11KV	Suryapet	06.00	08.15	02.15	E/L	Jumper cut	-
5		Nemmani	Merlakunta	11KV	Nalgonda	09.45	13.45	04.00	E/L	11KV jumper cut	-
6		Pamanagundla	Pittampally	11KV	Nalgonda	03.30	07.30	04.00	E/L	11KV line melting at village	-
7		Katangur	Katangur	11KV	Nalgonda	11.30	12.40	01.10	E/L	11KV Insulators failed	-
8		Akaram	Akaram	11KV	Nalgonda	10.40	13.40	03.00	E/L	11KV Insulators failed	-
1	MDK	ISMAILKANPET	ERDHANIOOR	11KV	SANGAREDDY	07.10	17.05	09.55		B/D DUE TO TREE FALLEN ON LINE	-
2		MALKAPUR	KOTHLAPUR	11KV	SANGAREDDY	16.00	17.30	01.30		B/D DUE TO TREE FALLEN ON LINE	-
3		FASALWADI	FASALWADI	11KV	SANGAREDDY	02.36	09.34	06.58		B/D DUE TO DISC FAILED	-
4		CHERYAL	JULKAL	11KV	SANGAREDDY	00.00	07.20	07.20		B/D DUE TO TREE FALLEN ON LINE	-
5		CHERYAL	KANDI	11KV	SANGAREDDY	08.00	09.00	01.00		B/D DUE TO RAIN FALL	-
6		CHERYAL	DVR	11KV	SANGAREDDY	18.10	18.55	00.45		B/D DUE TO LT JUMPER CUT	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Mayuri nagar	K T R Colony	11KV	KKP	15.30	16.30	01.00	BD	Cloth fallen On the 11kv Line At narayana Reddy colony	-
2		Nizampet	Rajadhani school	11KV	KKP	15.30	16.05	00.35	BD	11Kv post Of Insultor failed at Sy.no.191 rajadhani school	-
3		J D M SS-I	Meashawari	11KV	JDM	04.05	06.10	02.05	BD	11kv Ab Cable failed At Ram Chandra rubber	-
4		J D M SS-I	Phase-I	11KV	JDM	14.50	16.50	02.00	BD	11kv Line Petroling No Fout	-
5		J D M SS-I	Apiic	11KV	JDM	14.50	16.50	02.00	BD	Tree fallen on the 11kv Line At Phase-I	-
6		J D M SS-I	Triumala	11KV	JDM	15.25	16.25	01.00	BD	Due To Heavy Rain	-
7		J D M SS-3	Pipe line	11KV	JDM	15.02	16.52	01.50	BD	11kv In coming Jumper Cut &out Going jumperCut In sub-Station & 11kv Line Petroling No fout	-
8		Bowrampet	Bowrampet Village	11KV	JDM	14.59	16.02	01.03	BD	T/F HG Fuse Insultot failure & tree Fallen on the 11lv Line At mallenna Temple	-
9		Subash Nagar	Jairam nagar	11KV	Medchal	16.15	17.10	00.55	BD	Tree Fallen on 11KV Line at Gayathri Nagar	-
10		Kompally	Dholari Dhani	11KV	Medchal	15.30	17.05	01.35	BD	11KV Brass patti cut at Horlicks company	-
11		Kompally	Kompally	11KV	Medchal	15.30	16.45	01.15	BD	Tree Fallen on 11KV Line at Royal Park and Kompally Bridge	-
12		Kompally	Petbasheerbagh	11KV	Medchal	15.30	16.50	01.20	BD	Tree Fallen on 11KV Line at Balaji Hospital Backside	-
13		Kompally	NCL	11KV	Medchal	15.30	16.27	00.57	BD	Tree Fallen on 11KV Line at Cloud-9 Apartment	-
14		Subash Nagar	Jeedimetla	11KV	Medchal	16.10	16.50	00.40	BD	Tree Fallen on 11KV Line at Deewan Dhaba,Jeedimetla	-
15		Aliabad	HBL	11KV	Medchal	14.25	17.00	02.35	BD	No fault	-
16		Devarayamjal	Kottapet	11KV	Medchal	14.45	17.00	02.15	BD	Tree Fallen on 11KV Line at Radhika Garden,Devarayamjal	-
17		GP Pally	APIIC	11KV	Medchal	19.10	21.10	02.00	BD	132KV Line Fallen on 11KV Line at APIIC backside ( 11KV Jumper opened at Arunadaya Company )	-
1	HYD N	IDPL	Wonderplat	11KV	VI	15.30	16.35	01.05		Pin insulator flash over	-
1	HYD S	Miralam	Amzadullabad	11KV	III	15.02	16.50	01.48		RMA Fault	-
1	HYD C	Bathkamakunta	Ramalayam	11KV	II	14.10	16.10	02.00		Tree branches fallen on line	-
2		Zamisthanpur	Balajinagar	11KV	II	13.28	14.32	01.04		DTR Fault	-