

TSSPDCL - LMRC / Corporate office

Date: 24.10.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Jharasangam	33KV	Zaheerabad	6:30	7:50	1:20		Jumper cut	Jharasangam	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thungathurthy	Bandaramaram	11KV	Thungathurthy	10:15	12:20	2:05	EL	Jumper cut	No
2		Mukundapuram	Kalluru	11KV	Huzurnagar	11.15	15.40	04.25	EL	Tree branch fallen on the 11KV line near Kalluru village	No
3		Yennaram	Kunkuduplem	11KV	Bhongir	07.00	10.00	03.00	EL	11 KV Jumper cut	No
4		Azeempet	Kanchanapally	11KV	Bhongir	02.35	04.45	02.10	EL	Bird fallen on the 11 KV line near kanchanpally	No
5		Nandanam	Thukkapur	11KV	Bhongir	09.30	11.30	02.00	EL	11 KV insulator failed near thukkapur	No
6		Barinobanda	Baironibanda	11KV	Nalgonda	09.20	11.20	02.00	E/L	11 KV Line disc failed	No
7		Akaram	Vaddipamula	11KV	Nalgonda	07.50	11.30	03.40	E/L	11 KV Jumper cut	No
8		Narketpally	Narketpally T	11KV	Nalgonda	9:20	11:30	2:10	E/L	11 KV Insulator failed	No
1	RR S	NIRD	Grayhounds	11KV	Rajendranagar	16:02	17:24	1:22		11KV Disc failed at DOR Agriculture university	No
1	RR N	J D M SS-5	Rudralaya	11KV	Jeedimetla	10:10	11:20	1:10	EL	Tree fallen on the 11KV line at vijayal Company Phase-III	No

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		8		8		8			
3	MDK	87	828	1		1		1				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	8	1	8	1	8	0	0	
	Grand Total	908	6149	1	10	1	10	1	10	0	0	