

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		5		5		5			
6	RR(E)	38	360									
7	Hyd	186	1014		5		5		5			
	Total	504	2929	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948		5		5		5			
3	MDK	87	828	3	4	3	4	3	4			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	10	3	10	3	10	0	0	
	Grand Total	908	6149	3	21	3	21	3	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gajwel	Ahmedipur	33KV	Toopran	01.00	08.20	07.20		B/D Due to Jumper Cut	Ahmedipur	-
2		Husnabad	Katkoor	33KV	Siddipet	17.35	18.25	00.50		B/D Due Insulator Faliure	Katkoor	-
3		Gummadidala	GPSS-2	33KV	Sangareddy	09.40	14.05	04.25		B/D Due to Conductor Snapped	GPSS-2	-

TSSPDCL - LMRC / Corporate office

Date: 30.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Khanapur	11KV	Jadcherla	12.28	14.48	02.20		11 Kv Phase To Phase Near shamagadda Tanda Side	-
1	NLG	Indl Estate	Vijaya colony	11KV	Suryapet	07.20	08.36	01.16	EL	Jumper cut	-
2		Mukundapuram	Kallur	11KV	Huzurnagar	05.40	09.10	03.30	EL	11 KV Insulator failure	-
3		Arlagaddagudem	Chinna Suraram	11KV	Nalgonda	05.30	07.30	02.00	EL	11KV jumper cut	-
4		Wangapally	Wangapally Indus	11KV	Bhongir	15.00	17.00	02.00	EL	HT/LT	-
5		Palleria	Siddapuram	11KV	Bhongir	12.10	14.00	01.50	EL	11Kv Insulator failed Near Siddapur	-
1	MDK	Ponnal	Bakricheyal AGL	11KV	Siddipet	08.00	11.00	03.00		B/D Due to Jumper Cut	-
2		Thogita	Kuchanpally	11KV	Medak	03.35	05.15	01.40		B/D Due to Jumper Cut	-
3		Thogita	Kuchanpally	11KV	Medak	07.05	09.05	02.00		B/D Due to Jumper Cut	-
4		Alladurg	Venkatraopet	11KV	Medak	07.00	09.30	02.30		B/D Due Insulator Faliure	-
1	RR S	NPA	NPA(NPA)	11KV	RJNR	13.11	15.20	02.09	B/D	Tree branches Fallen on 11kv Line at NPA Side A.	-
1	RR N	Mayurinagar	Cable	11KV	Kukatpally	10.15	10.45	00.30	EL&OL	A Kite fall on the 11KV line near Ramalayam at Ramnaresh Nagar	-
2		Bachupally	Nizampet	11KV	Kukatpally	19.10	19.40	00.30	EL	11kv Disk Failure At GOVT High School Bachupally	-
3		HMT	Quthbullapur	11KV	Medchal	12.10	12.45	00.35		Tree branch fallen on the 11KV Line at Manjieera Apartment	-
4		GP Pally	GP Pally	11KV	Medchal	07.30	09.05	01.35		11KV Jumper Cut & Replaced at Ayodhya Chowrasta	-
5		Thurkapally	Yadaram	11KV	Medchal	12.30	13.15	00.45		11KV Pin Insulator failed at Kallu Compond, Yadaram	-
1	HYD S	Miralam	Mustafa Nagar	11KV	III	10.05	11.30	01.25	EL,OL	Insulator flash over at Mustafa Nagar	-----
2		C.R.P.F	Balapur	11KV	III	12.30	14.05	01.35	EL	Disc Insulator flash over at Link Line AB Switch, Balapur	-----
3		Ch' Baradari	Bilal Nagar	11KV	III	13.10	14.55	01.45	EL,OL	No Visible fault	Arranged B/F on 11KV Sattarbagh fdr
4		C.R.P.F	Balapur	11KV	III	14.12	15.30	01.18	EL	Forein material fallen on lines at Balapur	-----
5		Kanchanbagh	Riyasath Nagar	11KV	III	16.35	20.05	03.30	EL,OL-Bph	Cable fault	Arranged B/F on 11KV Omer Colony feeder