



S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	K.V.Pet	Town	11KV	Jadcherla	13.05	15.20	02.15		Tree fallen on the 11KV line near new bus stand side	No
2		K.V.Pet	Bandamedipally	11KV	Jadcherla	13.00	17.00	04.00		11 KV Insulator failed near J P Nagar	No
3		Balanagar	Nerellapally	11KV	Jadcherla	12.40	14.00	01.20		11 KV Jumper cut Near Udithyal Road	No
1	NLG	S.V Collage	G.Hotel	11KV	Suryapet	11:20	14:00	2:40	E/L	Bird fallen on the line	No
2		Durajpally	Vallabhapuram	11KV	Suryapet	14.40	17.00	02.20	E/L	Jumper cut at DTR	No
3		Alair	Ikkurthy	11KV	Bhongir	10.15	13.15	03.00	E/L	Tree branches fallen on the line	No
4		Shivannuguda	R.R.Pally	11KV	Devarakonda	04.30	07.30	03.00	E/L	11kv Jumper cut	No
1	MDK	Kondamrajpally	Kondamrajpally	11KV	Siddipet	1:00	6:10	6:10		Tree branches fallen on the line	No
1	RR N	Jeedimetla-I	Sudharshan Drugs	11KV	Jeedimetla	6:30	7:30	1:00		11kv line AB Cable Endkit Failure at Sai Kantta, Phase-I	No
2		Jeedimetla-I	Phase-II	11KV	Jeedimetla	02.10	03.25	01.15		Line Petroling No Visuble Falt	No
3		Devarayamjal	Pothaipally	11KV	Medchal	05.20	07.20	02.00		11KV UG Cable Earthling failed at Devaramjal Village	No
1	RR E	Narapally	Pratapsingaram	11KV	Keesara	17:25	18:35	1:10		Insulator failed at Koremulla Village	No

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		3		3		3			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		3		3		3			
2	NLG	150	948		4		4		4			
3	MDK	87	828		1		1		1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>0</b>	