

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Alawalpad	33KV	Gadwal	04.50	13.50	09.00	E/L	Pin insulator failed at Gadwal old SS & 33KV Alwalpadd SS	Alawalpad	No
2		Gadwal	Dharoor	33KV	Gadwal	04.50	13.50	09.00	E/L	Pin insulator failed near Gadwal out side	Dharoor	No
3		Gadwal	Nandinne	33KV	Gadwal	04.55	09.05	04.10	E/L	Due to Heavy Wind & Rain and AB Switch open at Dharoor	Nandinne	No
4		leeza	TT Doddi	33KV	Gadwal	07.35	10.20	02.45	E/L	Pin insulator failed at CT Pad	TT Doddi	No
5		leeza	TT Doddi	33KV	Gadwal	10:40	17:05	6:25	E/L	Pin insulators failed at CT Pad SS & CT Pad Village and Tuppathrala Village	TT Doddi	No
6		leeza	Madelabanda	33KV	Gadwal	05.30	08.20	02.50	E/L	Pin insulator failed at Madelabanda SS	Madelabanda	No
1	NLG	Ramannapet	Aroor	33KV	Bhongir	8:40	12:16	3:36	EL	Lighting Erester Failed 132 KV Ramannapet SS	Aroor	No
2		Bibinagar	B.ramaram	33KV	Bhongir	08.55	12.00	03.05	EL	33KV Jumper snapped at 132kv Bibinagar ss	B.ramaram	No
3		Kanagal	Pagidimarri	33KV	Nalgonda	09.40	13.15	03.35	EL	33 KV Line Insulator Failed	Pagidimarri	No
4		Nalgonda	Rayanguda	33KV	Nalgonda	10.20	12.25	02.05	EL	33 KV Line Insulator Failed	Rayanguda	No
5		Aitipamula	Arlagaddagudem	33KV	Nalgonda	04.00	08.00	04.00	EL	33 KV Line Insulator Failed	Arlagaddagudem	No
6		Narketpally	Eduloor	33KV	Nalgonda	06.15	10.15	04.00	EL	Tree Fallen on 33 KV Line	Eduloor	No
7		Mattampally	NCL	33KV	Huzurnagar	04.00	08.45	04.45	EL	Tree Fallen on 33 KV Line	NCL	No
8		Dirincherla	Garidepally	33KV	Huzurnagar	6:15	8:53	2:38	EL	33Kv Insulator failure	Garidepally	No
1	RR S	132kv RC Puram	33kv Shankar pally	33KV	Rajendranagar	11:20	15:20	4:00	BD	Tree branches fallen on 33kv Line at 400kv SS Shankarpally	Shankar pally	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Peddarevelly	11KV	Jadcherla	10.30	13.40	03.10		11KV Jumper cut near Jammigaddi DTR side	No
1	NLG	Motakondur	Motakondur	11KV	Bhongir	8:00	12:20	4:20	EL	Tree fallen on line	No
2		Motakondur	Cholluru	11KV	Bhongir	08.00	12.00	04.00	EL	Jumper cut mahipet	No
3		Y.gutta	Wangapally	11KV	Bhongir	08.00	10.30	02.30	EL	11KV Line snapped at Wangapally	No
4		Y.gutta	Mallapur	11KV	Bhongir	08.00	11.35	03.35	EL	11KV Line snapped at mllapur	No
5		Ida ss	Bommaipally	11KV	Bhongir	08.45	12.30	03.45	EL	11KV Line snapped at Bommaipally	No
6		Kudakuda	llapuram	11KV	Suryapet	03.45	07.20	03.35	E/L	Line Cut	No
7		Reddygudem	Kothagudem	11KV	Suryapet	12.50	15.10	02.20	E/L	Disk Failed	No
8		Gundepuri	Gundepuri	11KV	Suryapet	09.00	11.30	02.30	E/L	Tree Branch fallen	No
9		Palem	Ogodu	11KV	Nalgonda	06.55	11.20	04.25	E/L	11 KV Line Cut Under SS-1	No
10		Pamanagundla	lsmailpally	11KV	Nalgonda	12.25	14.42	02.17	E/L	11 KV Jumper Cut	No
11		Pole Center	Nalgnda Town	11KV	Nalgonda	06.30	08.30	02.00	E/L	11 KV Line Melting	No
12		Aregudem	Peddakaparthu	11KV	Nalgonda	09.30	14.00	04.30	E/L	LT Line Jumper Cut Under SS-1	No
13		Eduloor	Eduloor Town	11KV	Nalgonda	10.00	12.00	02.00	E/L	11 KV Insulator Failed Under SS-3	No
14		Kethepally	Gudiwada	11KV	Nalgonda	08.05	11.45	03.40	E/L	11 KV Line Disc Failure	No
15		Ghanpuram	Kondapuram	11KV	Devarakonda	08.00	11.00	03.00	E/L	11kv jumper cut	No
16		Chinthapally	Vinjumoor	11KV	Devarakonda	06.00	10.00	04.00	E/L	11kv insulator failure	No
17		Haliya	Haliya Town	11KV	Miryalaguda	05.30	07.00	01.30	E/L	11KV Disc failed	No
18		Ramadugu	Thimmapuram	11KV	Miryalaguda	05.15	08.40	03.25	E/L	11KV Insulator failed	No
19		Velmagudem	Peddagudem	11KV	Miryalaguda	05.30	06.50	01.20	E/L	Tree fallen on line	No
20		Pulicharla	Vootlapally	11KV	Miryalaguda	04.20	05.30	01.10	E/L	11KV Insulator failed	No
21		Tripuraram	Mukundapuram	11KV	Miryalaguda	05.50	07.10	01.20	E/L	Tree fallen on line	No
22		Palakeedu	Bothalapalem	11KV	Huzurnagar	09.20	13.00	03.40	EL	11 Disk failed at Bothalapalem village	No
23		Amaravaram	Lingagiri	11KV	Huzurnagar	11.00	14.00	03.00	EL/OL	11 kv line snapped at Lingagiri village	No
24		Nadigudem	Ratnavaram	11KV	Huzurnagar	08.25	10.40	02.15	EL	Tree branch fallen on 11kv line at Ramapuram village	No
25		Repala	Repala	11KV	Huzurnagar	9:30	11:30	2:00	EL	11 KV Insulator failed at Repala village	No
1	MDK	Rampur	Palamakula	11KV	Siddipet	10:00	18:00	8:00		B/d due to Disc failed	No
2		Medipally	Medipally	11KV	Siddipet	16.00	16.40	00.40		B/d due to AB Switch problem	No
3		Medipally	Ananthasagar	11KV	Siddipet	13.00	17.00	04.00		B/d due to Disc failed	No
4		Mallaram	Sikindlapur	11KV	Siddipet	13.42	15.26	01.44		B/d due to Tree brach fall on the 11 kv line	No
5		Chellapur	Rajakkapet	11KV	Siddipet	11.00	15.20	04.20		B/d due to Earthing Problem	No
6		Kothapally	Annaram	11KV	Medak	09.30	12.00	02.30		B/D due to insulator failed	No
7		Chippalthurthy	Jakkapally	11KV	Medak	14:00	15:25	1:25		B/D due to insulator failed	No
1	RR S	Ibrahimbagh	Military-II	11KV	RJNR	10:00	12:20	2:20		no visible fault Due to Heavy rain	No
2		Shamshabad	Shamshabad	11KV	RJNR	10.15	11.40	01.25		11kv Line AB switch Sparking at Manikyamma Colony	No
3		Shamshabad	Dharmasai	11KV	RJNR	10.15	13.00	02.45		Tree branches Fallen on 11kv line at kapu garden shamshabad	No
4		Shamshabad	Om Jai Bhavani	11KV	RJNR	10.20	11.25	01.05		Tree branches Fallen on 11kv line at ootpally village shamshabad	No
5		Gaganpahad	Gaganpahad	11KV	RJNR	12:22	13.28	01.06		Tree branches Fallen on 11kv line at siddhartha plastics industries	No
6		Sidduloor	Pulapally	11KV	VKB	12:20	13:30	1:10		11 kv Jumper snapped & touched to the crosaram at pulmamidi vg water supply	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Athiweily	SPIC	11KV	Medchal	6:50	9:25	2:35		11KV Pin Insulator failed at Gubba Company	No
2		Kompally	Kompally	11KV	Medchal	18.16	19.16	01.00		11KV Cable failed at Balreddy Apartment, Kompally	No
3		JDM-I	Sudharshan Durgs	11KV	Jeedimetla	11.45	12.45	01.00		11kv AB-Cable End-Kit failed at Phase-I Line	No
4		KPHB	Shathavahana Nagar	11KV	Kukatpally	14.20	15.10	00.50		11KV UG cable failed near ICICI bank, Backfeeding on KPHB feeder	No
1	RR E	Moula-Ali	HMT	11KV	Sainikpuri	12:32	14:02	1:30		Tree fallen on 11KV line at Eveready Company	No
2		Bandlaguda	Wambay Colony	11KV	Saroor Nagar	09.43	10.48	01.05	OL	Bird fallen on 11KV line at Srinivas Nagar	No
3		Thattiannaram	Thattiannaram	11KV	Saroor Nagar	09.48	11.29	01.41	EL	Tree branches fallen on 11KV line at Thattiannaram	No
4		Auto Nagar	Siris	11KV	Saroor Nagar	09.40	11.20	01.40	EL	Tree branches fallen on 11KV line at Chinthlagutta	No
5		AUTONAGAR	LB NAGAR	11KV	Saroor Nagar	09.45	11.20	01.35	EL	Tree branches fallen on 11KV line at Chinthlagutta	No
6		Ghatkesar	Kondapur	11KV	Keesara	10.00	12.30	02.30		Tree branches fallen on 11KV line near HPCL Company	No
7		Singapur	RGK	11KV	Keesara	16.05	18.05	02.00		11KV Disc failed near Power Grid backside	No
8		Abdullapurmet	Industrial	11KV	Saroor Nagar	09.25	10.45	01.15	OL	Tree Branches fallen on 11KV line at Kawadipally	No
9		Abdullapurmet	Batasingaram	11KV	Saroor Nagar	11.45	13.45	02.00	EL	11KV Disc Failed at Kothagudem	No
10		RFC	Umarkhan Guda	11KV	Saroor Nagar	16.00	17.54	01.54	EL	11KV Disc Failed at Grdicheruv	No
11		Thorrur	Munnunner	11KV	Saroor Nagar	11.42	14.10	02.28	OL	Tree Branches fallen on 11KV line at Munnunner	No
12		Turkamzal	Kamagudem	11KV	Saroor Nagar	11.00	13.00	02.00	EL	Tree Branches fallen on 11KV line at Kamagudem	No
13		Turkamzal	Turkamzal	11KV	Saroor Nagar	11.00	13.00	02.00	EL	HT/LT Line Cut at Turkamzal	No
14		Turkamzal	Manneguda	11KV	Saroor Nagar	11.00	12.00	01.00	EL	Tree Branches fallen on 11KV line at Manneguda	No
15		Turkamzal	Nadargool	11KV	Saroor Nagar	12.00	14.30	02.30	EL	Tree Branches fallen on 11KV line at Nadargool	No
16		Mangalpally	Mangalpally-2	11KV	Saroor Nagar	17.30	19.30	02.00	EL	11KV Disc Failed at Mangalpally	No
17		Mangalpally	MP Patelguda	11KV	Saroor Nagar	09.40	11.40	02.00	OL	Tree Branches fallen on 11KV line at Kogarakalan	No
18		Bandaravirala	Industrial	11KV	Saroor Nagar	9:00	10:58	1:58	OL	Tree Branches fallen on 11KV line at Bandaravirala	No
1	HYD N	Yousufguda	Gayatri Hills	11KV	Banjara Hills	05.00	07.40	02.40	EL,OL-Bph	AB Cable damaged at CRPF Qrts	Arranged B/F on 11KV Hylam Colony fdr
1	HYD S	Attapur	HUDA Colony	11KV	Charminar	10.30	11.35	01.05	EL,OL	HT Line snapped at Shivalayam	No
2		C.R.P.F.	Keshavgiri	11KV	Charminar	13:05	14:55	1:50	EL	Tree branches fallen on lines at BSNL Office	No
1	HYD C	Fever Hospital	BKP Bus Depot	11KV	Azamabad	10.05	11.48	01.43	EL,OL-Rph	DTR Fault at Kachiguda	No

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		4		4		4			
6	RR(E)	38	360		18		18		18			
7	Hyd	186	1014		4		4		4			
	Total	504	2929	0	27	0	27	0	27	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	6	1	6	1	6	1			
2	NLG	150	948	8	25	8	25	8	25			
3	MDK	87	828		7		7		7			
4	RR(S)	31	338	1	5	1	5	1	5			
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	15	38	15	38	15	38	0	0	
	Grand Total	908	6149	15	65	15	65	15	65	0	0	