

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		6		6		6			
3	MDK	87	828	8	2	8	2	8	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	8	8	8	8	8	8	0	0	
	Grand Total	908	6149	8	11	8	11	8	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.09.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Bollaram	Bollaram-II	33KV	Sangareddy	09.15	12.20	03.05		B/d due to Jumper cut	Bollaram-II	-
2		Pashamailaram	Inox	33KV	Sangareddy	10.50	11.50	01.00		B/D due to Conductor fallen on the Tower	Inox	-
3		Gummadidala	GPSS-II	33KV	Sangareddy	12.32	16.30	03.58		B/d due to Jumper cut near SS	GPSS-II	-
4		Pedda Shankarampet	Burugupally	33KV	Medak	12.15	14.00	01.45		B/D due to Tree branches fallen on the line near Shankarampet Village.	Burugupally	-
5		Medak	Shankarampet	33KV	Medak	19.30	21.25	01.55		B/d due to Jumper cut near Railway track.	Shankarampet	-
6		Narsapur	Kothapet	33KV	Medak	01.47	09.30	07.43		B/D due to Jumper cut near Lingapur Village.	Kothapet	-
7		Chegutna	Yeldurthi	33KV	Toopran	01.40	07.30	05.50		B/d due to Jumper cut near Polampally Village.	Yeldurthi	-
8		Thunki Bollaram	Markook	33KV	Siddipet	08.41	10.30	01.49		B/d due to Tree branches fallen on the line.	Markook	-

TSSPDCL - LMRC / Corporate office

Date: 11.09.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Penpahad	Macharam	11KV	Suryapet	10.30	11.44	01.14	EL	Jumper cut	-
2		Gondiryala	Chimiryala	11KV	Huzurnagar	05.20	07.30	02.10	EL	Due 100Kva DTR failure near Chimiryala village	-
3		G.Malkapuram	Thammaram	11KV	Huzurnagar	16.30	18.20	01.50	EL	Due to Jumper cutted near Thammaram village	-
4		Thimmannagude	Telankantigudem	11KV	Nalgonda	10.45	13.45	03.00	EL	Jumper Cut	-
5		Sharajipet ss	Tangutoor	11KV	Bhongir	15.30	17.10	01.40	EL	11KV Jumper snapped at Tangutoor	-
6		Ramannapet	Janmapally	11KV	Bhongir	11.46	15.00	03.14	EL	Tree Branches Fallen On Line	-
1	MDK	Dharmajipet	Dharmajipet	11KV	Siddipet	13.00	15.00	02.00		B/D due to Tree branche fall on the 11 Kv line at Dharmajipet Village	-
2		Rudram	Mallupally	11KV	Siddipet	10.20	12.00	01.40		B/d due to 11kv jumper cut at Mallupally Village	-
1	RR N	Suraram	Sri Ram Nagar	11KV	Jeedimetla	13.15	14.05	00.50	BD	Tree Branches Fallen On The 11kv Line At Sri Ram Nagar	-
2		Kandlakoya	Saigeetha Asramam	11KV	Medchal	14.20	15.20	01.00	BD	Tree Branch fallen on the 11KV Line at Kandlakoya Chowrasta	-
1	HYD C	Nampally	Red Hills	11KV	VII	03.02	04.30	01.28	All Indication	DTR fault at Rainbow Hotel & Jumper cut at Nisha Hospital	-