

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Mahabubnagar	02.50	14.40	11.50	E/L	L/C taken by AE/OP/Maganoor for 2Nos Insulator Replacement near Indupur Village and 2Nos Insulator Replacement near Mothinagar Village and Tree Cutting near Kosgi at Gudeballore	Makthal	-
2		Amarchintha	Amarchintha	33KV	Mahabubnagar	01.36	06.45	05.09	E/L	PTR Fuse Failure Replacement at 33KV Amarchintha SS	Amarchintha	-
3		Gadwal	Dharoor	33KV	Gadwal	04.25	10.20	05.55	E/L	Insulator Replasment near Gudendoddi Village	Gadwal	-
4		Gadwal	Nandinne	33KV	Gadwal	04.20	10.20	06.00	E/L	Insulator Replacement near Immnuni pally Village	Gadwal	-
5		Alampur	Alampur	33KV	Gadwal	01.06	03.44	02.38	E/L	AB Switch Open at Burdipad Village	Alampur	-
1	MDK	Kandi	HFC-II	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
2		Kandi	Signode	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
3		Kandi	Aradanafoods	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
4		Kandi	IIT	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
5		Kandi	ACE Tyres	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
6		Kandi	Exel Rubber	33KV	Sangareddy	21.25	24.00	02.35		B/D due to Continue	Kandi	-
7		Jogipet	Laxmisagar	33KV	Jogipet	21.05	24.00	02.55		B/D due to Continue	Jogipet	-
8		Kowdipally	Ch. Ganapur	33KV	Medak	22.10	00.20	02.10	B/D due to Tree branches fallen on the line near Variguntham Tanda	B/D due to Tree branches fallen on the line near Variguntham Tanda	Kowdipally	-
1	RR S	132Kv Puttapahad	Chowdapur	33KV	Vikarabad	03.50	04.50	01.00		33kv Disc failed at Ramapur village side	132Kv Puttapahad	-

TSSPDCL - LMRC / Corporate office

Date: 15.09.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pedda Kadmoor	Pedda Kadmoor	11KV	Mahabubnagar	10.00	14.50	04.50		11KV Phase to Phase at Kalwall (Vi)	-
2		Devarkadra	Gudibanda	11KV	Mahabubnagar	05.40	11.00	05.20		11KV Insulator Damage at Menugonipally (vi)	-
3		Mustipally	Mustipally	11KV	Mahabubnagar	01.00	07.30	06.30		11KV Insulator Failure at Mustipally (vi)	-
4		Kotakonda	Bandagonda	11KV	Mahabubnagar	06.15	13.10	06.55		11KV Conductor cut at Ganimonibandthanda (Vi)	-
5		Bijwar	Bijwar	11KV	Mahabubnagar	04.20	09.30	05.10		11KV Disk failure at Pathapally (vi)	-
6		ChinnaJatram	Anthwar	11KV	Mahabubnagar	09.50	12.40	02.50		11KV Conductor cut at Aasolonipally (Vi)	-
7		Avancha	Buddasamudram	11KV	Jadcherla	14.00	16.00	02.00		11Kv Jumper Cut Near Ammapally (Vi).	-
1	NLG	Dirsincherla	Somaram	11KV	Huzurnagar	01.10	07.00	05.50	EL	Due to 11Kv Jumper cut near Somaram village	-
2		Janpahad	Janpahad	11KV	Huzurnagar	14.11	17.45	03.34	EL	Due 11kv line cutted near Vajinepally village	-
3		Repala	V R Puram	11KV	Huzurnagar	09.15	13.50	04.35	EL	Due DTR Failure near V R Puram village	-
4		Kodad	Komarabanda Agl	11KV	Huzurnagar	09.50	12.10	02.20	EL	Due DTR Failure near Komarabanda Agl village	-
5		Pamanagundla	Pittampally	11KV	Nalgonda	10.25	11.40	01.15	E/L	11 KV Jumper Cutting	-
6		Palem	Ogodu	11KV	Nalgonda	09.20	11.00	01.40	E/L	11 KV Jumper Cutting	-
7		Gurrampodu	Thenapally	11KV	Devarakonda	08.00	11.00	03.00	E/L	11 KV Jumper Cutting	-
8		Gurrampodu	Chepur	11KV	Devarakonda	07.00	10.30	03.30	O/L	Insulator Failed	-
1	MDK	Gummadidala	Belremidi	11KV	Sangareddy	11.45	13.00	01.15		B/D due to AB switch Problem	-
1	RR S	CBIT	Movie Towers	11KV	Ibrahimbagh	05.15	06.10	00.55		No visible fault found	-
1	RR N	J D M Ss-I	Su-Drugs	11KV	Jeedimetla	05.30	07.09	01.39	EL&oL	11kv Pin Insultor Failure At U M A Industri Phase-I	-
2		J D M Ss-I	NiTco	11KV	Jeedimetla	15.17	17.17	02.00	EL	11kv Jumper Cut Touched on channel At Sai Kanta	-
3		GP Pally	GP Pally	11KV	Medchal	08.10	10.10	02.00		Bird fallen on the 11KV Line at GP Pally	-
4		Kandlakoya	Saigeetha Asramam	11KV	Medchal	05.30	06.30	01.00		Tree fallen on the 11KV Line at Indian Petrol Pump	-
5		Madinaguda	C B R	11KV	Kukatpally	05.30	06.55	01.25	EL	11kv Pin Insultor Failure At Deepathi srinagar	-
1	RR E	Moula-Ali	Meerpet	11KV	Sainikpuri	11.09	12.19	01.10		11Kv Disk Insulator failed at Thirumal Nagar (LM Venkatesh)	-
2		NADERGAL	SAPATHAGIRI COLONY	11KV	IBRAHIMPATNAM	05.30	06.30	01.00	EL	11KV LINE CUT AT KOHEDA	-
1	HYD N	Prashanth Nagar	Sony Complex	11KV	Bowenpally	04.00	06.30	02.30	All Indication	Conductor snapped at Water Tank	-
1	HYD S	Malakpet	Plant Protection	11KV	Asmangadh	22.50	00.12	01.22	EL,OL-Yph	Disc Insulator flash over at Housing Board	-

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201	1	1	1	1	1	1			
5	RR(N)	82	407		5		5		5			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		2		2		2			
	Total	504	2929	1	10	1	10	1	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	5	7	5	7	5	7			
2	NLG	150	948		8		8		8			
3	MDK	87	828	8	1	8	1	8	1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	13	16	13	16	13	16	0	0	
	Grand Total	908	6149	14	26	14	26	14	26	0	0	