

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		2		2		2			
5	RR(N)	82	407		3		3		3			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014		4		4		4			
	Total	504	2929	0	12	0	12	0	12	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	4	1	4	1	4	1			
2	NLG	150	948		1		1		1			
3	MDK	87	828		4		4		4			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	4	6	4	6	4	6	0	0	
	Grand Total	908	6149	4	18	4	18	4	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.09.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Kothur	33KV	Mahabubnagar	00.15	01.05	00.50		No Visible Fault was found	Kothur	AB Switch open at Bomraspet
2		Mahabubnagar	Nawabpet	33KV	Mahabubnagar	21.30	21.36	00.06	E/L&O/L	Opening Isolator at Boyapally Stood OK	Nawabpet	-
3		Wanaparthy	Solipur	33KV	Wanaparthy	13.23	20.58	07.35	E/L	Insulator Failed at Almayapally	Solipur	Jumper Removing at Mamidimada Cut Point at 17:35Hrs. Kamaloddi poor Jumper Removing at Cut Point at 18:24. Jumper Closing at Mamidimada Cut Point at 19:02. Near Nagaiah Land Cut Point Jumpers Opened Supply is Properly at 19:36.
4		leeza	Venkatapuram	33KV	Gadwal	00.25	08.05	07.40	E/L	Pin Insulator Failed near leeza	Venkatapuram	-

TSSPDCL - LMRC / Corporate office

Date: 30.09.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Karvena	11KV	Jadcherla	06.00	08.50	02.50		11 KV Insulator failure Near Kotha Molgara (V)	-
1	NLG	Thatipamula	Sriram thanda	11KV	Suryapet	06.30	08.00	01.30	EL	Tree branch fallen	-
1	MDK	Gavvalapally	S. Kondapur	11KV	Medak	00.00	10.05	10.05		B/D due to 11Kv line cut	-
2		Narsapur	Narayanpur	11KV	Medak	21.40	08.30	11.10		B/D due to Insulator Failed	-
3		Chippalthurthy	Chippalthurthy	11KV	Medak	00.00	04.30	04.30		B/D due to Tree fallan on line	-
4		Kanchanpally	Kanchanpally	11KV	Medak	06.30	07.50	01.20		B/D due to 11Kv Conductor Snapped.	-
1	RR S	Kattedan-II	Murali hotel	11KV	RJNR	02.10	04.10	02.00	B/D	11KV Insulator failed at Murali hotel opp	-
2		Indira Gandhi Society	Indirashivashakti	11KV	RJNR	07.10	09.30	02.20	B/D	CTBT Fail at maheswari Dalmill	-
1	RR N	Madinaguda	JPN Nagar	11KV	Kukatpally	09.03	09.50	00.47	EL	11kv line AB Cable Failure at Srichaithanya Ladeis Callage ,Bachupally	-
2		Mayurinagar	DivyaShakthi	11KV	Kukatpally	05.02	09.30	04.28	EL	Rat Fallon The Brekar At DivyaShakthi Delikate Brekar at Sub-Station Beside	-
3		Aliabad	HBL	11KV	Medchal	11.05	12.58	01.53	EL	11KV Disc failed at Aliabad	-
1	RR E	singapur	Singapur	11KV	Keesara	06.20	08.30	02.10		11KV pin insulator fail at gas plant singapur town ship	-
2		singapur	Annojiguda	11KV	Keesara	06.30	08.55	02.25		11KV pin insulator fail at out ringroad	-
3		Nagaram	Bandlaguda	11KV	Keesara	08.58	09.30	00.32		insutor fail at Bharath rathna school	-
1	HYD N	Gunrock	Surya Enclave	11KV	VI	12.15	13.25	01.10	EL,OL-Rph	Pin Insulator flash over at Surya Bhagavan Temple	-
2		Marredpally	Addagutta	11KV	V	14.25	15.55	01.30	All Indication	AB Cable fault at Wadder Basti	-
3		Chilkaiguda	P.R Nagar	11KV	V	16.48	18.17	01.29	EL,OL-Rph	No Visible Fault	-
1	HYD S	Santosh Nagar	Dry Land Agriculture	11KV	VIII	15.40	17.50	02.10	EL	Disc Insulator flash over at Azad Functional Hall	-