

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550	3	7	3	7	3	7			
6	RR(E)	168	403		15		15		15			
7	Hyd	194	1044		34		34		34			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>56</b>	<b>3</b>	<b>56</b>	<b>3</b>	<b>56</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5		5		4		1		1 no.33kv still
2	NLG	144	988	18	4	18	4	5	4	13		13 no.s 33kv still
3	MDK	107	933	5	7	5	7	5	7			
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>28</b>	<b>11</b>	<b>28</b>	<b>11</b>	<b>14</b>	<b>11</b>	<b>14</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>31</b>	<b>67</b>	<b>31</b>	<b>67</b>	<b>17</b>	<b>67</b>	<b>14</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 01.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mukundapuram	Dacharam	11kv	Huzurnagar	18.00	20.00	02.00	E/L	11 kv line snapped at Dachram village	-
2		Turkapally	M.Gouraram	11kv	Nalgonda	08.30	10.40	02.10	E/L	11KV jumper cut	-
3		Arlagaddagudem	N.R.Gudem	11kv	Nalgonda	15.00	17.05	02.05	E/L	11KV jumper cut	-
4		Chandupatla	Chandupatla	11kv	Bhongir	18.40	20.30	01.50	E/L	11KV jumper cut	-
1	MDK	Medak	Ausulapally	11kv	Medak	03.35	06.04	02.29		BD due to Jumper cut	-
2		Medak	Komtur	11kv	Medak	03.56	06.05	02.09		BD due to Insulatoe failed	-
3		Thogita	Kuchanpally	11kv	Medak	07.46	11.15	03.29		BD due to Insulatoe failed	-
4		Narsapur	Narayanpur	11kv	Medak	17.00	18.35	01.35		BD due to Jumper cut	-
5		Narsapur	Reddypally	11kv	Medak	17.00	19.00	02.00		BD due to Jumper cut	-
6		SANGAREDDY-I	COLLECTORATE	11kv	Sangareddy	16.15	17.35	01.20		B/D DUE TO TREE FALLEN ON LINE	-
7		AROOR	INDL	11kv	Sangareddy	13.15	14.15	01.00		B/D DUE TO TREE FALLEN ON LINE	-
1	RR N	Aleap	Madhuranagar	11kv	Kukatpally	02.20	04.15	01.55	BD	Construction Sticks Fallon the 11kv line at Incoies X Road	-
2		Nizampet	Bandari-Lay-Out	11kv	Kukatpally	04.20	05.30	01.10	BD	Construction Sticks Fallon the 11kv line at Road:1, Bandari-Lay-out	-
3		HMT	Venkanna Hills	11kv	Medchal	05.55	06.45	00.50	BD	11KV Pin Insulator Failed at Venkatesh Nagar	-
4		Gowdavelly	IDA	11kv	Medchal	04.40	05.30	00.50	BD	Tree fallen on the 11KV Line at Saketh Venture	-
5		Kandlakoya	Saigeetha Ashramam	11kv	Medchal	00.20	01.10	00.50	BD	11KV Disc failed at Saigeetha Asramam	-
6		Shameerpet	Thumkunta	11kv	Medchal	17.45	18.40	00.55	BD	Tree Fallen on the 11KV Line at Pallavi School, Thumkunta	-
7		Shameerpet	Anthaipally	11kv	Medchal	20.20	21.50	01.30	BD	No Fault	-
1		Cherelapally-IV	Sun Rice	11kv	RR East	03.20	03.20	04.20		Tree fallen on 11Kv line at near Sun Rice Compony (AE/OP)	-
2		Moula-Ali	Jawhar Nagar	11kv	RR East	16.19	16.19	17.00		11Kv Pin Insuletor failure at Jawahar Nagar (ADE/AS Rao Nagar)	-
3		Vinayak Nagar	Devi Nagar	11kv	RR East	17.30	17.30	18.20		Copper Patti cut at near Cheruvu Katta DTR (AE/OP)	-
4		Polytechnic	Sri Nagar Colony	11kv	Habsiguda	16.30	17.39	01.09		100KVA DTR Brass patti cut at Sri Nagar Colony due to heavy rain and gale	-
5		Polytechnic	Madhura Nagar	11kv	Habsiguda	16.35	17.30	00.55		Tree branches fallen on 11kv line AB Switch at Madhura Nagar due to Heavy rain and gale	-

## TSSPDCL - LMRC / Corporate office

Date: 01.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
6	RR E	Polytechnic	Srinivasa Puram	11kv	Habsiguda	16.28	18.40	02.12		Tree fallen on 11KV Line and line cut at Srinivasa Puram due to heavy rain and gale	-	
7		Ramanthapur	Venkat Reddy Nagar	11kv	Habsiguda	15.57	18.55	02.58		Tree fallen on 11KV Line at PS Colony	-	
8		Mallapur-2	Narsimha Nagar	11kv	Habsiguda	16.05	16.45	00.40		11KV Disc failed near MS Biryani and 11KV Pin Insulator failed near Sri Vidyanikethan School	-	
9		IICT	CCMB	11kv	Habsiguda	18.20	19.10	00.50		11KV AB Switch Insulator failed near Sai Durga Garden	-	
10		CRPF	Chennapur	11kv	Habsiguda	17.20	18.40	01.20		Tree branches fallen on 11KV line at Arundathi Nagar	-	
11		Cherlapally	Rampally	11kv	Habsiguda	17.00	20.30	03.30		11Kv Insulator failed near Ravi Engg	-	
12		Peerzathiguda	Chenna Reddy Thota	11kv	Habsiguda	19.16	21.00	01.44		11KV line cut near Big Bazar Opposite	-	
13		Peerzathiguda	RTC	11kv	Habsiguda	16.00	17.30	01.30		11KV End Kit failed at SS Yard	-	
14		Chakripuram	SV Nagar	11kv	Habsiguda	16.30	17.34	01.04		Line patrolling but no visible fault	-	
15		Pocharam	Jodimetla	11kv	Habsiguda	16.33	17.24	00.51		11KV line cut near Revathi Rice Mill	-	
1			E.S.I.	B.K.Guda	11kv	IV	16.28	17.47	01.19	EL,OL-Rph	Pin Insulator flash over at B.K.Guda Park	-
2			Nehru Nagar	Contonment	11kv	V	15.52	17.00	01.08	All Indication	No Visible Fault	-
3			Lalaguda	Chenna Reddy	11kv	V	15.59	17.10	01.11	OL-Yph	Kite Sticks on lines at S.V.Land Mark Apts	-
4			Osm. University	Keshav Nagar	11kv	V	15.50	17.00	01.10	EL,OL	No Visible Fault	-
5			Osm. University	Osm. University	11kv	V	15.55	17.45	01.50	EL	Tree branches fallen on lines at Darga PT	-
6	Marredpally		Addagutta	11kv	V	16.05	17.40	01.35	EL	Kite sticks on lines at Addagutta	-	
7	Marredpally		Jyothi Colony	11kv	V	16.10	17.50	01.40	EL,OL-Bph	Cloth fallen on lines at Jyothi Colony	-	
8	Gymkhana		Sikh Village	11kv	V	16.10	18.30	02.20	EL,OL	Tree branches fallen on lines at Sikh Village	-	
9	Gymkhana		Balamrai	11kv	V	16.24	18.35	02.11	EL,OL	Tree branches fallen on lines at Balamrai	-	
10	James Street		S.D.Road	11kv	V	16.50	20.20	03.30	EL,OL	Faulty AB Cable at Rangrez Bazar	-	
11	Sanjeevaiah Park		Police Lines	11kv	V	16.25	19.10	02.45	EL	Faulty 11KV Rani Bagh loads (B/F)	-	

## TSSPDCL - LMRC / Corporate office

Date: 01.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
12	HYD N	Gymkhana	Mud Fort	11kv	V	17.53	19.10	01.17	EL,OL	No Visible Fault	-
13		Patigadda	Rasoolpura	11kv	V	16.35	18.40	02.05	EL	Breaker problem at SS	-
14		Chilkaiguda	Pragatools	11kv	V	16.20	18.05	01.45	EL,OL	No Visible Fault	-
15		Vasanthapuri	Shesha Pahadi	11kv	V	15.48	17.02	01.14	EL,OL	No Visible Fault	-
16		Vasanthapuri	Siripuri	11kv	V	15.52	17.01	01.09	EL,OL	No Visible Fault	-
17		Vasanthapuri	Siripuri	11kv	V	17.03	18.40	01.37	EL,OL	No Visible Fault	-
18		Tirumalagiri	Srinagar Colony	11kv	VI	16.30	17.50	01.20	EL,OL-Bph	Tree branches fallen on lines & Pin Insulator flash over at Srinagar Colony	-
19		Bowenpally	Ferozguda	11kv	VI	16.20	17.35	01.15	EL,OL-Rph	No Visible Fault	-
20		Bhudevi Nagar	Yadamma Nagar	11kv	VI	16.30	18.15	01.45	EL	Pin Insulator flash over at Yadamma Nagar	-
21		Bowenpally	Jaya Nagar	11kv	VI	16.20	18.20	02.00	EL	Banners fallen on lines at Bowenpally Bus Stand	-
22		Bowenpally	Sancharpuri Colony	11kv	VI	16.20	18.20	02.00	EL	Banners fallen on lines at Bowenpally Bus Stand	-
23		Chinna Thokatta	Old Bowenpally	11kv	VI	16.44	18.05	01.21	All Indication	Tree branches fallen on lines at SS	-
1		HYD C	Indira Park	Indian Bulls	11kv	I	16.38	19.45	03.07	EL	Rain water entered in Cable at Indian Bulls
2	Indira Park		Kavadiguda	11kv	I	16.28	18.00	01.32	OL-R&Bph	Tree branches fallen on lines & Cable fault at Kavadiguda	-
3	Industrial Area		Mother Dairy	11kv	II	16.10	17.45	01.35	EL,OL-Rph	Tree branches fallen on lines at Balaji Nagar	-
4	Industrial Area		Vidya Nagar	11kv	II	16.15	17.30	01.15	EL	No Visible Fault	-
5	Bathkammakunta		Ramalayam	11kv	II	16.27	18.57	02.30	EL,OL-Rph	Big tree fallen on lines at Corporate Bank	-
6	Bathkammakunta		D.D.Colony	11kv	II	16.24	19.30	03.06	EL	No Visible Fault	-
7	Bathkammakunta		C.E.Colony	11kv	II	16.25	18.30	02.05	EL,OL-Bph	Big tree fallen on lines at Karur Vysa Bank	-
8	Bathkammakunta		Sai Baba Temple	11kv	II	16.43	19.25	02.42	EL,OL-Rph	No Visible Fault	-
9	Chilkaiguda		44 Bus Stop	11kv	II	16.15	18.00	01.45	EL	No Visible Fault	-
10	Chilkaiguda		Parsigutta	11kv	II	17.20	18.45	01.25	EL,OL-Rph	No Visible Fault	-
1	HYD S	Santosh Nagar	Moin Bagh	11kv	III	16.30	18.26	01.56	OL-R&Bph	No Visible Fault	-

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Ghanpur	33kv	Mahabubnagar	09.50	10.00	00.10	E/L	Stay Wire Problem	Ghanpur	-
2		Kodangal	Kothur	33kv	Mahabubnagar	12.30	13.20	00.50	E/L	HG Fuse Problem at 33KV Bomraspet	Kothur	-
3		Maddur	Kankurthy	33kv	Mahabubnagar	23.30	00.00	00.30	E/L	Not Rectified	Kankurthy	-
4		Wanaparthi	Gopalpet	33kv	Wanaparthi	18.50	19.20	00.30		Insulator Damaged at Bondalapally(V)	Gopalpet	-
5		Achampet	Amrabad	33kv	Nagarkurnool	16.50	21.10	04.20	E/L	Insulators Damaged near Mananoor(V)	Amrabad	-
1	NLG	Haliya	Yacharam	33kv	Miryalaguda	19.50	00.00	04.10		Due to rain	Yacharam	-
2		Madugulapally	Agamothkur	33kv	Miryalaguda	18.30	00.00	05.30		Due to rain	Agamothkur	-
3		Dirshincherla	Garidepally	33kv	Miryalaguda	20.40	00.00	03.20		Due to rain	Garidepally	-
4		K.M.Pally	Nampally	33kv	Devarakonda	21.10	00.00	02.50		Due to rain	Nampally	-
5		K.M.Pally	Gurrampodu	33kv	Devarakonda	22.15	00.00	01.45		Due to rain	Gurrampodu	-
6		K.M.Pally	Chinthapally	33kv	Devarakonda	20.15	00.00	03.45		Due to rain	Chinthapally	-
7		Guntipally	Chandampet	33kv	Devarakonda	15.40	00.00	08.20		Due to rain	Chandampet	-
8		Guntipally	Yerraram	33kv	Devarakonda	15.45	00.00	08.15		Due to rain	Yerraram	-
9		Atipamula	Atipamula	33kv	Nalgonda	18.10	22.20	04.10		Due to rain	Atipamula	-
10		Atipamula	Kethapally	33kv	Nalgonda	18.25	00.00	05.35		Due to rain	Kethapally	-
11		Yerrabelly	Mushampally	33kv	Nalgonda	20.15	00.00	03.45		Due to rain	Mushampally	-
12		Yerrabelly	kannikal	33kv	Nalgonda	20.30	22.25	01.55		Jumper Cut	kannikal	-
13		Munagala	Nadigudam	33kv	Suryaapt	21.30	02.15	04.15		Insuletor Faild	Nadigudam	-
14		Thungathurthi	Ravulapally	33kv	Suryaapt	20.00	00.00	04.00		Due to rain	Ravulapally	-
15		Thungathurthi	Annaram	33kv	Suryaapt	20.00	00.00	04.00		Due to rain	Annaram	-
16		Thungathurthi	Phanigiri	33kv	Suryaapt	20.00	00.00	04.00		Due to rain	Phanigiri	-
17		B.B.Nagar	Bollepally	33kv	Bhongiri	18.00	22.30	04.30		33KV CT Blast 132 KV Bibinagar	Bollepally	-
18		Mothkur	Azempet	33kv	Bhongiri	19.20	20.50	01.30		Line Falt	Azempet	-
1	MDK	Pashamailaram	Nandigama	33kv	Sangareddy	12.21	15.30	03.09		BD Due to Heavy wind	Nandigama	-
2	Siddipet	Palamakula	Narmetta	33kv	Siddipet	16.08	18.35	02.27		Tree fallen	Narmetta	-
3		Shanigaram	Begumpet	33kv	Siddipet	15.40	18.30	02.50		Pin Insulator fail	Begumpet	-
4		Tunkibollaram	Vantimamidi	33kv	Siddipet	15.30	18.13	02.43		Jumper loose connection	Vantimamidi	-
5		Duddeda	Kolanpaka	33kv	Siddipet	17.03	18.02	00.59		Tree fallen	Kolanpaka	-
1	RR N	132KV LGM Pet	33KV LGM Pet	33kv	Medchal	16.47	19.41	02.54		33KV Pin Insulator Failed at LGM Pet Village	33KV LGM Pet	-
2		132KV Medchal	33KV GP Pally-II	33kv	Medchal	17.41	18.25	00.44		No fault	33KV GP Pally-II	-
3		132KV Medchal	33KV GP Pally-II	33kv	Medchal	19.05	20.52	01.47		33KV Pin Insulator failed at GP Pally Village	33KV GP Pally-II	-