

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234		10		10		10			
5	RR(N)	54	550	1	11	1	11	1	11			
6	RR(E)	168	403									
7	Hyd	194	1044	2	20	2	20	2	20			
	Total	606	3055	3	41	3	41	3	41	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	7		7		6		1		1 NO. 33KV STILL
2	NLG	144	988	43	209	43	209	43	209			
3	MDK	107	933	2	23	2	23	2	21		2	2 no.s 11kv still
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	52	232	52	232	51	230	1	2	
	Grand Total	1082	6468	55	273	55	273	54	271	1	2	

TSSPDCL - LMRC / Corporate office

Date: 02.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ragadapa	Tripuraram	11KV	Miryalaguda	21.30	10.30	11.00	E/L	Tree branches fallen on the line	
2	NLG	Matoor	Tripuraram	11KV	Miryalaguda	21.30	12.00	09.30	E/L	Tree branches fallen on the line	
3	NLG	K.R.GUDEM	Tripuraram	11KV	Miryalaguda	18.00	17.30	23.30	E/L	Tree branches fallen on the line	
4	NLG	KONTHAPALAPALLY	Tripuraram	11KV	Miryalaguda	18.00	12.00	06.00	E/L	Tree branches fallen on the line	
5	NLG	PUSALAPADU	Tripuraram	11KV	Miryalaguda	18.00	11.30	06.30	E/L	11KV pin insulator failed	
6	NLG	BRUNDAVANA PURAM	Tripuraram	11KV	Miryalaguda	18.00	13.00	05.00	E/L	Tree branches fallen on the line	
7	NLG	Neelaigudem	Tripuraram	11KV	Miryalaguda	00.00	14.00	14.00	E/L	11KV disc insulator failed	
8	NLG	TRIPURARAM INDUSTRIAL	Tripuraram	11KV	Miryalaguda	20.30	13.30	07.00	E/L	11KV codncutor snapped	
9	NLG	S.N.PURAM	Tripuraram	11KV	Miryalaguda	20.30	14.00	06.30	E/L	Tree branches fallen on the line	
10	NLG	DUGGEPALLY	Tripuraram	11KV	Miryalaguda	20.30	19.30	23.00	E/L	Poles damaged	
11	NLG	P.D.PALLY	Tripuraram	11KV	Miryalaguda	20.30	16.45	20.15	E/L	poles damaged	
12	NLG	GAJALAPURAM	Tripuraram	11KV	Miryalaguda	20.30	21.00	01.30	E/L	Poles damaged	
13	NLG	MuKUNDAPURAM	Tripuraram	11KV	Miryalaguda	20.30	12.30	16.00	E/L	11KV pin insulator failed	
14	NLG	LIFT	Tripuraram	11KV	Miryalaguda	20.30	13.00	16.30	E/L	Tree branches fallen on the line	
15	NLG	TRIPURARAM	Tripuraram	11KV	Miryalaguda	20.30	13.30	17.00	E/L	Tree branches fallen on the line	
16	NLG	Rajavaram	Haliya	11KV	Miryalaguda	20.30	15.30	19.00	E/L	Tree branches fallen on the line	
17	NLG	Pulimamdidi	Haliya	11KV	Miryalaguda	00.10	08.50	08.40	E/L	Momenrty fault and not charged	
18	NLG	Sreenadapuram	Haliya	11KV	Miryalaguda	19.00	12.40	17.40	E/L	Tree fallen on the line near village	
19	NLG	Marapaka	Haliya	11KV	Miryalaguda	19.05	11.30	16.25	E/L	Tree fallen on the line near village	
20	NLG	Chennaram	Haliya	11KV	Miryalaguda	19.00	16.30	21.30	E/L	Tree fallen on the line near village	
21	NLG	Ibrahimpeta	Haliya	11KV	Miryalaguda	19.30	17.30	22.30	E/L	Poles damaged	
22	NLG	Naidupalem	Haliya	11KV	Miryalaguda	19.35	18.00	22.25	E/L	Poles damaged	
23	NLG	Kupasally	Haliya	11KV	Miryalaguda	18.00	09.20	15.20	E/L	Tree fallen on the line near village	
24	NLG	Ramadugu	Haliya	11KV	Miryalaguda	18.00	07.00	13.00	E/L	Momenrty fault and not charged	
25	NLG	Thimmapur,	Haliya	11KV	Miryalaguda	18.00	07.00	13.00	E/L	Momenrty fault and not charged	
26	NLG	Shakapuram	Nidmanoor	11KV	Miryalaguda	18.30	19.00	00.30	E/L	Tree fallen on the line near village	
27	NLG	Water works	Nidmanoor	11KV	Miryalaguda	20.00	22.00	02.00	E/L	Tree fallen on the line near village	
28	NLG	Nidmanoor Town	Nidmanoor	11KV	Miryalaguda	20.00	22.00	02.00	E/L	Tree fallen on the line near village	
29	NLG	Bankapuram	Nidmanoor	11KV	Miryalaguda	20.00	22.00	02.00	E/L	Tree fallen on the line near village	
30	NLG	Water works	Nidmanoor	11KV	Miryalaguda	18.30	13.20	05.10	E/L	11KV conductor snapped	
31	NLG	Lift feeder	Nidmanoor	11KV	Miryalaguda	19.00	12.40	06.20	E/L	Tree branches fallen on the line	
32	NLG	Utkur	Nidmanoor	11KV	Miryalaguda	19.00	11.50	07.10	E/L	2Nos poles damaged	
33	NLG	Mupparam	Nidmanoor	11KV	Miryalaguda	18.30	07.10	12.40	E/L	Tree fallen on the line near village	
34	NLG	Yerrabelli	Nidmanoor	11KV	Miryalaguda	18.30	07.10	12.40	E/L	Tree fallen on the line near village	
35	NLG	Guntipally	Nidmanoor	11KV	Miryalaguda	18.30	12.30	18.00	E/L	Poles damaged	
36	NLG	Yerrabelli	Nidmanoor	11KV	Miryalaguda	18.30	12.30	18.00	E/L	Poles damaged	
37	NLG	JK Gudem	Nidmanoor	11KV	Miryalaguda	18.30	14.30	20.00	E/L	11KV conductor Snapped	
38	NLG	Dharmapuram	Nidmanoor	11KV	Miryalaguda	18.30	16.00	22.30	E/L	Tree fallen on the line near village	
39	NLG	Guntipally	Nidmanoor	11KV	Miryalaguda	18.30	15.00	20.30	E/L	Tree fallen on the line near village	
40	NLG	G.K.palem	Nidmanoor	11KV	Miryalaguda	18.30	16.00	22.30	E/L	Poles damaged	
41	NLG	Machanapally	Nidmanoor	11KV	Miryalaguda	18.30	16.30	22.00	E/L	Poles damaged	
42	NLG	Narammagudem	Nidmanoor	11KV	Miryalaguda	10.00	15.20	05.20	E/L	11KV Conductor snapped	

43	NLG	Thummadam	Nidmanoor	11KV	Miryalaguda	10.00	14.15	04.15	E/L	Tree branches fallen on the line	
44	NLG	Gaddameedi thanda	Peddavoor	11KV	Miryalaguda	20.30	10.45	14.15	E/L	11KV Conductor snapped	
45	NLG	Chalukurthy	Peddavoor	11KV	Miryalaguda	06.30	09.00	02.30	E/L	11KV Conductor snapped	
46	NLG	Navodaya	Peddavoor	11KV	Miryalaguda	06.30	09.00	02.30	E/L	Tree fallen on the line near village	
47	NLG	Ramannagudem	Peddavoor	11KV	Miryalaguda	06.30	12.30	06.00	E/L	11KV pin insulator failed	
48	NLG	Peddavoor Rural	Peddavoor	11KV	Miryalaguda	19.00	17.30	22.30	E/L	11KV conductor Snapped	
49	NLG	Basireddypally	Peddavoor	11KV	Miryalaguda	19.00	16.30	21.30	E/L	Pole damage	
50	NLG	Battugudem	Peddavoor	11KV	Miryalaguda	19.00	11.30	16.30	E/L	11KV disc insulator failed	
51	NLG	Thungathurty	Peddavoor	11KV	Miryalaguda	19.00	12.00	17.00	E/L	11KV conductor failed	
52	NLG	Nayanivanikunta	Peddavoor	11KV	Miryalaguda	19.00	08.00	13.00	E/L	Tree fallen on the line near village	
53	NLG	Velmagudem	Peddavoor	11KV	Miryalaguda	09.00	16.00	20.00	E/L	Tree fallen on the line near village	
54	NLG	Peddagudem	Peddavoor	11KV	Miryalaguda	09.00	14.00	05.00	E/L	11 KV Disc insulator failed	
55	NLG	Basireddypally	Peddavoor	11KV	Miryalaguda	09.00	16.15	20.15	E/L	Tree fallen on the line near village	
56	NLG	Vemulapally Agl	Vemulaply	11KV	Miryalaguda	20.30	18.10	21.10	E/L	Tree fallen on the line near village	
57	NLG	RAVULAPENTA	Vemulaply	11KV	Miryalaguda	20.30	16.00	19.30	E/L	Pole damage	
58	NLG	MANGAPURAM	Vemulaply	11KV	Miryalaguda	20.30	12.00	15.30	E/L	11KV pin insulator failed	
59	NLG	THOPUCHERLA	Vemulaply	11KV	Miryalaguda	20.30	11.30	15.00	E/L	Tree fallen on the line near village	
60	NLG	MOLKAPATNAM	Vemulaply	11KV	Miryalaguda	20.30	19.00	22.30	E/L	Tree fallen on the line near village	
61	NLG	Thungapadu	Miryalagud Rural	11KV	Miryalaguda	00.30	11.30	11.00	E/L	11KV pin insulator failed	
62	NLG	Iyalapuram	Miryalagud Rural	11KV	Miryalaguda	00.30	17.44	17.14	E/L	Tree branches fallen on the line	
63	NLG	V.K.Palem	Miryalagud Rural	11KV	Miryalaguda	00.30	12.10	11.40	E/L	11KV conductor snapped	
64	NLG	KOTHAGUEM TOWN	Miryalagud Rural	11KV	Miryalaguda	23.45	11.10	12.35	E/L	11 KV Disc insulator failed	
65	NLG	Laxmipuram	Miryalagud Rural	11KV	Miryalaguda	23.45	12.20	11.25	E/L	11KV Conductor snapped at two places	
66	NLG	KOTHAGUEM INDL.	Miryalagud Rural	11KV	Miryalaguda	23.45	10.30	13.15	E/L	11KV disc insulator failed	
67	NLG	KOTHAGUEM(KO THAGUEM)	Miryalagud Rural	11KV	Miryalaguda	23.45	11.00	12.45	E/L	11KV Pin insulator failed	
68	NLG	Avanthipuram	Miryalagud Rural	11KV	Miryalaguda	00.30	10.30	10.00	E/L	11 KV conductor Snapped	
69	NLG	Gudur	Miryalagud Rural	11KV	Miryalaguda	00.30	11.00	10.30	E/L	11KV Pin insulator failed	
70	NLG	Indi-II	Miryalagud Rural	11KV	Miryalaguda	00.30	09.50	09.20	E/L	Tree branches fallen on the line	
71	NLG	Badalapuram	Miryalagud Rural	11KV	Miryalaguda	00.30	10.30	10.00	E/L	11KV disc insulator failed	
72	NLG	Utlapally	Miryalagud Rural	11KV	Miryalaguda	00.30	11.00	10.30	E/L	11 KV conductor Snapped	
73	NLG	Yadgarpally	Miryalagud Rural	11KV	Miryalaguda	00.30	12.30	12.00	E/L	11KV Pin insulator failed	
74	NLG	Kalwapally	Miryalagud Rural	11KV	Miryalaguda	00.30	11.30	11.00	E/L	Tree branches fallen on the line	
75	NLG	Settiapalem	Miryalagud Rural	11KV	Miryalaguda	00.30	15.00	14.30	E/L	1No dis and pin insulator failed	
76	NLG	Thadakamilla	Miryalagud Rural	11KV	Miryalaguda	00.30	12.40	12.10	E/L	11KV Pin insulator failed	
77	NLG	Salkanoor	Miryalagud Rural	11KV	Miryalaguda	00.30	13.20	12.50	E/L	Tree branches fallen on the line	
78	NLG	Ulsaipelm	Damarcherla	11KV	Miryalaguda	06.00	11.30	05.30	E/L	Tree branches fallen on the line	
79	NLG	Kondrapole	Damarcherla	11KV	Miryalaguda	09.00	10.25	01.25	E/L	Tree branches fallen on the line	
80	NLG	Nunavath thanda	Damarcherla	11KV	Miryalaguda	09.00	10.25	01.25	E/L	Tree branches fallen on the line	
81	NLG	Ramky	Damarcherla	11KV	Miryalaguda	09.00	11.00	02.00	E/L	Tree branches fallen on the line	
82	NLG	Chandupatla	Chandupatla	11KV	Bhongir	18.40	20.30	01.50	E/L	11Kv Stay Snapped and Pole Bend	
83	NLG	addguduru	Ch.ramaram	11KV	Bhongir	05.30	07.30	02.00	E/L	Due to Havy Gale & wind Pole Damaged	
84	NLG	addguduru	Kotamarthy	11KV	Bhongir	05.30	07.30	02.00	E/L	Due to Havy Gale & wind Pole Damaged	
85	NLG	Azeempet	Azeempet	11KV	Bhongir	03.00	05.00	03.00	E/L	Due to Havy Gale & wind Poles damaged	
86	NLG	Azeempet	T.Repaka	11KV	Bhongir	03.00	05.00	03.00	E/L	Due to Havy Gale & wind Poles Damaged HT/LT	
87	NLG	Chandur	Thummalapally	11KV	Nalgonda	17.20	08.20	15.40	E/L	HT/LT melting	
88	NLG	Chandur	Gundrepally	11KV	Nalgonda	06.00	08.30	02.30	E/L	AB switch problem	
89	NLG	Chityala	Nerada Express	11KV	Nalgonda	18.20	19.40	01.20	E/L	11KV line melting	

90	NLG	Pagidimarri	Madanapuram	11KV	Nalgonda	06.00	08.16	02.16	O/L	AB switch problem	
91	NLG	Turkapally	M.Gouraram	11KV	Nalgonda	22.00	11.10	13.10	E/L	Tree fallen on 11KV line near Raghupathi Rao thota	
92	NLG	Aitipamula	Ch.Chennaram	11KV	Nalgonda	00.30	08.00	07.30	E/L	Tree fallen on 11kv line near by village	
93	NLG	Kattangur	Kalimera	11KV	Nalgonda	00.20	11.10	10.50	E/L	11KV Insulator failed	
94	NLG	Kattangur	Mallaram	11KV	Nalgonda	03.00	10.30	07.30	E/L	Tree fallen on line	
95	NLG	Kattangur	Duginelly	11KV	Nalgonda	18.00	10.40	16.40	E/L	Tree fallen on line	
96	NLG	Gudapoor	Munugode town	11KV	Nalgonda	19.00	20.15	01.15	E/L	11KV Insulator failed	
97	NLG	Gudapoor	Singaram	11KV	Nalgonda	08.00	10.30	02.30	E/L	11KV line cut at nearby Rathipally(V)	
98	NLG	Palem	Industrial	11KV	Nalgonda	18.00	21.30	03.30	O/L	Tree fallen on line	
99	NLG	Palem	Bopparam	11KV	Nalgonda	18.30	22.50	04.20	E/L	Tree fallen on line	
100	NLG	Palem	Ogodu	11KV	Nalgonda	18.00	07.50	13.50	E/L	Tree fallen on line, 11KV line cut	
101	NLG	Arjalabavi	Marriguda Indl.	11KV	Nalgonda	18.20	21.10	02.50	E/L	11KV jumper cut	
102	NLG	Gollaguda	Ramnagar	11KV	Nalgonda	19.15	21.30	02.15	E/L	Tree fallen on 11kv line	
103	NLG	B.Vellemla	Auravani	11KV	Nalgonda	06.00	11.00	13.50	E/L	Tree fallen on line	
104	NLG	Akaram	Vallala	11KV	Nalgonda	20.00	09.15	13.15	E/L	Tree fallen on 11KV line	
105	NLG	Baironibanda	Baironibanda	11KV	Nalgonda	06.00	11.20	05.20	E/L	Tree fallen on line	
106	NLG	Madgulapally	Madgulapally Town	11KV	Nalgonda	18.00	23.10	05.10	E/L	11KV line cut	
107	NLG	Chandur	Kastala	11KV	Nalgonda	17.20	11.00	17.20	E/L	Tree branches fallen on line	
108	NLG	Pullemla	Bodangiparthi	11KV	Nalgonda	17.20	09.30	18.50	O/L	HT/LT melting	
109	NLG	Kanagal	Kanagal AGL	11KV	Nalgonda	18.00	12.00	18.00	E/L	11KV Disc insulator failed	
110	NLG	Thimmannagudem	Narsimhapuram	11KV	Nalgonda	18.00	08.45	14.45	E/L	Tree branches fallen on line	
111	NLG	Thimmannagudem	Chennaram	11KV	Nalgonda	18.00	08.50	14.50	O/L	Tree branches fallen on line	
112	NLG	Thimmannagudem	T.K.Gudem	11KV	Nalgonda	18.00	14.15	20.15	E/L	11KV line cut	
113	NLG	Thoragal	Thangellavarigudem	11KV	Nalgonda	19.00	12.00	17.00	E/L	11KV Disc insulator failed	
114	NLG	Thoragal	Madaram	11KV	Nalgonda	19.00	12.30	17.30	O/L	11KV line cut	
115	NLG	Pamanagundla	Yerasanigudem	11KV	Nalgonda	06.37	11.25	18.05	E/L	11KV V X arms damaged	
116	NLG	Marrur	Marrur	11KV	Nalgonda	18.00	12.05	18.05	E/L	HT/LT melting	
117	NLG	Marrur	Mangalapally	11KV	Nalgonda	18.00	15.15	21.15	O/L	11KV Insulator failed	
118	NLG	Mushampally	Mushampally AGL	11KV	Nalgonda	02.10	11.30	18.05	E/L	Tree branches fallen on line	
119	NLG	Mushampally	Muthyalamma	11KV	Nalgonda	02.10	12.50	18.05	E/L	Tree branches fallen on line	
120	NLG	Mushampally	Erugantipally	11KV	Nalgonda	02.10	12.25	18.05	O/L	11KV Insulator failed	
121	NLG	Narsingbatla	Gadibaigudem	11KV	Nalgonda	07.30	11.20	03.50	E/L	11KV Disc insulator failed	
122	NLG	Narsingbatla	Chennugudem	11KV	Nalgonda	07.30	10.40	03.10	E/L	11KV line cut	
123	NLG	SLBC	SRTIST	11KV	Nalgonda	18.00	11.40	17.40	O/L	Tree branches fallen on line	
124	NLG	SLBC	M.D.Pally	11KV	Nalgonda	18.00	12.00	18.00	O/L	3Nos. Poles damaged	
125	NLG	Nakkalapally	Nakkalapally	11KV	Nalgonda	21.30	09.40	12.10	E/L	Tree branches fallen on line	
126	NLG	Nakkalapally	Shapally	11KV	Nalgonda	21.30	10.50	13.20	E/L	11KV line cut at SS-10	
127	NLG	Baironibanda	N.G.Kothapally	11KV	Nalgonda	06.00	15.15	09.15	E/L	HT/LT melting	
128	NLG	S.Gouraram	Gurajala	11KV	Nalgonda	19.30	11.10	15.40	E/L	11KV jumper cut	
129	NLG	S.Gouraram	Adloor	11KV	Nalgonda	06.30	09.37	03.07	E/L	Tree branches fallen on line	
130	NLG	Keshrajupally	Mahilapranaganam	11KV	Nalgonda	06.00	11.50	05.50	O/L	Tree fallen on line	
131	NLG	Keshrajupally	Patapally	11KV	Nalgonda	03.00	11.40	08.40	E/L	Tree fallen on line	
132	NLG	Madgulapally	Kukkadam	11KV	Nalgonda	18.00	16.00	22.00	O/L	11KV jumper cut	
133	NLG	Rajupeta	Bandavarigudem	11KV	Nalgonda	20.00	15.00	19.00	E/L	Tree branches fallen on line	
134	NLG	Rajupeta	Rajupeta	11KV	Nalgonda	20.00	16.05	20.05	O/L	Tree branches fallen on line	
135	NLG	Rajupeta	Jonnagaddalagudem	11KV	Nalgonda	20.00	11.00	15.00	O/L	Tree branches fallen on line	
136	NLG	Rayaniguda	Korvonigudem	11KV	Nalgonda	07.00	12.00	05.00	E/L	11KV Disc insulator failed	
137	NLG	Rayaniguda	Kondaram	11KV	Nalgonda	07.00	12.10	05.10	E/L	Tree branches fallen on line	
138	NLG	Rayaniguda	Jangareddygudem	11KV	Nalgonda	07.00	11.30	04.30	E/L	HT/LT melting	
139	NLG	Rayaniguda	Rayanigudem	11KV	Nalgonda	07.00	12.00	05.00	O/L	11KV jumper cut	
140	NLG	Rayaniguda	A.D.Pally	11KV	Nalgonda	07.00	10.35	03.35	O/L	11KV jumper cut	

141	NLG	Thipparthi	Sarvaram	11KV	Nalgonda	18.20	16.10	21.50	E/L	11KV Insulator failed	
142	NLG	Thipparthi	Silarmiyagudem	11KV	Nalgonda	18.20	09.15	14.55	E/L	11KV Insulator failed	
143	NLG	Thipparthi	Thipparthi town	11KV	Nalgonda	18.20	09.55	15.05	E/L	11KV Insulator failed	
144	NLG	Thipparthi	G.G.Palem	11KV	Nalgonda	18.20	16.00	22.40	E/L	11KV jumper cut	
145	NLG	Thipparthi	Marriguda	11KV	Nalgonda	18.20	14.25	21.05	O/L	11KV Disc insulator failed	
146	NLG	Thipparthi	Indloor	11KV	Nalgonda	18.20	16.05	21.15	E/L	11KV line cut	
147	NLG	Marrigiua	Y.G.pally	11KV	Devarakonda	23.30	06.00	06.30	E/L	Rine	
148	NLG	Kopple	Ranaigudam	11KV	Devarakonda	18.58	16.50	10.00	E/L	Pole Damaged	
149	NLG	Kopple	Bollaram	11KV	Devarakonda	18.58	18.00	11.00	E/L	Pole Damaged	
150	NLG	K.M.Pally	Idl	11KV	Devarakonda	17.00	23.00	06.00	E/L	11Insulator Fail	
151	NLG	K.M.Pally	K.M.Pally Townen	11KV	Devarakonda	17.00	23.00	06.00	E/L	11Insulator Fail	
152	NLG	K.M.Pally	C.A.Pally	11KV	Devarakonda	17.00	23.00	06.00	E/L	Tree Follows	
153	NLG	K.M.Pally	Chenaram	11KV	Devarakonda	17.00	16.00	23.00	E/L	11KV Wire Cut	
154	NLG	K.M.Pally	Doniyala	11KV	Devarakonda	17.00	11.00	21.00	E/L	1PH Dtr fail	
155	NLG	Angadipeta	Gudipally	11KV	Devarakonda	18.30	16.00	11.30	E/L	Jumper Cut & Pole Damaged	
156	NLG	Angadipeta	Akkampally	11KV	Devarakonda	18.30	17.00	10.30	E/L	Pole Damaged	
157	NLG	Angadipeta	R.R.Gudeam	11KV	Devarakonda	18.30	16.30	11.00	E/L	Pole Damaged	
158	NLG	Angadipeta	P.A.Pally R	11KV	Devarakonda	18.30	16.30	10.30	E/L	Pole Damaged	
159	NLG	Angadipeta	Chilkamarri	11KV	Devarakonda	18.30	17.00	09.30	E/L	11 Kv line Cut	
160	NLG	Angadipeta	P.A.Pally T	11KV	Devarakonda	18.30	17.00	10.30	E/L	Pole Damaged	
161	NLG	Ghanpuram	SLBC	11KV	Devarakonda	18.30	17.30	11.00	E/L	Pole Damaged	
162	NLG	Ghanpuram	G.B.Pally	11KV	Devarakonda	19.30	07.00	12.30	E/L	Pole Damaged	
163	NLG	Ghanpuram	Polkampally	11KV	Devarakonda	20.30	17.30	09.00	E/L	11KV Wire Cut	
164	NLG	Ghanpuram	Kodhanda Puram	11KV	Devarakonda	21.30	17.00	07.30	E/L	11KV Wire Cut	
165	NLG	Ghanpuram	Ghanpuram	11KV	Devarakonda	22.30	18.00	15.00	E/L	Pole damaged	
166	NLG	Azmapuram	Chanampally	11KV	Devarakonda	06.00	17.00	11.00	E/L	Pole damaged	
167	NLG	Azmapuram	Mallapuram	11KV	Devarakonda	16.00	18.00	02.00	E/L	11KV Wire Cut	
168	NLG	Dugayala	Thirumalagiri	11KV	Devarakonda	20.00	14.00	15.00	E/L	Jumpr Cut & Earth Probleam	
169	NLG	Dugayala	Dugayala	11KV	Devarakonda	20.00	16.00	08.00	E/L	11Kv Line Cut	
170	NLG	Puttamgandi	Chinthal Thanda	11KV	Devarakonda	19.00	14.00	07.00	E/L	Jumper Cut & Pole	
171	NLG	Mellavai	Pasnoor	11KV	Devarakonda	14.30	16.00	01.30	E/L	11Kv Line Cut	
172	NLG	Mellavai	Revalli	11KV	Devarakonda	14.30	17.00	02.30	E/L	11Kv Line Cut	
173	NLG	Nampally	Peddapuram	11KV	Devarakonda	14.30	17.00	02.30	E/L	jumper cutt	
174	NLG	Nampally	M.r.pally	11KV	Devarakonda	14.30	16.25	01.35	E/L	jumper cutt	
175	NLG	Nampally	Nawalagudam	11KV	Devarakonda	14.30	18.20	03.50	E/L	Tree Fallen	
176	NLG	Chepur	Mosangi	11KV	Devarakonda	11.00	17.00	06.00	E/L	pole Damaged	
177	NLG	Chepur	Theripally	11KV	Devarakonda	11.00	17.30	06.00	E/L	pole Damaged	
178	NLG	Junuthala	Paliphad	11KV	Devarakonda	11.00	13.20	02.20	E/L	pole Damaged	
179	NLG	Palakeedu	Palakeedu	11KV	Huzurnagar	19.00	07.10	12.10	E/L	11 KV Jumper cut at Palakeedu (v)	
180	NLG	Mukundapuram	Mukundapuram	11KV	Huzurnagar	18.45	14.19	19.34	E/L	11kv line snapped at Mukundapuram (v)	
181	NLG	Gaddipally	Ponugodu	11KV	Huzurnagar	18:30	12.40	18.10	E/L	Tree follen11kv line snapped at ponugodu (v)	
182	NLG	Keethavarigudem	Rainigudem	11KV	Huzurnagar	18.30	17.05	23.05	E/L	11kv line snapped at Rainigudem (v)	
183	NLG	Huzurnagar	Town-2	11KV	Huzurnagar	19.00	02.30	07.30	E/L	11 KV Jumper Cut at Huzurnagar (T)	
184	NLG	Ananthagiri	Shantinagar	11KV	Huzurnagar	19.20	01.00	05.20	E/L	11kv Line snapped at Shantinagar (v)	
185	NLG	Thogarrai	Kapugallu	11KV	Huzurnagar	21.30	10.00	12.30	E/L	11kv jumper cut at Kapugallu (v)	
186	NLG	Chilukur	Palannaram	11KV	Huzurnagar	20.10	10.40	13.40	E/L	11kv inslater failed at Palannaram (v)	
187	NLG	Munagala	Munagala town	11KV	Huzurnagar	00.00	08.30	08.30	E/L	11kv line snapped at Munagala (v)	
188	NLG	Nadigudem	Ramapuram	11KV	Huzurnagar	21.00	17.45	21.45	E/L	11kv linslater failed at Ramapuram (v)	
189	NLG	Jammigadda	Town	11KV	Suryapet	18.45	21.35	02.50	E/L	Conductor Snapped	
190	NLG	Jammigadda	Ambedkar Nagar	11KV	Suryapet	20.40	22.30	01.50	E/L	Tree Branch fallen on the line	
191	NLG	Jammigadda	Estate	11KV	Suryapet	18.45	20.45	02.00	E/L	Tree Branch fallen on the line	
192	NLG	Kudakuda	Ilapuram	11KV	Suryapet	02.00	07.30	05.30	E/L	Tree Branch fallen on the line	

193	NLG	Kudakuda	MG Nagar Thanda	11KV	Suryapet	07.00	09.00	02.00	E/L	Tree Branch fallen on the line	
194	NLG	Ramachandrapuram	Ramachandrapuram	11KV	Suryapet	04.00	08.00	04.00	E/L	Lince Cut & Tree Branch fallen on the line	
195	NLG	Ramachandrapuram	Rathnapuram	11KV	Suryapet	05.00	08.00	03.00	E/L	Lince Cut & Tree Branch fallen on the line	
196	NLG	Indl.Estate	Bibigudem Express	11KV	Suryapet	20.05	21.07	01.02	E/L	Tree Branch fallen on the line	
197	NLG	Indl.Estate	Vijayacolony	11KV	Suryapet	20.14	21.30	01.16	E/L	Tree Branch fallen on the line	
198	NLG	Indl.Estate	Durajpally	11KV	Suryapet	20.10	21.57	01.47	E/L	Tree fallen on the line & Conductor snapped	
199	NLG	Indl.Estate	Estate	11KV	Suryapet	19.50	22.15	02.25	E/L	Tree fallen on the line & Conductor snapped	
200	NLG	Nagaram	Nagaram	11KV	Suryapet	02.00	06.00	04.00	E/L	Insulator failed	
201	NLG	S.V Collage	G.Hotel	11KV	Suryapet	20.00	21.00	01.00	E/L	Tree Branch fallen on the line	
202	NLG	S.V Collage	New Bus Stand	11KV	Suryapet	20.00	23.00	03.00	E/L	Tree Branch fallen on the line	
203	NLG	S.V Collage	Layola Express	11KV	Suryapet	20.00	22.00	02.00	E/L	Tree Branch fallen on the line	
204	NLG	Arvapally	Town	11KV	Suryapet	02.00	08.00	06.00	E/L	Tree Branch fallen on the line	
205	NLG	Arvapally	Thungagudem	11KV	Suryapet	02.00	10.00	08.00	E/L	Tree Branch fallen on the line	
206	NLG	Tekumatla	Pillalamarry	11KV	Suryapet	00.00	11.10	11.10	E/L	Insulator Flashover	
207	NLG	Yerkaram	Yerkaram	11KV	Suryapet	02.00	09.30	07.30	E/L	Line Melt & Conductor Snapped	
208	NLG	Yerkaram	Ramannagudem	11KV	Suryapet	01.00	06.00	05.00	E/L	Insulator failed	
209	NLG	Kasarabada	Circlepeta	11KV	Suryapet	06.00	12.00	06.00	E/L	Insulator failed	
1	Siddipet	Rampur	Maqdumpur	11KV	Siddipet	17:00	7:00	14:00		Disk fail	
2		Rampur	Palamakula	11KV	Siddipet	0:50	8:00	7:10		11 KV Wire Cut	
3		Ankshapur	Khanapur	11KV	Siddipet	7:00	12:45	5:45		Disk fail,Poles Damage	
4		Ankshapur	Nagarajpally	11KV	Siddipet	0:00	11:12	11:12		HT/LT Wire Damage	
5		Kondamrajpally	Kondamrajpally	11KV	Siddipet	17:30	21:30	4:00		Disk fail	
6		Pullur	Pullur	11KV	Siddipet	17:50	20:00	2:10		11 KV Wire Cut	
7		Raghvapur	Bachaipally	11KV	Siddipet	16:50	0:00	7:10		Till Now	
8		Raghvapur	Peddalingareddypally	11KV	Siddipet	16:45	18:45	2:00		Tree branches fall on the 11 KV wire	
9		Raghvapur	Raorukula	11KV	Siddipet	16:55	18:55	2:00		Poles Damage	
10		Peddagundavelly	Balwanthapur	11KV	Siddipet	16:30	21:30	5:00		Earth Load	
11		Peddagundavelly	Peddagundavelly I	11KV	Siddipet	17:30	22:00	4:30		Earth Load	
12		Thimmapur	Thimmapur	11KV	Siddipet	16:00	18:30	2:30		Tree branches fall on the 11 KV wire	
13		Irkode	Chinnagundavelly	11KV	Siddipet	17:00	18:05	1:05		Tree branches fall on the 11 KV wire	
14		Irkode	Irkode	11KV	Siddipet	17:00	20:15	3:15		Tree branches fall on the 11 KV wire	
15		Kammarlapally	Kothapally	11KV	Siddipet	15:00	18:00	3:00		Jumper Cut	
16		Kammarlapally	Kothapally	11KV	Siddipet	23:00	6:00	7:00		AB Switich problem	
17		Gurralagondi	Malyala	11KV	Siddipet	1:00	7:00	6:00		Poles Damage	
18		Jakkapur	Shanigakuntla	11KV	Siddipet	6:00	9:30	3:30		Insulater fail	
19		Vittalapur	Vittalapur	11KV	Siddipet	8:30	12:45	4:15		Jumper Cut	
20		Tadkapally	Tadkapally	11KV	Siddipet	9:00	12:30	3:30		Tree branches fall on the 11 KV wire	
21		Ponnala	Ponnala	11KV	Siddipet	16:10	9:30	17:20		Poles Damage,Tree branches fall on the 11 KV wire	
22	Ponnala	Bakrichepyala	11KV	Siddipet	16:10	9:30	17:20		Poles Damage,Tree branches fall on the 11 KV wire		
23	Ponnala	Rangadampally	11KV	Siddipet	16:10	0:00	7:50		Till Now		
1	RR south	GACHIBOWLI	Hafeezpet	11KV	GACHIBOWLI	16.58	18.00	01.02	EL/OL	Due to Heavy rain	
2		GACHIBOWLI	Papireddy colony	11KV	GACHIBOWLI	17.00	18.30	01.30	OL	Due to Heavy rain, In Middle Incoming Supply Failure, No visible fault	
3		GACHIBOWLI	Papireddy colony	11KV	GACHIBOWLI	17.15	18.15	01.00	OL	Due to Heavy rain, In Middle Incoming Supply Failure, No visible fault	
4		GACHIBOWLI	Papireddy colony	11KV	GACHIBOWLI	17.15	18.15	01.00	OL	Due to Heavy rain, In Middle Incoming Supply Failure, No visible fault	
5		GACHIBOWLI	Mathrusri nagar	11KV	GACHIBOWLI	17.25	18.40	01.15	OL	Due to Heavy rain	

6	GACHIBOWLI	Gachibowli	11KV	GACHIBOWLI	19.40	21.05	01.25	OL	11KV disc fail at Chirag Public School	
7	GACHIBOWLI	Hafeezpet	11KV	GACHIBOWLI	19.50	21.00	01.10	EL/OL Y-Ph	LABS open at Anapurna Hotel	
8	KONDAPUR	Kothaguda	11KV	KONDAPUR	17.10	18.15	01.05	EL/OL	Due to heavy rain	
9	KONDAPUR	Kothaguda	11KV	KONDAPUR	18.40	19.50	01.10	EL/OL	Due to heavy rain	
10	Kokapet	IBRAHIMBAGH	11KV	Kokapet	15.55	20.35	04.40	OL	Phase touched to advertisement Board at Rockwell School	

1	RR North	Hudatruckpark	Sangeethnagar	11KV	Kukatpally	17.22	18.10	00.48	EL	11kv line PinInsulater failure near KSR Tower at Kukatpally	
2		Nizampet	Bandari lay-out	11KV	Kukatpally	17.55	18.30	00.35	EL/OL	11kv line PinInsulater failure near KSR Tower at Kukatpally	
3		Jeedimetla-III	Sudharshan Drugs	11KV	Jeedimetla	18.08	20.08	02.00	EL/OL	11kv line AB Cable Failure at Sai Kantta	
4		Jeedimetla-I	Shapur Nagar	11KV	Jeedimetla	18.20	19.50	01.30	EL/OL	Tree Fallen the 11kv line At Shapur Nagar	
5		Jeedimetla-I	Phase-I	11KV	Jeedimetla	18.20	20.20	02.00	EL/OL	Tree Fallen the 11kv line At phase-I { Line AB Opend }	
6		Subash Nagar	Jeedimetla	11KV	Medchal	18.10	19.15	01.05	BD	11KV Dise failed at Sindhu Apartment	
7		Subash Nagar	Pragha Tools	11KV	Medchal	18.20	19.20	01.00	BD	Tree fallen on the 11KV Line at Praghatools Company	
8		Subash Nagar	Jairam Nagar	11KV	Medchal	18.15	19.09	00.54	BD	Tree fallen on the 11KV Line at Jeans Company	
9		Subash Nagar	Padma Nagar	11KV	Medchal	17.50	19.05	01.15	BD	Tree fallen on the 11KV Line at Padma Nagar Ringroad	
10		GP Pally	Maisammaguda	11KV	Medchal	07.50	08.40	00.50	BD	Tree fallen on the 11KV Line at Satyam Computers	
11		Athiwelly	Dabeerpur	11KV	Medchal	18.30	19.30	01.00	BD	Tree fallen on the 11KV Line at Railway Colony	
1	Hyd central	Nizam College	Little Flower	11KV	I	18.15	19.28	01.13	EL	No Visible Fault	-----
2		Exhibition	Collector Office	11KV	I	18.15	19.35	01.20	EL,OL-Rph	Cable End Kit fault at Hindi Milap	-----
3		Asif Nagar	Padmanabha Nagar	11KV	VII	17.42	18.56	01.14	EL,OL-Rph	Faulty loads of 11KV Saber Nagar feeder (B/F)	-----
4		S.D.Hospital	Ahmed Nagar Cable	11KV	VII	18.01	19.11	01.10	EL	HT Jumper cut at Priyadarshini Apts	-----
5		Gudimalkapur	Zeba Bagh	11KV	VII	18.23	20.23	02.00	EL	Cable fault at Zeba Bagh	Arranged B/F on 11KV Zaheera Masjid fdr
1	Hyd north	E.S.I.	B.K.Guda	11KV	IV	17.59	19.07	01.08	EL,OL-Bph	No Visible Fault	-----
2		Road No.22	Obul Reddy	11KV	X	17.36	18.46	01.10	EL,OL-Rph	Tree branches fallen on lines at Road No.45	-----
3		Toli Chowki	Hanuman Temple	11KV	X	17.43	19.15	01.32	EL	No Visible Fault	-----
4		Film Nagar	B.V.Bhavan	11KV	X	17.45	19.46	02.01	EL,OL-Rph	UG Cable damaged at B.V.Bhavan	-----
5		MLA Colony	Lotus Pond	11KV	X	17.48	19.55	02.07	EL,OL	Cable End Kit failed at K.R.Venkat Reddy's House	-----
6		Road No.2	Lumbini Mall	11KV	X	17.50	20.55	03.05	EL	Cable End Kit failed at SBI Bank, Sagar Society	-----
7		Yellareddyguda	Engineers Colony	11KV	X	17.52	19.21	01.29	EL	Pin Insulator flash over at Peacock Hotel	-----
8		Road No.2	E-Seva	11KV	X	18.15	20.18	02.03	EL	HG fuse B/O at Road No.4	-----
9		Yousufguda	Hylam Colony	11KV	X	19.28	21.40	02.12	EL,OL-Rph	Pin Insulator flash over at Road No.10 C, Venkatagiri	Arranged B/F on 11KV Venkatagiri fdr
10		K.I.M.S.	D.V.Colony	11KV	V	18.22	19.49	01.27	EL,OL-Rph	Cloth fallen on lines at V.R.Apts	-----
11		Bansilalpet	Naganna Kunta	11KV	V	18.35	20.00	01.25	OL-R&Bph	Big tree fallen on lines at Bansilalpet	-----
1	Hyd South	Panjasha	Panjasha	11KV	III	13.25	14.40	01.15	EL	2No. DTR's fault at Panjasha	-----
2		Malakpet	Komatiwadi	11KV	VIII	21.25	22.42	01.17	EL	HT Line snapped at inside MCH Office & Opp: Metro Rail Office	Arranged B/F on 11KV Noorkhan Bazar & 11KV Bibi Ka Alawa feeders
3		E.N.T	Rang Mahal	11KV	IX	18.00	19.40	01.40	EL,OL-Bph	DTR fault at Gujarathi Galli	-----
4		Seetharambagh	Dhoolpet OH	11KV	IX	18.00	19.15	01.15	OL-Rph	Pin Insulator flash over at Dood Khana	-----

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Kothapally	33kv	Mahabubnagar	18.10	18.20	00.10		Due to Heavy Wind & Rain	Kothapally	-
2		Maddur	Mogalmadka	33kv	Mahabubnagar	15.30	17.30	02.00		Due to Heavy Wind & Rain	Mogalmadka	-
3		Makthal	Narwa	33kv	Mahabubnagar	17.20	21.20	04.00	O/L	Due to Heavy Wind & Jumpers Opened at Manthan Goud	Narwa	-
4		Makthal	Krishna	33kv	Mahabubnagar	18.10	00.00	05.50	O/L	Not Rectified	Krishna	-
5		Wanaparthy	Revally	33kv	Wanaparthy	06.40	09.45	03.05		Conductor Snapped at 4Locations	Revally	-
6		Kalwakurthy	Polkampally	33kv	Jadcherla	00.00	06.25	06.25	E/L	Tree Branches Fallen on the Line	Polkampally	-
7		Achampet	Uppununthala	33kv	Nagarkurnool	03.10	05.05	01.55	E/L	Heavy Wind & Rain	Uppununthala	-
1	NLG	Bibinagar	Bollepally	33kv	Bhongir	18.00	22.30	04.30	E/L	33KV CT Blast 132 KV Bibinagar	Bollepally	
2	NLG	Mothkur	Azeempet	33kv	Bhongir	19.20	23.55	03.03	E/L	Tree Branches Fallen On Line	Azeempet	
3	NLG	Choutuppal	Jaikesaram	33kv	Choutuppal	18.15	11.35	17.20	E/L	7 Insulator failed , Alaternatesuply Given	Jaikesaram	
4	NLG	Aitipamula	Aitipamula	33kv	Nalgonda	18.30	20.20	01.50	E/L	Heavy Gale and wind	Aitipamula	
5	NLG	Aitipamula	Kethepally	33kv	Nalgonda	18.30	08.40	14.10	E/L	Tree fallen on 11KV line	Kethepally	
6	NLG	Nalgonda	Pajjur	33kv	Nalgonda	18.30	11.10	16.40	E/L	Heavy Gale and wind	Pajjur	
7	NLG	Nalgonda	Mamillagudem	33kv	Nalgonda	18.30	11.20	16.50	E/L	Heavy Gale and wind	Mamillagudem	
8	NLG	Nalgonda	Cheekatimamidi	33kv	Nalgonda	18.30	22.00	03.30	E/L	Heavy Gale and wind	Cheekatimamidi	
9	NLG	Nalgonda	Gudapoor	33kv	Nalgonda	18.30	08.30	14.00	E/L	Heavy Gale and wind	Gudapoor	
10	NLG	Ramannapet	Chityala (Nerada)	33kv	Nalgonda	18.30	22.00	03.30	E/L	Tree cutting work in progress, tobe cleared	Chityala (Nerada)	
11	NLG	Yerrabelly	Mushampally	33kv	Nalgonda	18.30	02.30	08.00	E/L	Heavy Gale and wind	Mushampally	
12	NLG	K.M.Pally	Chinthapally	33kv	Devarakonda	20.15	14.30	16.15	E/L	33kv line Problem	Chinthapally	
13	NLG	K.M.Pally	Nampally	33kv	Devarakonda	21.23	14.30	15.00	E/L	33kv line Problem	Nampally	
14	NLG	K.M.Pally	Gurrampode	33kv	Devarakonda	22.15	10.00	12.15	E/L	33 insulator Fail	Gurrampode	
15	NLG	Kandukur	Chandhampeta	33kv	Devarakonda	15.40	14.00	22.20	E/L	33kv line Problem	Chandhampeta	
16	NLG	Kandukur	Yerraram	33kv	Devarakonda	15.45	10.00	18.15	E/L	33kv line Problem	Yerraram	
17	NLG	Dirincherla	Garidepally	33kv	Huzurnagar	20.40	14.10	17.30	E/L	33kv pin binding cut at Garidepally (v)	Garidepally	
18	NLG	Ramapuram	Mellacheruvu	33kv	Huzurnagar	19.35	15.15	19.50	E/L	33kv inslater failed at Mellacheruvu (v)	Mellacheruvu	
19	NLG	Kodad	Akupamula	33kv	Huzurnagar	19.00	11.15	16.15	E/L	33KV line Tree follen at Akupamula (v)	Akupamula	
20	NLG	Mattampally	Huzurnagar	33kv	Huzurnagar	19.02	10.36	15.28	E/L	Heavy Rain Problem	Huzurnagar	
21	NLG	Suryapet	Nuthankal	33kv	Suryapet	21.40	07.30	09.50	E/L	Insulator falshover and Tree fallen on the line	Nuthankal	
22	NLG	Suryapet	Chivemla	33kv	Suryapet	21.20	06.30	09.10	E/L	Insulator falshover and Tree fallen on the line, Line Melt & Pole leaning	Chivemla	
23	NLG	Suryapet	Nemmikal	33kv	Suryapet	20.45	14.30	16.45	E/L	33KV Nemmikal Feeder VCB 2No.s Limbs blosted and 1No.CT Blost	Nemmikal	
24	NLG	Thungathurty	Ravulapally	33kv	Suryapet	20.50	15.20	17.30	E/L	Conductor snapped & Tree branches fallen on the line & Jumper Replacement	Ravulapally	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
25	NLG	Thungathurty	Annaram	33kv	Suryapet	20.40	06.10	09.30	E/L	Jumpers Replacemetns and Insulator flashover & Pole damaged	Annaram	
26	NLG	Thungathurty	Phanigiri	33kv	Suryapet	21.20	06.40	09.00	E/L	Tree fallen on the line and conductor snapped	Phanigiri	
27	NLG	Miryalaguda	Miryalaguad Town	33kv	Miryalaguda	18.34	00.40	06.06	E/L	Jumpers opened at two places	Miryalaguad Town	
28	NLG	Miryalaguda	Avathipuram	33kv	Miryalaguda	18.30	00.30	06.00	E/L	33Kvline cut felt on cross arm at pole No, 112	Avathipuram	
29	NLG	Miryalaguda	Huzurnagar	33kv	Miryalaguda	18.30	23.45	05.15	E/L	33 KV Jumper cut near Gudur village	Huzurnagar	
30	NLG	Miryalaguda	V.Kpalem	33kv	Miryalaguda	18.00	00.30	06.30	E/L	AB swith opened at V.K.Palem SS i.e., t	V.Kpalem	
31	NLG	Miryalaguda	V.Kpalem	33kv	Miryalaguda	18.00	15.00	21.00	E/L		V.Kpalem	
32	NLG	Miryalaguda	Kannekal (old)	33kv	Miryalaguda	18.00	09.00	15.00	E/L	Tree branches fallen	Kannekal (old)	
33	NLG	Miryalaguda	Matoor	33kv	Miryalaguda	18.00	21.00	03.00	E/L	Jumpers opened towards Thimmapuram SS	Matoor	
34	NLG	Miryalaguda	Matoor	33kv	Miryalaguda	18.00	09.00	15.00	E/L	Jumpers Cut near Thimmapuram SS	Matoor	
35	NLG	Madgulapally	B.B.Gudem	33kv	Miryalaguda	18.10	11.20	17.10	E/L	33KV jumpers cut and felt on cross arm	B.B.Gudem	
36	NLG	Madgulapally	Agamothkur	33kv	Miryalaguda	20.20	12.45	16.25	E/L	33 KV pin insulator failed	Agamothkur	
37	NLG	Madgulapally	Thadakamalla	33kv	Miryalaguda	19.55	22.00	02.05	E/L		Thadakamalla	
38	NLG	Madgulapally	Visaka Indl	33kv	Miryalaguda	18.15	19.10	00.55	E/L	Tree branches fallen	Visaka Indl	
39	NLG	Madgulapally	Visaka Solar	33kv	Miryalaguda	18.15	14.15	19.30	E/L	Tree branches fallen	Visaka Solar	
40	NLG	Yerrabelly	Kannekal	33kv	Miryalaguda	20.30	22.25	01.55	E/L	Jumpers opened towards K.R.Gudem SS	Kannekal	
41	NLG	Yerrabelly	Kannekal	33kv	Miryalaguda	20.30	11.30	15.00	E/L	Tree branches fallen	Kannekal	
42	NLG	Haliya	Yacharam	33kv	Miryalaguda	20.30	15.45	19.15	E/L	Tree branches fallen	Yacharam	
43	NLG	Haliya	Rajavaram	33kv	Miryalaguda	23.30	06.15	06.45	E/L	Movementry fault and not charged	Rajavaram	
1	Siddipet	Siddipet	Palamakula	33kv	Baddipadaga	09.00	10.00	01.00		Insulator Damaged	Palamakula	-
2		Siddipet	Siddipet	33kv	Rampur	01.00	12.00	12.00		Due to Rian	Siddipet	-
1	RR N	132KV Medchal	33KV Kompally	33kv	Medchal	18.01	19.20	01.19	BD	No fault	33KV Kompally	-
1	HYD N	132KV I.D.P.L	I.D.P.L - II (Pragatools, Malhotra, Tecumsha - HT Services)	33kv	Bowenpally	10.24	10.37	00.13	EL,OL-Bph	Cable damaged at Opp: 33KV Pragatools SS	I.D.P.L - II (Pragatools, Malhotra, Tecumsha - HT Services)	Loads transferred onto 132KV I.D.P.L SS
2	HYD S	220KV Ch' Gutta - Santosh Nagar Ckt-I	Yakuthpura	33kv	Charminar	12.35	12.45	00.10	EL	Cable damaged by Master Plan on 33KV Madannapet near Line	Yakuthpura	Loads transferred onto 132KV Imlibun SS