

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550		4		4		4			
6	RR(E)	168	403		5		5		5			
7	Hyd	194	1044		1		1		1			
	Total	606	3055	0	10	0	10	0	10	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		8		8		8			
3	MDK	107	933	3		3		3				
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	4	8	4	8	4	8	0	0	
	Grand Total	1082	6468	4	18	4	18	4	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Kothagudem	11KV	Suryapet	08.20	10.56	02.36	EL	Jumper cut	-
2		Athmakur (S)	Dacharam	11KV	Suryapet	06.50	09.20	02.30	EL	Line melt	-
3		Dirsenpally	Alugunur	11KV	Suryapet	14.50	17.00	02.10	EL	Insulator Flashover	-
4		Kondamadugu	Kepal	11KV	Bhongiri	06.40	09.20	02.40	EL	Jumper cut	-
5		Mukundapuram	Mukundapuram	11KV	Huzurnagar	12.21	14.19	01.58	EL	11 KV Snapped	-
6		Keethavarigudem	Rainigudem	11KV	Huzurnagar	09.20	11.54	02.34	EL	Jumper cut	-
7		Avanthipuram	Avanthipuram	11KV	Miryalaguda	07.30	09.00	01.30	EL	11 KV Conductor Snapped	-
8		Yacharam	Annaram	11KV	Miryalaguda	08.00	09.30	01.30	EL	11 KV Pin Insulator failure	-
1	RR N	Jeedimetla ss V	Rudralaya	11KV	Jeedimetla	19.25	21.05	01.40	EL/OL	11 kv Line snaped at Opp Reddy lab	-
2		Shameerpet	Anthaipally	11KV	Medchal	17.05	19.20	02.15	BD	11KV Conductor Snapped at Vital reddy Bavi,Athaipally Village	-
3		Keshavaram	Keshavaram	11KV	Medchal	17.45	19.00	01.15	BD	11KV Disc failed at Keshavaram Village	-
4		DP Pally	Gagillapur	11KV	Jeedimetla	05.30	07.00	01.30	BD	11kv insulator failure at Dundigal	-
1	RR E	Cherlapally-IV	Dainatech	11KV	Sainikpuri	15.22	18.22	03.00		Copper Patti cut on Stey Wire Tued at Bagya Laxmi Compony due to Heavy Rain (LM Kashiram)	-
2		Cherlapally-IV	Polimer Industry	11KV	Sainikpuri	15.25	17.50	02.25		11Kv line cut at Rama Painting Ragavendra Hotel due to Heavy Rain (LM Kashiram)	-
3		NN Colony	Vasavishiva Nagar	11KV	Sainikpuri	15.10	16.10	01.00		Tree fallen on 11Kv line at Vasavishiva Nagar (LM Narsinga Rao)	-
4		Balaji nagar	Mahankali	11KV	Keesara	15.02	15.32	00.30		11kv line twisted at Govt school mahankali nagar	-
5		Nagaram	P.S rao nagar	11KV	Keesara	15.12	16.18	01.06		coconut tree fallen on 11kvl ine at P.S rao nagar shashank enclave	-
1	HYD S	Salarjung	Abid Ali Eye Hospital	11KV	VIII	16.05	17.35	01.30	All Indication	Twisted Lines near SS (Delay due to double circuit line)	Arranged B/F on 11KV Chaderghat fdr

TSSPDCL - LMRC / Corporate office

Date: 03.04.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Mahabubnagar	18.10	10.40	16.30	O/L	for Due to Heavy Wind & Rain, Tree Follen on the Line and Disc Failed & Pin Insulater Damaged Near Roadam Street	Krishna	-
1	MDK	Pashamailaram	Manjeera	33KV	Sangareddy	10.35	11.45	01.10		B/D due to Jumper cut	Manjeera	-
2		Gummadidala	Gummadidala	33KV	Sangareddy	08.25	10.25	02.00		B/D due to Tree branches fallen on the line	Gummadidala	-
3		Gummadidala	GPSS-II	33KV	Sangareddy	09.45	11.20	01.35		B/d due to Insulator failure.	GPSS-II	-