

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550		1		1		1			
6	RR(E)	168	403		1		1		1			
7	Hyd	194	1044	1		1		1				
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		10		10		10			
3	MDK	107	933		4		4		4			
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	1	16	1	16	1	16	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Annaram	Sangem	11KV	Suryapet	7:30	9:10	1:40	EL	Tree branch fallen on the line	No
2		Nereda	Nereda AGL	11KV	Nalgonda	07.45	12.25	04.40	E/L	Tree branch fallen on the line	No
3		Baironibanda	N.G.Kothapally	11KV	Nalgonda	10.00	12.05	02.05	E/L	Insulator failed	No
4		Thurkapally	M.Gouraram	11KV	Nalgonda	11.02	17.20	06.18	E/L	Jumper Cut	No
5		Teededu	Teededu	11KV	Devarakonda	12.30	15.00	02.30	E/L	Jumper cut	No
6		Chandhampet	Gajilapuram	11KV	Devarakonda	19.30	05.00	09.30	E/L	1 Ph DTR failed	No
7		Ghanapuram	G.B.Pally	11KV	Devarakonda	07.00	10.30	03.30	E/L	Conductor Snapped	No
8		Angadipeta	P.a.pally Rural	11KV	Devarakonda	21.00	13.00	08.00	E/L	Conductor Snapped	No
9		Gondiryala	Chimiryala	11KV	Huzurnagar	20.00	00.00	04.00	EL	11KV Line snapped at Chimiryala village	No
10		Chanuapally	Tripuraram	11KV	Huzurnagar	2:20	9:00	6:40	EL	Conductor Snapped	No
1	MDK	Chitkul	Chitkul	11KV	Medak	10:00	11:00	1:00		Insulator failed	No
2		Gaddipeddapur	Gaddipeddapur	11KV	Medak	09.00	14.00	05.00		Jumper cut	No
3		Ramojeepally	Ramojeepally	11KV	Medak	11.05	12.58	01.53		Insulator failed	No
1	SDPT	Thotapally	Anthakkapet	11KV	Husnabad	19.00	21.00	02.00		Insulator failed	No
1	RR N	Suraram	Sri Ram nagar	11KV	Jeedimetla	17:45	19:02	1:17		Iron rod fallen on the 11KV Line At sriram nagar	No
1	RR E	Balaji Nagar	Dental College	11KV	Keesara	15:40	16:20	0:40		Bird fallen on 11KV line near Dumping Yard	No

TSSPDCL - LMRC / Corporate office

Date: 10.04.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Gunrock	Airport (Tirumalagiri)	33KV	Nehru Ngr	20.10	20.15	00.05	EL	Cable Joint failed	Airport (Tirumalagiri)	Loads transferred onto 132KV Gunrock SS via 33KV Macha Bollaram SS