

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234	1	2	1	2	1	2			
5	RR(N)	54	550		3		3		3			
6	RR(E)	168	403									
7	Hyd	194	1044		6		6		6			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933	2	4	2	4	2	4			
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>19</b>	<b>4</b>	<b>19</b>	<b>4</b>	<b>19</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 24.04.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Kankurthy	33KV	Narayanapet	12.55	14.30	01.35	OL	No visible fault due to Heavy Gail	Kankurthy	Alternate Supply Arranged from Mogalmdaka
1	MDK	Pashamailaram	Manjeera	33KV	Sangareddy	03.26	08.15	04.49		B/D Due to Insulator Failure near ring road	Manjeera	-
2		Gummadidala	GPSS-1	33KV	Sangareddy	23.10	02.15	03.05		B/D Due to Jumper Cut	GPSS-1	-
1	RR S	RC Puram	Giridar Ispat	33KV	IBGH	11.45	17.30	05.45		33 KV Disk Fail at Thellapur	Giridar Ispat	-