

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234		2		2		2			
5	RR(N)	54	550									
6	RR(E)	168	403									
7	Hyd	194	1044		2		2		2			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988	1	18	1	18	1	18			
3	MDK	107	933									
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	2	21	2	21	2	21	0	0	
	Grand Total	1082	6468	2	25	2	25	2	25	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.04.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Narayanpet	Narayanpet Rural	11KV	Mahabubnagar	15.00	18.00	03.00		11 KV breaker and relay Problem in Substation	-
2		Karkonda	Khanapur	11KV	Jadcherla	12.20	14.40	02.20		11kv Jumper cut near Khanapur	-
3		Kothamolgara	Kothamolgara	11KV	Jadcherla	10.00	12.00	02.00		11kv Jumper cut near Kappeta	-
1	NLG	Dirsenapally	Dirsenapally	11KV	Suryapet	06.25	08.05	01.40	E/L	SS-1 11Kv Disk Failure	-
2		Veliminedu	Veliminedu	11KV	Nalgonda	05.00	15.00	10.00	E/L	Poles Damaged Due to Heavy Gale and Wind	
3		Veliminedu	Corramandal	11KV	Nalgonda	03.15	11.00	07.45	E/L	Heavy Gale and Wind 11 KV Jumper Cut and Tree Branches Fallen on the line	
4		Veliminedu	K.R.Palimers	11KV	Nalgonda	03.15	11.00	07.45	E/L & O/L	Heavy Gale and Wind 11 KV Jumper Cut and Tree Branches Fallen on the line	
5		Veliminedu	Perapally	11KV	Nalgonda	03.15	12.30	09.15	E/L	Poles Damaged Due to Heavy Gale and Wind	
6		Veliminedu	Pittampally	11KV	Nalgonda	03.15	15.30	12.15	E/L & O/L	Poles Damaged Due to Heavy Gale and Wind	
7		Veliminedu	Gundrampally	11KV	Nalgonda	03.15	16.00	12.45	E/L & O/L	Poles Damaged Due to Heavy Gale and Wind	
8		Gundrampally	Gundrampally	11KV	Nalgonda	03.15	16.30	13.15	E/L	Poles Damaged Due to Heavy Gale and Wind	
9		Gundrampally	Apoor	11KV	Nalgonda	03.15	15.00	11.45	E/L	Poles Damaged Due to Heavy Gale and Wind	
10		Gundrampally	Toolget	11KV	Nalgonda	03.15	11.00	07.45	E/L	Poles Damaged Due to Heavy Gale and Wind	
11		Aregudem	Aregudam	11KV	Nalgonda	03.15	16.00	12.45	E/L & O/L	Poles Damaged Due to Heavy Gale and Wind	
12		Aregudem	Chinna Kaparathi	11KV	Nalgonda	03.15	15.00	11.45	E/L	Poles Damaged Due to Heavy Gale and Wind	
13		Aregudem	Pedda Kaaparathi	11KV	Nalgonda	03.15	15.30	12.15	E/L & O/L	Poles Damaged Due to Heavy Gale and Wind	
14		Aregudem	Chityala AGL	11KV	Nalgonda	03.15	14.00	10.45	E/L & O/L	Poles Damaged Due to Heavy Gale and Wind	
15		Bollepally	Jampally	11KV	Bhongir	09.00	11.00	02.00	E/L	11Kv Insulator failed at P.B Thanda Ramesh Artisan 8247205892	-
16		Golanpally	Nemilikalwa	11KV	Choutuppal	13.50	15.35	01.45	E/L	HT/LT	-
17		Jublakpally	Kanmukula	11KV	Choutuppal	19.35	06.35	11.00	E/L	11KV Poles 2 Broken at Near 33/11KV SS Jublakpally	-
18		Choutuppal	Lingojigudem	11KV	Choutuppal	00.00	10.10	10.10	E/L	11Kv Insulator failed At SC Colony & Poles Damaged	-
1	RR S	Papireddy colony	Dubey colony	11KV	Gachibowli	10.20	11.30	01.10		Tree fallen on the 11kv line at Coffeeday shop, Dubey colony	-
2		Chanda Nagar	Tara Nagar	11KV	Gachibowli	18.30	19.40	01.10		11kv Disk failed at Shivaji Nagar	-
1	HYD C	A.C.Guards	Shanthi Nagar	11KV	Saifabad	09.30	10.40	01.10	All Indication	Cable End Kit fault	Arranged B/F on 11KV Vijay Nagar Colony feeder
2	HYD S	C.R.P.F	Omar Colony	11KV	Charminar	19.00	20.50	01.50	EL,OL	Cable fault at Bismillah Dairy Form	Partial fdr charged and Arranged B/F on 11KV Baba Nagar feeder

TSSPDCL - LMRC / Corporate office

Date: 30.04.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Ravelly	33KV	Wanaparthy	06.55	08.05	01.10	E/L&O/L	Back Feeding Supply Taken to 33KV Peddakothapally Feeder in 132KV SS Nagarkurnool	Ravelly	-
1	NLG	Ramannapeta	Velminedu	33KV	Nalgonda	18.05 (29.04.18)	3.15 (30.04.18)	09.10		2 Nos. 33 KV Poles Damaged & trees fallen on the line	Velminedu, Aregudem, Gundrampally	Alternate Supply taken from 33 KV Chityala and 33 KV Panthangi Feeders on 30.04.2018 at 3:15 Hrs Morning