

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	1	12	1	12	1	12	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988		7		7		7			
3	MDK	107	933		5		5		5			
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	21	2	21	2	21	0	0	
	Grand Total	1082	6468	3	33	3	33	3	33	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Bijwararam	33KV	Gadwal	11.58	18.50	06.52	E/L&O/L	Pin Binding Work near Old Gadwal SS and Pin Binding Failure near Sangala Charu Village	Gadwal	No
2		Gadwal	Gadwal	33KV	Maldakal	20.10	01.20	05.10	E/L	for Pin Insulater Replacement at Buddipad	Gadwal	No
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	08.24	18.58	10.34		CT Stud Jumper cut and Lighting arrester Failed at 132KV Medchal SS		-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Moosapet	11KV	Jadcherla	08.30	10.05	01.35		11 Kv Jumper Cut Near Chakrapur(VI).	-
2		Tirumalapur	Khanapur	11KV	Jadcherla	06.48	10.07	03.17		11KV Insulator Failure Near narsampally TandaSide.	-
1	NLG	Kandagatla	Thimmapuram	11KV	Suryapeta	05.00	07.20	02.20	E/L	Jumper cut	-
2		Chandupatla	Cheemalakoduru	11KV	Bhongiri	13.35	14.50	01.15	E/L	Insulator failure	-
3		Pamanagundla	Ismailpally	11KV	Nalgonda	13.00	14.10	01.10	E/L	11KV Line Insulator failed	-
4		Koppole(K)	Bheemaram	11KV	Nalgonda	10.50	12.00	01.10	E/L	11KV Line Cut	-
5		Seethyathanda	Seethyathanda	11KV	Miryalaguda	05.00	08.00	03.00	E/L	Jumper cut	-
6		Dilshincherla	Somaram	11KV	Huzurnagar	05.00	07.30	02.30	E/L	Jumper cut	-
7		Palakeedu	Bonthalapalem	11KV	Huzurnagar	04.00	06.30	02.30	E/L	11KV Line Snapped	-
1	MDK	Kondapur	Gangaram	11KV	Sangareddy	22.00	05.30	07.30		B/D Due to tree fallen on the line	-
2		Gollapally	Munidevunipally	11KV	Sangareddy	04.00	06.00	02.00		B/D Due to Jumper Cut	-
3		Gummadidala	Gummadidala	11KV	Sangareddy	09.30	10.45	01.15		B/D Due to Conductor Snapped	-
4		Bollaram - II	Vasagatta	11KV	Sangareddy	13.40	17.40	04.00		B/D Due to Jumper Cut	-
5		Thogita	Kuchanpally	11KV	Medak	00.00	06.05	06.05		B/D Due to Jumper Cut	-
1	SDPT	Komaticheruvu	Srinagar Colony	11KV	Siddipet	20.05	20.35	00.30		B/D - Insulator fail	
2		BEJJANKI	KALLEPALLI	11KV	Siddipet	00.00	11.30	11.30		Due to Insulator failure	
3		BEJJANKI	MUTHANNAPETA	11KV	Siddipet	00.00	10.30	10.30		Due to line snapped same rectifaied	
4		SHANIGARAM	THANGALLAPALLI	11KV	Siddipet	18.00	23.25	05.25		1-PSH OK 3-PSH BREAK DOWN	
5		MUSTHYAL	CHUNCHANAKOTA	11KV	Siddipet	03.30	14.10	10.40		Due to Disk failure same rectifaied	
6		MUSTHYAL	CHERIAL AGL	11KV	Siddipet	14.25	17.30	03.05		Due to line snapped same rectifaied	
7		GAGILLAPUR	GAGILLAPUR	11KV	Siddipet	01.00	07.00	06.00		Due to line snapped same rectifaied	
1	RR S	L&T	URDU University	11KV	Gachibowli	10.43	11.45	01.02		11KV Insulator Failure near 25 KVA T/F at Bank of Baroda.	-
2		Gachibowli	Kalajyothy	11KV	Gachibowli	07.25	09.20	01.55		11KV Disk Failed near SBI Bank at Maseed Banda.	-
1	RR N	Kistapur	IDA Hanuman	11KV	Medchal	10.00	10.55	00.55		Tree Branches fallen on the 11KV Line at Ravalkole Common	-
1	RR E	Mallapur	Noma	11KV	Habsiguda	00.05	02.20	02.15		11kv Pin insulaotr fail at Fci gowdham	-
2		Nacharam Indore	Surana	11KV	Habsiguda	23.30	01.05	01.35		11KV Pin Insulaotr failed near Hyundai Show Room	-
3		Moula-Ali	Spectra	11KV	Sainikpuri	23.31	01.17	01.46		11Kv Pin Insuletor at IDA Moula-Ali (Artisan /Kristofer)	-
4		Moula-Ali	HCL	11KV	Sainikpuri	23.36	00.54	01.18		11Kv Pin Insuletor at IDA Mangapuram (Artisan /Kristofer)	-
5		Vinayak Nagar	Tankbund	11KV	Sainikpuri	04.35	05.10	00.35		11Kv Disk failure at Safilguda Chourastha (AE/OP)	-
6		CRPF	CRPF Residential	11KV	Keesara	07.05	08.30	01.25		11KV Pin Insulaotr failed at CRPF Campus	-
1	HYD S	Devi Bagh	Rama Talkies	11KV	Charminar	00.30	01.55	01.25	EL	Conductor snapped at Rama Talkies	-
2		Malakpet	Noorkhan Bazar	11KV	Asmangadh	01.35	03.12	01.37	EL	Cable fault at Noorkhan Bazar	Arranged B/F on 11KV Komatiwadi fdr
3		Devi Bagh	Kamela	11KV	Charminar	09.34	11.25	01.51	EL	Breaker fault at SS & Bird fault at Kamela	Arranged B/F on 11KV I.T.I fdr