

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	10	2	10	2	10	0	0	
	Grand Total	1082	6468	2	13	2	13	2	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.08.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Mogalmadka	33KV	Mahabubnagar	17.00	20.50	03.50	E/L&O/L	Due to Heavy Gale & Wind Rain	Mogalmadka	Alternate Supply Arrange from 33KV Kankurthy feeder at 17:20Hrs
2		Alampur	Shanthinagar-I	33KV	Gadwal	14.20	15.50	01.30	E/L&O/L	AB Switch open at Ramapuram SS and Isolator Open & Close at Julapally stage	Shanthinagar-I	No

TSSPDCL - LMRC / Corporate office

Date: 04.08.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Gangapur	11KV	Jadcherla	04.00	07.40	03.40		11KV Wire cut near Gangapur	No
1	NLG	Rajapet	Pamkunta	11KV	Bhongir	11:20	16:00	4:40	E/L	11Kv line snapped & pin Insuloter failed near Gandamla (v)	No
2		Jalalpuram	Marri kunta thanda	11KV	Suryapet	11.40	14.20	02.40	E/L	11Kv Conductor snapped	No
3		Keethavarigudem	Velidanda	11KV	Huzurnagar	03.05	06.30	03.20	E/L	11Kv Line snapped at Velidanda (v)	No
4		Ananthagiri	Mogalaikota	11KV	Huzurnagar	03.15	06.15	03.00	E/L	11kv disk failed at Mogalaikota (v)	No
5		Ananthagiri	Ameenabad	11KV	Huzurnagar	13.50	16.10	02.20	E/L	11kv jumper cut at ameenabad (v)	No
6		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	08.00	11.40	03.40	E/L	11KV insulator failed at SS-2	No
7		Madgulapally	Kukkadam	11KV	Nalgonda	05.00	07.40	02.40	E/L	11KV jumper cut near by village	No
8		Pamanagundla	Yerasanigudem	11KV	Nalgonda	10.00	13.00	03.00	E/L	AB switch female cut at SS-5 and lines touched	No
9		Marriguda	Vatipally	11KV	Devarakonda	13:35	14:30	0:55	E/L	AB Switch Problem	No
1	RR N	Jagathgiringutta	Maqdoom Nagar	11KV	Medchal	0:40	1:50	1:10		11KV Cable failed at Corporater Office	No
2		Kompally	Jaibheri	11KV	Medchal	10.50	11.20	00.30		11KV Jumper Replaced at Nagarjuna Homes	No
1	HYD S	Falaknuma	Jangamett OH	11KV	Charminar	14.50	16.34	01.44	EL,OL-Rph	3way RMU Cable fault near Seven Temple	Arranged B/F on 11KV Sharda College fdr