

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		3		3		3			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 06.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Edulur	Munukuntla	11KV	Nalgonda	11.30	13.00	01.30	E/L	11KV Line cut	-
2		Madgulapally	Kukadam	11KV	Nalgonda	09.45	11.00	01.15	E/L	11KV Line jumper cut	-
3		Penpahad	Anajipuram	11KV	Suryapet	03.45	07.30	03.45	E/L	Insulator failed	-
1	MDK	Inole	Indresham	11KV	Patancheru	12.03	13.03	01.00		BD due to Conductor snapped	-
2	SDPT	Katkur	Ramavaram & Mallaram	11KV	SDPT	07.00	10.30	03.30		JUMPER CUT	-
3		Guruvannapet	Guruvannapet	11KV		16.20	18.30	02.10		HT/LT SHORT	-
4		Guruvannapet	Posanpally	11KV		16.20	23.50			1PH OK,3PH BD	-
5		Komuravelly	Kistampet	11KV		10.15	15.00	04.45		11KV CONDUCTOR SNAPPED	-
6		Komuravelly	Inapur + Posanpally + Inapur 24 Hrs	11KV		14.10	16.10	02.00		JUMPER CUT	-
7		Rebarthy	Rebarthy	11KV		03.05	06.00	02.55		11KV INSULATOR FAILURE	-

## TSSPDCL - LMRC / Corporate office

Date: 06.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanthinagar 1	33KV	Gadwal	16.30	17.20	00.50	EL	Tree branches follen on the line	Shanthinagar 1	-
2		Amangal	Polepally	33KV	Shadnagar	16.05	18.05	02.00	OL	No Visible fault Supply stude OK	Polepally	-
1	MDK	Narayankhed	Poosalpad	33KV	Jogipet	10.45	14.55	04.10		BD due to Pin Insulator failed	Poosalpad	-