

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933									
4	SDPT			1	4	1	4	1	4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	2	16	2	16	2	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Miryalguda	Matoor	33KV	Miryalguda	17.15	19.20	02.05	E/L	33KV Jumper cut near 220KV SS	Matoor, B.Annaram & Thimmapuram	-
1	Siddipet	Husnabad	Koheda	33KV	Husnabad	14.15	18.20	04.05		Tree branches fallen on the line	Koheda	-

TSSPDCL - LMRC / Corporate office

Date: 07.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Burgupally	11KV	Jadcherla	09.00	13.00	04.00		11KV Jumper cut Near Aloor thanda	-
2		Kuchoor	Kuchoor	11KV	Jadcherla	14.30	16.00	01.30		11KV Phase to Phase Near Karoor(V)	-
1	NLG	Penpahad	Potlapahad	11KV	Surypet	12.02	13.50	01.48	E/L	11Kv Jumper cut	-
2		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	10.36	12.50	02.14	E/L	11kv insulator failure	-
3		Kalmalcheruvu	Kalmalchervu	11KV	Huzurnagar	14.37	17.38	03.01	E/L	11Kv line snapped	-
4		Nadigudem	Brundavanapuram	11KV	Huzurnagar	18.50	21.00	02.10	E/L	Tree branch fall on 11kv line	-
5		Nadigudem	Ramapuram	11KV	Huzurnagar	02.00	05.30	03.30	E/L	11kv insulator failure	-
6		B.Ramaram	Saiteja	11KV	Bhongir	05.00	07.40	02.40	E/L	Arrakunta carcile near Line ABSwich Disc Failed	-
7		Ragnathpur	Chalur	11KV	Bhongir	09.40	13.40	04.00	E/L	Tree Branches fallen in line near Guraipally (V)	-
1	Siddipet	THOTAPALLY	GANDHINAGAR AGL	11KV	Siddipet	00.00	10.00	10.00		Due to Insulator failed	-
2		BEJJANKI	MUTHANNAPET	11KV	Siddipet	00.00	09.00	09.00		Tree branches fallen	-
3		BEKKAL	THORNALA	11KV	Siddipet	07.30	10.00	02.30		Tree branches fallen	-
4		BEKKAL	BAIRANPALLY	11KV	Siddipet	11.50	14.40	02.50		Tree branches fallen	-
1	RR N	Dulapally	Steel City	11KV	Medchal	06.28	07.30	01.02	BD	Material fallen on the 11KV Line at Raju Water Pump	-
1	RR E	Keesara	Bogarm	11KV	Keesara	12.40	15.50	03.10		AGL T/F Belt putti cut & twisted to AB swith at SC colony	-
1	HYD S	Gosha Mahal	Hindi Nagar	11KV	IX	04.00	05.10	01.10	EL,OL-Yph	Cable fault at Police Quarters	-