

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		4		4		4			
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		16		16		16			
	Total	606	3055	0	22	0	22	0	22	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		7		7		7			
3	MDK	107	933		2		2		2			
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	17	1	17	1	17	0	0	
	Grand Total	1082	6468	1	39	1	39	1	39	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthu	Solipur	33KV	Wanaparthu	08.30	09.25	00.55	E/L&O/L	AB Swtich open at Chinnamandadi SS	Wanaparthu	No

TSSPDCL - LMRC / Corporate office

Date: 09.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Sri ram thanda	11KV	Suryapeta	10.50	13.00	02.10	E/L	Insulator failure	-
2		Alingapuram	Gundlapahad	11KV	Huzurnagar	03.15	06.30	03.15	E/L	11KV Line Snapped	-
3		Garidepally	Ponugodu	11KV	Huzurnagar	03.45	06.00	02.45	E/L	11KV Line Snapped	-
4		Pamanagundla	Pittampally	11KV	Nalgonda	09.50	11.40	01.50	E/L	11KV Line cut	-
5		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	08.40	12.50	04.10	E/L	Insulator failure	-
6		Cheruvupally	Thungathurthy	11KV	Nalgonda	07.00	09.20	02.20	E/L	11KV Line cut	-
7		Muahampally	Muthyalamma	11KV	Nalgonda	08.00	09.20	01.20	E/L	11KV Line Insulator failure	-
1	MDK	Narsapur	Narayanapur	11KV	Medak	04.00	09.40	05.40		B/D Due to tree branches fallen on the line	-
2		Narsapur	Avancha	11KV	Medak	05.00	07.35	02.35		B/D Due to Jumper Cut	-
3		Irkode	Irkode	11KV	Siddipet	06.10	08.30	02.20		B/D (Tree branches fall on the line)	-
4		Raghavapur	Raorukula	11KV	Siddipet	06.15	07.05	00.50		B/D (Tree branches fall on the line)	-
5		Pullur	Pullur	11KV	Siddipet	15.15	18.40	03.25		B/D (Tree Braches Fall on the 11KV line)	-
6		Pedda Cheekode	Kamarpally	11KV	Siddipet	04.45	09.15	04.30		B/D (Insuletat fail)	-
7		Pothareddypet	Rameshampally	11KV	Siddipet	02.00	09.04	07.04		B/D (Tree Braches Fall on the 11KV line)	-
8		Narsapur	Lingareddypally	11KV	Siddipet	05.40	06.40	01.00		B/D (Pole damage)	-
9		Husnabad	Madtha	11KV	Siddipet	03.20	09.10	05.50		JUMPER BREAK SAME REPLACED	-
10		Koheda	Thegalaguntapalli	11KV	Siddipet	01.30	11.04	09.34		LINE SNAPPED SAME RECTIFAIED	-
1	RR S	Chandanagar	Engineers Enclave	11KV	GCB	14.45	15.45	01.00		11kv Pin- Insulator failed at Huda colony, old police station	-
2		L & T	PJR Nagar	11KV	GCB	14.55	16.25	01.30		Overhead End kit failed Near MLC house, Telecom nagar	-
3		Gaganphad	NPA	11KV	Rajendra Nagar	03.43	05.08	01.25	BD	11KV Pin insulator failed at Gaganphad Railway Gate.	-
4		NPA	Raghavendra Colony	11KV	Rajendra Nagar	17.40	20.50	03.10	BD	No Visuable fault	-
1	RR E	IICT	Snehapuri	11KV	Habsiguda	18.28	19.58	01.30		Insulaotr fail at Snehapuri colony	-
2		Narapally	P.Singaram	11KV	Keesara	04.25	05.15	00.50		Pin Insulaotr fail at OU colony chawdariguda	-
1	HYD N	Nehru Nagar	Hari Hara Kala Bhavan	11KV	Sec-Bad	21.40	23.05	01.25	EL	Faulty DTR at Hari Hara Kala Bhavan	-
2		Toli Chowki	Hanuman Temple	11KV	Banjarahills	22.22	23.44	01.22	EL	Line AB Switch Jumper cut at Hanuman Temple	-
3		Jubilee Hills	P.E.I. OH	11KV	Banjarahills	23.26	00.37	01.11	EL,OL-Rph	Tree branches fallen on lines at Road No.56	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Miralam	Tadbund	11KV	Charminar	19.55	21.40	01.45	EL,OL-Rph	Disc Insulator flash over at Bilal Medical Shop	-
1	HYD C	Toli Chowki	Para Mount Colony	11KV	Mehdipatanam	15.35	17.45	02.10	OL	Lugs burntout & Disc Insulator flash over at Paramount Gate No.2	-
2		Hyderguda	Boggula Kunta	11KV	Saifabad	18.25	19.45	01.20	EL	No Visible Fault	-
3		Exhibition	Jawaharlal Nehru	11KV	Saifabad	18.28	20.00	01.32	EL,OL-Bph	Tree branches fallen on lines at Opp: Collector Office	-
4		S.D Hospital	Ahmed Nagar OH	11KV	Mehdipatanam	18.40	20.00	01.20	EL,OL-Bph	Pin Insulator flash over at behind S.D Hospital	-
5		A.C.Guards	Niloufor	11KV	Mehdipatanam	20.40	22.40	02.00	All Indication	UG Cable End Kit failed at Express Apts	-
6		Nampally	Pearl Regency	11KV	Mehdipatanam	21.49	22.57	01.08	EL,OL-Rph	Tree branches fallen on lines at C.A.College	-
7		Langerhouse	Pensionpura	11KV	Mehdipatanam	21.55	23.00	01.05	EL	Tree branches fallen on lines at Pensionpura	-
8		Asif Nagar	Alapati Nagar	11KV	Mehdipatanam	20.47	22.10	01.23	EL	LT Line snapped at Kids Shopping Mall	-
9		Jawahar Nagar	Bank of Baroda	11KV	Saifabad	21.40	23.55	02.15	OL-Bph	No Visible Fault	-
10		Langerhouse	Pensionpura	11KV	Mehdipatanam	23.45	01.10	01.25	EL	AB Switch Insulator flash over at Edgah	-
11		Mothi Mahal	Balanser	11KV	Mehdipatanam	23.54	01.45	01.51	EL,OL-R&Yph	Disc Insulator flash over at Golconda Fort	-
12		Bathkammakunta	Saibaba Temple	11KV	Azamabad	23.05	01.55	02.50	EL,OL-Rph	Pin Insulator flash over at Sai Baba Temple	-