

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044	1	2	1	2	1	2			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	2	13	2	13	2	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kaverammamet	Bandamidipally	11KV	Jadcherla	08.45	10.10	01.25		Tree follon the line near Macharam	-
1	NLG	Kandagatla	Guttakinda	11KV	Suryapeta	11.30	14.05	02.35	E/L	Conductor Snapped	-
2		Alingapoor	Chennaipalem	11KV	Huzurnagar	09.00	11.00	02.00	E/L	11KV Disk failed	-
3		Raghunadhapalem	Nakkalagudem	11KV	Huzurnagar	07.00	10.00	03.00	E/L	11KV Disk failed	-
4		Velminedu	Pittampally	11KV	Nalgonda	13.45	16.50	03.05	E/L	11KV Insulator failure	-
1	SDPT	Akunoor	Rudraipally	11KV	SDPT	07.30	22.50	15.20		CT FAILURE	-
2		Gagillapur	Gagillapur Agl	11KV	SDPT	00.00	07.00	07.00		CONDUCTOR SNAPPED	-
1	RR N	Madinaguda	H M T	11KV	Kukatpally	22.25	23.34	01.09	EL/OL	11kv Pin insultor Failure At prashanth Nagar	-
1	RR E	Yapral	Kowkooor	11KV	Sainikpuri	19.30	20.20	00.50		11KV Pin Insulator Failed Prakruthivihar, Yapral	-
2		Anandbagh	Shivapuri	11KV	Sainikpuri	20.20	21.50	01.30		UG Cable Failed at Vishnupuri Colony	-
3		Malkajgiri	Durganagar Cable	11KV	Sainikpuri	22.50	00.00	01.20		Line Petroling due to Heavy Rain	-
1	HYD S	Salarjung	Alija Kotla	11KV	III	14.50	16.15	01.25	All Indication	2No. HT Lines snapped at Bismillah Hotel	
2	HYD N	I.D.P.L	Vijaya Electrical	11KV	VI	22.35	00.45	02.10	EL,OL-Rph	Pin Insulator flash over at Opp: Shivalayam Temple	

TSSPDCL - LMRC / Corporate office

Date: 13.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gummadidala	Gummadidala		Patancheru	08.05	09.15	01.10		B/D due to Jumper cut	Gummadidala	-
1	HYD N	132KV Erragadda	Jana Priya	33KV	Erragadda	11.07	11.12	00.05	EL	Heavy dip due to GHMC digging at Mothi Nagar X Road	Jana Priya	Loads transferred onto 132KV Erragadda SS via 33KV IDPL feeder