

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>14</b>	<b>2</b>	<b>14</b>	<b>2</b>	<b>14</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 14.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramapuram	Mellacheruvu	33KV	Huzurnagar	11.00	14.00	03.00	EL	Due to 33Kv line Snapped	Mellacheruvu	-
1	MDK	Narsapur	Reddypally	33KV	Medak	15.25	17.30	02.05		B/D Due to Insulator Failure	Reddypally	-

TSSPDCL - LMRC / Corporate office

Date: 14.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamangundla	Yerrasanigudem	11KV	Nalgonda	01.00	02.30	01.30	E/L	11KV Insulator Failed	-
2		Aitipamula	R.C.puram	11KV	Nalgonda	06.30	07.45	01.15	E/L	11KV Jumper cut	-
3		Penpahad	Anajipuram	11KV	Suryapet	11.40	14.30	02.50	E/L	Conductor snapped	-
4		Dirsincherla	Somaram	11KV	Huzurnagar	03.30	07.00	03.30	E/L	Due to 11Kv jumper cutted	-
5		Raghunadapalem	Nakkalagudem	11KV	Huzurnagar	02.30	05.30	03.00	E/L	Due to 11Kv line cutted	-
6		MT.Pally	Dharmaram	11KV	Bhongir	09.30	13.00	03.30	E/L	11kv line Snaped in Jagyaa Thanda	-
1	MDK	Bollaram - II	Vipla	11KV	Patancheru	03.10	05.47	02.37		B/D Due to Conductor Snapped	-
2		Isnapur	Wedia	11KV	Sangareddy	09.35	10.40	01.05		B/D Due to Jumper Cut	-
1	RR N	UMCC	RM Nagar	11KV	Medchal	03.00	04.20	01.20		11KV Pin Insulator failed at RM Nagar	-
2		UMCC	HAL Colony	11KV	Medchal	16.00	17.00	01.00		11KV Pin Insulator failed at CMR School	-
3		Gowdavelly	Ayodhya	11KV	Medchal	10.30	13.20	02.50		Tree Fallen on 11KV Line at Mallikarjuna Temple,Ayodya X Road	-
1	RR E	Kushaiguda	Rukminipuri	11KV	Sainikpuri	02.10	03.00	00.50		Ground Petrolling don't but No Visible fault found	-
2		Vasanthapuri	Sai Ram	11KV	Sainikpuri	14.01	15.13	01.12		Ground Patrolling Done But No fault found (L.Insp Srinivas Reddy)	-
1	HYD C	Asif Nagar	Market Yard	11KV	VII	09.30	10.50	01.20	EL,OL	Cable fault at Saibaba Temple	-