

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403									
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		10		10		10			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	11	2	11	2	11	0	0	
	Grand Total	1082	6468	2	20	2	20	2	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepur	33KV	Narayanapet	17.50	22.15	04.25	EL	Insulator failed	Vepur	Alternate supply arranged from 33KV Kothapally SS
1	MDK	Pashamailaram	SKOL	33KV	Sangareddy	08.40	12.50	04.10		BD due to Insulator failure near IIT.	SKOL	-

TSSPDCL - LMRC / Corporate office

Date: 21.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thirumalagiri	Bakthalapuram	11KV	Suryapeta	09.15	10.45	01.30	E/L	Jumper cut	-
2		Bibinagar	Gudur	11KV	Bhongiri	12.00	15.00	03.00	E/L	11KV Line snapped	-
3		Nemaragomula	Nemaragomula	11KV	Bhongiri	11.30	13.00	02.30	E/L	11KV Insulator failure	-
4		Teededu	Teededu	11KV	Devarakonda	15.00	16.00	01.00	E/L	Jumper cut	-
5		Ghanapuram	G.B.Pally	11KV	Devarakonda	12.40	13.40	01.00	E/L	Insulator failure	-
6		Palakeedu	Bonthalapalem	11KV	Huzurnagar	12.30	15.30	03.00	E/L	11KV Disk Failure	-
7		Thimmareddy gudem	Ganapavaram	11KV	Huzurnagar	04.45	07.55	03.10	E/L	11KV Disk Failure	-
8		Akaram	Shanthinagar	11KV	Nalgonda	10.30	13.10	02.40	E/L	Insulator failure	-
9		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	04.30	08.30	04.00	E/L	11KV Line cut	-
10		Urumadla	Elikatte	11KV	Nalgonda	05.00	07.30	02.30	E/L	11KV Line cut	-
1	MDK	Bollaram-II	Vipla	11KV	Patancheru	01.45	02.45	01.00		B/D due to Jumper cut	-
1	RR N	Vijayanagar	AS Rajunagar	11KV	Kukatpally	12.50	14.50	02.00	EL	HT line Snaped at V V Nagar, Gate:3	-
2		Jeedimetla-I	JETL	11KV	Jeedimetla	04.40	06.00	01.20	EL/OL	Incoming Jumper Cut at SS	-
3		Devarayamjal	Kottapet	11KV	Medchal	10.20	13.00	02.40	BD	Tree Fallen on the 11KV Line at DMC Area	-
4		Gowdavelly	IDA Gowdavelly	11KV	Medchal	13.30	15.00	01.30	BD	11KV Line Cut & Replaced at Star Poultry Farm	-
1	HYD N	Madhapur	Gowrah	11KV	X	08.55	10.00	01.05	All Indication	No Visible Fault	-
2		Macha Bollaram	Reddy Enclave	11KV	C-VI	16.55	19.00	02.05	EL	Pin Insulator flash over at Madhura Enclave	-
1	HYD S	Kanchan Bagh	I.S.Sadan	11KC	VIII	14.38	15.40	01.02	OL-Rph	No Visible Fault	-
1	HYD C	Fever Hospital	Fever Hospital	11KC	II	18.49	19.55	01.06	EL,OL-Bph	Cable End Kit failed at Indian Bank	-
2		Bathkammakunta	Ayyappa Temple	11KC	II	19.16	20.36	01.20	EL,OL-Rph	Big tree fallen on line at Red Building	-