

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		2		2		1		33KV 1No. Still
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>11</b>	<b>2</b>	<b>11</b>	<b>2</b>	<b>11</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>1</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 25.08.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Eidra	33KV	Mahabubnagar	13.15	19.16	06.01	LV's Pol Out	LV's Pull Out Insulator Failure Disc Failure and Jumper Cut	SVS Eidra	No
2		Balanagar	Navadurga	33KV	Shadnagar	15.40	16.20	00.40	E/L	LA Failure near at Navadurga Industri	Navadurga	No
3		Gadwal	Bijwar	33KV	Gadwal	22.50	00.00	01.10	E/L	Not Rectified	Bijwar	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nerada	Kashireddypally	11KV	Nalgonda	7:05	9:00	1:55		11KV Line Jumper Cut	No
2		Urumadla	Yelikatte	11KV	Nalgonda	04.45	11.00	06.15		11KV Line Jumper Cut	No
3		Narketpally	Mandra	11KV	Nalgonda	08.00	09.45	01.45		11KV Line Jumper Cut	No
4		Aitipamula	R.C.Puram	11KV	Nalgonda	10.35	11.56	01.21		11KV Line Insulato Failure	No
5		Marriguda	Vattipally	11KV	Devarakonda	02.30	08.35	06.05		11 KV Dics Faild	No
6		Thatipamula	Sri Ram Thanda	11KV	Suryapet	09.00	10.50	01.50		11KV Jumper cut	No
7		Munagala	Munagala(T)	11KV	Huzurnagar	11.50	15.00	03.10		Due to 11kv jumper cutted	No
8		Repala	Repala	11KV	Huzurnagar	11.35	14.20	02.45		Due to 11Kv Insulator failure	No
9		Repala	Kalakova	11KV	Huzurnagar	12:00	14:50	2:50		Due to 11kv line cutted	No
1	SDPT	Musthyal	Chunchanakota	11KV	Husnabad	11:25	15:25	4:00		Insulator failed	No
2		Koheda	Theegalakuntapally	11KV	Husnabad	0:00	7:00	7:00		Disc failed	No
1	RR S	Chandanagar	Engineers Enclave	11KV	Gachibowli	17:35	18:45	1:10		11kv Disc failed at Huda colony (Due to heavy rain)	No
1	RR N	Shemshiguda	Janmaboomi Colony	11KV	Kukatpally	18:50	20:45	1:55	EL/OL	11kv line OH Cable Milted at PJR X Road & Clamp Burned Reqtified at SS	No
2		Kompally	Dholari Dhani	11KV	Medchal	20.15	21.15	01.00	BD	11KV Jumper cut & replacement at Pochammagadda	No
1	RR E	Kushaiguda	Sri Ram Nagar	11KV	Sainikpuri	6:30	7:20	0:50		Tree branches fallen on 11Kv line near Asha Hospital	No
2		VP Nagar	VV Puram	11KV	Sainikpuri	10.50	11.23	00.33		Copper Patti cut at GK Ragavendra Apt Ragavendra Nagar	No