

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>15</b>	<b>0</b>	<b>15</b>	<b>0</b>	<b>15</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988	2	8	2	8	2	8			
3	MDK	107	933	2	3	2	3	2	3			
4	SDPT			1	5	1	5	1	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>7</b>	<b>17</b>	<b>7</b>	<b>17</b>	<b>7</b>	<b>17</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>32</b>	<b>7</b>	<b>32</b>	<b>7</b>	<b>32</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 27.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Moosapet	11kv	Jadcherla	21.00	12.00	15.00		Tree fallen on 11 kv line, 11 kv disk fail near nijalapur and 11 kv wirecut near chakrapur.	-
1	NLG	Mukundapuram	Kalluru	11kv	Huzurnagar	05.22	07.00	01.38	E/L	11Kv Insulator failure	-
2		Garidepally	Kalmalchervu	11kv	Huzurnagar	17.20	20.00	02.40	E/L	Tree branch fall on 11Kv line	-
3		Gondriyala	Kothagudem	11kv	Huzurnagar	16.15	19.00	02.45	O/L	11Kv Insulator failure	-
4		Gaddipaly	Ponugodu	11kv	Huzurnagar	10.35	13.15	02.40	O/L	Tree branch fall on 11Kv line	-
5		Narkatpally	Narkatpally town	11kv	Nalgonda	12.00	14.30	02.30	E/L	11KV line cut at Narkatpally town	-
6		Pamanagundla	Pittampally	11kv	Nalgonda	09.35	12.20	02.45	E/L	11KV line cut at SS-2	-
7		Athmakur(S)	Athmakur Agl	11kv	Suryapet	09.20	10.40	01.20	E/L	11Kv Disc Flashover	-
8		Nuthankal	Yerrapahad	11kv	Suryapet	14.20	16.30	02.10	E/L	11Kv Conductor snapped	-
1	MDK	Nandigama	Fenoplast	11kv	Sangareddy	04.30	08.00	03.30		B/D due to Jumper cut at Kardhanoor (V)	-
2		Seelampally	Faizabad	11kv	Medak	07.00	13.05	06.05		B/d due to Insulator failed	-
3		Chippalthurthy	Jakkapally	11kv	Medak	01.00	10.40	09.40		B/D due to 11 Jumper cut	-
1	SDPT	Gouravelli	Gubbadi	11kv	SDPT	05.30	11.20	05.50		Insulator Failure 3Ph	-
2		Ramchandrapur	Vinjapally	11kv	Husnabad	00.00	02.00	02.00		Jumper Cutting 3Ph	-
3		Theegalakuntapally	Theegalakuntapally	11kv		00.00	07.50	07.50		Disk Failure 3Ph	-
4		Mustyala	Gadithota	11kv		00.00	11.15	11.15		11 kv Line cutting	-
5		Mustyala	Cherial Agl	11kv		00.00	12.30	12.30		Break Down, Insulator failure	-
1	RR S	Gachibowli	Nalagandla	11kv		GCB	06.55	08.45	01.50		11KV Line Snapped at Gulmohar Park.
2		IIIT	GPRA	11kv	GCB	04.58	06.38	01.40		11KV DTR Pin Insulator Failed at Laxmi Enclave.	-
1	RR N	Kolthur	Anantharam	11kv	Medchal	13.00	14.05	01.05	BD	11KV Jumper cut and replaced at Pochaiiah Bhavi, Anantharam	-
2		Athiwelly	Dabeerpur	11kv	Medchal	04.45	05.35	00.50	BD	11KV Line cut and replaced Lingapur village	-
3		Aliabad	HBL	11kv	Medchal	00.10	05.25	05.15	BD	Bird fallen on the 11KV Line at Monsanto Company	-
1	RR E	Cherlapally-II	Junnurm	11kv	Sainikpuri	16.48	18.45	01.57		11Kv Pin Insuletor failure at Mintu Colony (AE/OP)	-
2		NN Colony	Bavanaruchi	11kv	Sainikpuri	14.30	15.05	00.35		HG fuse Insuletor fail at Bavanaruchi Vencher (LM Balaram)	-
3		Vinayak Nagar	Neredmet Dite	11kv	Sainikpuri	16.44	17.16	00.32		Post of Insuletor fail at near Dite Collage (AE/OP)	-
4		RGK	Nissa	11kv	Sainikpuri	18.20	19.05	00.45		Ground Petrolling done but no visible fount found	-
5		Balaji Nagar	Sai Baba	11kv	Keesara	18.30	19.40	01.10		11KV Disc failed at Muthu Swamy Colony	-
6		Cherlapally	Rampally	11kv	Keesara	16.45	19.00	02.15		11KV Pin Insulator failed near Earth Power Company	-
1	HYD N	Gun Rock	Subhash Nagar	11kv	C-VI	07.50	09.15	01.25	EL	2No. Jumpers cut at Gunrock Pump House & Limb to CT Jumper cut at SS	-
1	HYD S	C.R.P.F.	Jamal Banda	11kv	III	02.20	04.50	02.30	EL	Disc Insulator flash over at Salala Grave Yard	-
2		Moosarambagh	Moosarambagh	11kv	VIII	16.10	17.50	01.40	EL,OL	Pin Insulator flash over at Moosarambagh	-
1	HYD C	A.S.R.Raju Nagar	Jeevan Kalyan Nagar	11kv	VII	01.35	03.26	01.51	EL,OL	Cable fault at V.K.Enclave Apts (2No.DTR's kept off)	Arranged B/F on 11KV Murad Nagar feeder

## TSSPDCL - LMRC / Corporate office

Date: 27.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	RWS	33kv	Gadwal	14.55	15.15	00.20	EL	Due to Heavy Gale & Winds Rain No Visibul fault	RWS	-
2		Kothur	Ennar Steel	33kv	Shadnagar	19.25	22.30	03.05	EL	for Pole Damaged & New Pole erection work at Kothur Bawarchi hotel	Ennar Steel	-
1	NLG	Narkatpally	Nemmani	33kv	Nalgonda	16.30	19.50	03.20	E/L	33Kv Line Jumper and Bass side Jumper Cut	Nemmani	-
2		Narkatpally	Nakkalapally	33kv	Nalgonda	17.00	17.30	00.30	E/L	Alternate supply Arranged 132Kv Sh.Gouraram SS in 33Kv Akkanepally Feeder at 17:30 hr's	Nakkalapally	-
1	MDK	Pashamailaram	ALP4	33kv	Sangareddy	02.00	14.25	12.25		BD due to 2 No.s Bus Jumpers snapped at 132KV SS	ALP4	-
2		Kowdipally	Ch.Ghanpur	33kv	Medak	16.02	17.40	01.38		BD due to Disk failed	Ch.Ghanpur	-
3	SDPT	Duddeda	Bandaram	33kv	SDPT	05.00	06.50	01.30		line fault	Bandaram	-