

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.12.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Rayanguda	K.K.Pally	11KV	Nalgonda	12:30	15:20	2:50	EL	11KV Line Jumper Cut	No
2		Kethepally	Gudivada	11KV	Nalgonda	04.00	06.30	02.30	EL	11 KV Line cut	No
3		Mattampally	Choutapally	11KV	Huzurnagar	03.00	09.00	03.00	EL	11 KV Conductor Snapped	No
4		Panugodu	Kothagudem	11KV	Huzurnagar	03.00	06.00	03.00	EL	11 KV Line snapped	No
5		Sirikonda	Namavaram	11KV	Huzurnagar	03.00	06.30	03.30	EL	11 KV Jumper cut	No
6		Alingapuram	Chennaipalem	11KV	Huzurnagar	14.45	16.05	01.20	EL	11 KV Insulator failed	No
7		Bethavolu	Bethavolu	11KV	Huzurnagar	10:50	11:55	1:05	EL	11 KV Line snapped	No
1	MDK	Patancheru Town	Allwyn	11KV	Patancheru	8:20	9:20	1:00		Jumper Cut	No